OMB No. 2040-0042

Approval Expires 12/31/2018

.O.EDA

United States Environmental Protection Agency Washington, DC 20460

WEL!	Comple	letion Form For Injecti	ion Wells	
		Administrative Information		
1. Permittee	Florence Copper Inc.			
Address (F	Permanent Mailing Address) (Street, City, and 2	ZIP Code)		
1575 W H	funt Hwy, Florence, AZ 85132			
2. Operator	Florence Copper Inc.			
1	Street, City, State and ZIP Code)			
	unt Hwy, Florence, AZ 85132			
3. Facility Na	ame Copper Inc.		Telephone Number (520) 374-3984	
	Copper Inc. Street, City, State and ZIP Code)		(520) 374-3984	
	funt Hwy, Florence, AZ 85132			
13,5	III Hwy, Fiorence, A.D. 65.52			
	ocation Description of Injection Well(s)			
State Arizo	ona	County		
Surface Loca	ation Description			
SW 1/4 of	SW 1/4 of <u>NE</u> 1/4 of SW 1/4 of Section 28	8 Township 4S Range 9E		
Locate well i	in two directions from nearest lines of quarter s	section and drilling unit		
Surface				
	ft. frm (N/S) N Line of quarter section			
	from (E/W) E Line of quarter section.			
Well	II Activity	Well Status	Type of Permit	
	Class I	✗ Operating	Individual	
<u></u>	Class II	Modification/Conversion	X Area: Num	mber of Wells 33
	Brine Disposal Enhanced Recovery	Proposed		
	Hydrocarbon Storage			
×	Class III			
	Other			
Leas 	se Number NA	Well Number O-04		
	Submit with this Completion Form	n the attachments listed in A	Attachments for Completion Fe	orm.
		Certification		
this doc	under the penalty of law that I have pe sument and all attachments and that, b og the information, I believe that the int ant penalties for submitting false inform	based on my inquiry of those oformation is true, accurate, a	e individuals immediately respo	onsible for
	ficial Title (Please type or print)	Signature		Date Signed
Ian Ream, S	Senior Hydrogeologist	Home		9-12-2018

PAPERWORK REDUCTION ACT

The public reporting and record keeping burden for this collection of information is estimated to average 49 hours per response for a Class I hazardous facility, and 47 hours per response for a Class I non-hazardous facility. Burden means the total time, effort, or financial resource expended by persons to generate, maintain, retain, or disclose or provide information to or for a Federal Agency. This includes the time needed to review instructions; develop, acquire, install, and utilize technology and systems for the purposes of collecting, validating, and verifying information, processing and maintaining information, and disclosing and providing information; adjust the existing ways to comply with any previously applicable instructions and requirements; train personnel to be able to respond to the collection of information; search data sources; complete and review the collection of information; and, transmit or otherwise disclose the information. An agency may not conduct or sponsor, and a person is not required to respond to, a collection of information unless it displays a currently valid OMB control number. Send comments on the Agency's need for this information, the accuracy of the provided burden estimates, and any suggested methods for minimizing respondent burden, including the use of automated collection techniques to Director, Collection Strategies Division, U.S. Environmental Protection Agency (2822), 1200 Pennsylvania Ave., NW, Washington, D.C. 20460. Include the OMB control number in any correspondence. Do not send the completed forms to this address.

Attachments to be submitted with the Completion report:

I. Geologic Information

- 1. Lithology and Stratigraphy
- A. Provide a geologic description of the rock units penetrated by name, age, depth, thickness, and lithology of each rock unit penetrated.
- B. Provide a description of the injection unit.
- (1) Name
- (2) Depth (drilled)
- (3) Thickness
- (4) Formation fluid pressure
- (5) Age of unit
- (6) Porosity (avg.)
- (7) Permeability
- (8) Bottom hole temperature
- (9) Lithology
- (10) Bottom hold pressure
- (11) Fracture pressure
- C. Provide chemical characteristics of formation fluid (attach chemical analysis).
- D. Provide a description of freshwater aquifers.
- (1) Depth to base of fresh water (less than 10,000 mg/l TDS).
- (2) Provide a geologic description of aquifer units with name, age, depth, thickness, lithology, and average total dissolved solids.

II. Well Design and Construction

- Provide data on surface, intermediate, and long string casing and tubing. Data must include material, size, weight, grade, and depth set.
- 2. Provide data on the well cement, such as type/class, additives, amount, and method of emplacement.
- 3. Provide packer data on the packer (if used) such as type, name and model, setting depth, and type of annular fluid used.

- 4. Provide data on centralizers to include number, type and depth.
- 5. Provide data on bottom hole completions.
- 6. Provide data on well stimulation used.

III. Description of Surface Equipment

1. Provide data and a sketch of holding tanks, flow lines, filters, and injection pump.

IV. Monitoring Systems

- 1. Provide data on recording and nonrecording injection pressure gauges, casing-tubing annulus pressure gauges, injection rate meters, temperature meters, and other meters or gauges.
- 2. Provide data on constructed monitor wells such as location, depth, casing diameter, method of cementing, etc.

V. Logging and Testing Results

Provide a descriptive report interpreting the results of geophysical logs and other tests. Include a description and data on deviation checks run during drilling.

- **VI.** Provide an as-built diagrammatic sketch of the injection well(s) showing casing, cement, tubing, packer, etc., with proper setting depths. The sketch should include well head and gauges.
- **VII.** Provide data demonstrating mechanical integrity pursuant to 40 CFR 146.08.
- **VIII.** Report on the compatibility of injected wastes with fluids and minerals in both the injection zone and the confining zone.
- IX. Report the status of corrective action on defective wells in the area of review.
- **X.** Include the anticipated maximum pressure and flow rate at which injection will operate.



HALEY & ALDRICH, INC. One Arizona Center 400 E. Van Buren St., Suite 545 Phoenix, AZ 85004 602.760.2450

TECHNICAL MEMORANDUM

14 September 2018 File No. 129687-010

TO: Florence Copper Inc.

Ian Ream, Senior Hydrogeologist


FROM: Haley & Aldrich, Inc.

Lauren Candreva, R.G.

Subject: Drilling, Installation, and Integrity Testing Summary

PTF Observation Well O-04

Florence Copper Inc., Florence, Arizona



The Arizona Department of Water Resources Registry ID for well O-04 is 55-227233; the Well Registry Report is included in Appendix A. Well O-04 is located in the southeast quarter of the northwest quarter of the southwest quarter of Section 28 of Township 4 north, Range 9 East of the Gila and Salt River Baseline and Meridian (D(4-9)28CBD). Well O-04 is located within the Underground Injection Control (UIC) Permitted Area of Review (AOR) for UIC Permit R9UIC-AZ3-FY11-1 and was completed as a Class III observation well for the PTF (Figure 1).

Florence Copper contracted Hydro Resources to drill, install, and test well O-04 in accordance with *Bid Specification: Drilling, Installation, and Testing of Class III Observation Wells, Production Test Facility, Florence, Arizona* (Haley & Aldrich, Inc. [Haley & Aldrich], 2017). A Challenger 320 drilling rig was used for all drilling and construction activities. Haley & Aldrich provided oversight of drilling activities, geophysical logging, well installation, and testing. All reported depths are in feet below ground surface unless otherwise noted.



I. Geologic Information

1. Lithology and Stratigraphy

A. Geology of Penetrated Units

The geology penetrated during the drilling of the Class III well O-04 is summarized in the table below and a lithologic log is included in Appendix B.

Lithologic Unit Name	Depth to Bottom of Unit (feet)	Thickness of Unit (feet)	Lithology and Age of Unit
Upper Basin Fill Unit (UBFU)	280	280	Alluvium; Quaternary to Tertiary
Middle Fine-Grained Unit (MFGU)	302	22	Alluvium; Tertiary
Lower Basin Fill Unit (LBFU)	390	88	Alluvium; Tertiary to Cretaceous
Bedrock Oxide Unit (Oxide)	Not encountered	>818	Igneous porphyry – Precambrian

B. Description of Injection Unit

Name	Bedrock Oxide Unit
Depth Drilled	1,208 feet
Thickness	>818 feet
Formation Fluid Pressure	Atmospheric plus head of freshwater – no additional formation pressure
Age of Unit	Precambrian with intrusions of Precambrian to Tertiary rocks
Porosity ¹	Approximately 6 to 8.5%
Permeability	Hydraulic Conductivity = 0.56 feet per day
Bottom Hole Temperature	34.4 degrees Celsius
Lithology	Igneous porphyry – quartz monzonite, granodiorite with diabase and andesite dykes (detailed log included in Appendix B)
Bottom Hole Pressure	Approximately 430 pounds per square inch (PSI) (pressure exerted by the column of freshwater with no additional contribution from formation pressure)
Fracture Pressure	0.65 PSI per foot
¹ Porosity values for the bedrock o	xide unit are approximate values from calculated neutron porosity values from

¹ Porosity values for the bedrock oxide unit are approximate values from calculated neutron porosity values from injection well borehole surveys.



C. Chemical Characteristics of Formation Fluid

The chemical characteristics of the formation fluid in the injection zone are summarized below and the results of the sampling of the center PTF wellfield well R-09. The table below summarizes the primary chemical characteristics detected in a formation fluid sample collected on 23 April 2018; the complete analytical report is included in Appendix C.

Analyte	Result (mg/L)
Metals	
Aluminum	<0.08
Antimony	<0.005
Arsenic	0.0016
Barium	0.071
Beryllium	<0.0005
Cadmium	<0.00025
Calcium	140
Chromium	0.0051
Cobalt	<0.00025
Copper	0.011
Iron	<0.30
Lead	<0.0005
Magnesium	27
Manganese	0.002
Mercury	<0.001
Nickel	0.0033
Potassium	6.8
Selenium	<0.0025
Sodium	170
Thallium	<0.0005
Zinc	<0.04
Anions	
Bicarbonate	150
Chloride	310
Fluoride	<0.5
Nitrate	8.8
Sulfate	190
Field Parameters	
Total Dissolved Solids	1,000
рН	7.8
Radiochemicals	•
Uranium	0.016
Notes:	•
mg/L = milligrams per liter	

Results of the sampling of well O-04 are included in the *PTF Mine Block Ambient Groundwater Concentrations and Initial Discharge Characterization of the Underground Workings* (Brown and Caldwell, 2018).



D. Description of Freshwater Aquifers

- 1) The depth to the base of the freshwater aquifer is defined by the interface where deeper formation fluid exhibits a total dissolved solids (TDS) value of 10,000 milligrams per liter (mg/L). The depth of the 10,000 mg/L interface is deeper than all of the wells drilled at the site and consequently has not been defined.
- 2) The geologic description of the aquifer units is included below:

Aquifer Unit Name	Age	ge Depth Th		Lithology	Average Total Dissolved Solids ¹ (mg/L)
UBFU	Quaternary/Tertiary	0 to 280	280	Alluvium	914
LBFU	Tertiary	302 to 390	88	Alluvium	754

¹ Average TDS values calculated from UBFU and LBFU monitoring well ambient monitoring results near the PTF.

II. Well Design and Construction

1. Well O-04 Casing Installed:

Casing	Material	Diameter (inches)	Weight (pounds per foot)	Depth (feet)	Borehole Diameter (inches)	Drilling Method
Surface	Mild Steel	14 O.D. 13% I.D.	47.36	0 to 40	24	Solid-stem auger
Well Casing	Fiberglass Reinforced Plastic	5.47 O.D. 4.74 I.D.	5.40	-2.0 to 498	12¼	Reverse Flooded Rotary
Screen	PVC SCH80 with 0.020-inch wide slots	5.56 O.D. 4.81 I.D.	4.08	498 to 1,200	12¼	Reverse Flooded Rotary

Notes:

I.D. = inside diameter

O.D. = outside diameter

PVC = polyvinyl chloride

SCH = Schedule



2. Well Cement

Cement Interval	Cement Type	Additives	Amount Installed (cubic yards)	Method of Emplacement
Surface Casing	Type V Neat 21 sack slurry	None	7	Submerged tremie
Well Casing	Type V Neat 21 sack slurry	None	26.2	Submerged Tremie

Field forms documenting pipe tallies, annular materials, and cement tickets are included in Appendix D.

3. Annular Packers

No annular packers were used during construction of well O-04.

4. Centralizers

Casing	Centralizer Type	Number and Spacing				
Well – FRP and PVC	Stainless steel – Heavy Duty	28 installed – every 40 feet				
Notes:						
FRP = fiberglass reinforced plastic						
PVC = polyvinyl chloride						

5. Bottom Hole Completion

There is no bottom hole completion as this is not an oil/gas well. The well was completed at the bottom with a stainless-steel endcap of the same diameter as the well screen.

6. Well Stimulation

No well stimulation was used during the drilling and construction of well O-04.

III. Description of Surface Equipment

1. Surface Equipment

Well O-04 is an observation well and has been equipped with a pressure transducer for monitoring water level and a low-flow pump for collecting fluid samples for analysis of specific conductance. A diagram of the wellhead is included in the well as-built in Figure 2.



IV. Monitoring Systems

1. Well Monitoring Equipment

Equipment Type	Location	Туре	Purpose
Pressure Transducer	Well Casing	Recording	Monitor water column/pressure
Electrical Conductivity Sensors	Well Annulus	Non-recording	Monitor formation conductivity
Annular Conductivity Sensors	Well Annulus	Non-recording	Monitor formation conductivity

2. Monitoring Wells

There are a total of 16 monitoring wells associated with the PTF: 7 point-of-compliance (POC) wells, 7 United States Environmental Protection Agency (USEPA) supplemental monitoring wells, and 2 operational monitoring wells. The POC wells are located outside the AOR and are not constructed as Class III wells. The supplemental monitoring and operational monitoring wells are located within the AOR and are constructed as Class III wells as required by the UIC Permit. The wells are summarized in the tables below by type.

	POC Wells								
Well ID	Location X/Y (State Plane NAD 83)	Depth (feet)	Well Nom. Diameter (inches)	Cementing Method	Screened Interval (feet)	Screened Lithologic Unit			
M14-GL	846750.23 746461.52	859	5 9/16 OD	Submerged tremie	778 to 838	LBFU			
M15-GU	846697.17 746464.82	615	5 9/16 OD	Submerged tremie	554 to 594	LBFU			
M22-O	846751.26 746514.47	1,140	5 9/16 OD to 528 feet; 4½ OD to 1,140 feet	Submerged tremie	932 to 1,130	Oxide			
M23-UBF	846688.13 746512.48	250	6% OD	Submerged tremie	210 to 250	UBFU			
M52-UBF	851092.00 774178.00	274	5 9/16	Submerged tremie	198 to 273	UBFU			
M54-LBF	847331.96 746682.61	630	5 9/16	Submerged tremie	310 to 629	LBFU			
M54-O	847342.99 746702.36	1,199	5 9/16	Submerged tremie	668 to 1,198	Oxide			



	Supplemental Monitoring Wells								
Well ID	Location X/Y (State Plane NAD 83)	Depth (feet)	Well Nom. Diameter (inches)	Cementing Method	Screened Interval (feet)	Screened Lithologic Unit			
M55-UBF	847541.46 746280.63	261	5	Submerged tremie	240 to 260	UBFU			
M56-LBF	847518.70 746303.41	340	5	Submerged tremie	320 to 340	LBFU			
M57-O	847378.37 746248.93	1,200	5	Submerged tremie	523 to 1,199	Oxide			
M58-O	847672.23 746595.97	1,200	5	Submerged tremie	594 to 1,199	Oxide			
M59-O	847934.95 746218.89	1,201	5	Submerged tremie	534 to 1,199	Oxide			
M60-O	847599.37 745903.70	1,201	5	Submerged tremie	444 to 1,200	Oxide			
M61-LBF	848184.46 746148.88	629	5	Submerged tremie	429 to 629	LBFU			

Operational Monitoring Wells								
Well ID	Location X/Y (State Plane NAD 83)	Screened Interval (feet)	Screened Lithologic Unit					
MW-01-LBF	847487.97 746360.54	444	5	Submerged tremie	330 to 440	LBFU		
MW-01-0	847499.04 746369.31	1,200	5	Submerged tremie	500 to 1,200	Oxide		

V. Logging and Testing Results

Borehole geophysical logging was conducted on well O-04 in two phases: 1) open-hole surveys in the 12.25-inch borehole prior to installation of the well casing and screen, and 2) cased-hole surveys in the completed well.

The open-hole geophysical surveys completed at well O-04 included:

- Spontaneous potential;
- Natural gamma;



- Electrical resistivity (short and long normal);
- Caliper with calculated volume;
- Temperature;
- Sonic; and
- Deviation.

The cased-hole geophysical surveys completed included:

- Sonic (for cement bond with fiberglass reinforced plastic [FRP]);
- 4 Pi Density (for cement bond with FRP);
- Dual Density (for cement bond with FRP);
- Natural Gamma;
- Fluid Conductivity;
- Temperature;
- Gyroscopic Deviation Survey; and
- Video Survey.

Open-hole geophysical surveys were used to support identification of the lithologic contacts, to evaluate the condition of the borehole, and to evaluate the deviation of the borehole.

The primary logs used to evaluate lithologic contacts are natural gamma ray, short (16-inch) and long (64-inch) normal electrical resistance, and single-point resistance. The lithologic contacts for the Middle Fine-Grained Unit (MFGU) were selected based on the short and long resistance and the single-point resistance. All the resistivity logs decreased and stayed consistently low through the MFGU. This contact is generally a relatively sharp decrease in resistance at the top of the unit and a gradual increase in resistance below the bottom of the unit.

The contact between the Lower Basin Fill Unit (LBFU) and the bedrock was identified primarily with natural gamma and correlated with the resistance logs. There is a consistent increase in gamma at the contact between the LBFU and the bedrock that had been identified and documented at the site during exploration in the 1990s. For well O-04, the gamma is consistently at approximately 60 American Petroleum Institute (API) units throughout the Upper Basin Fill Unit (UBFU) and MFGU, a slight increase to approximately 80 API units in the LBFU, and an increase at 390 feet to over 140 API units. After the increase at 390 feet, the natural gamma begins to vary significantly more than it did in the alluvial units. This change in the response of the natural gamma indicates the contact with the bedrock unit. Also, at this approximate depth there is also an increase in the single-point resistance and the short normal resistance, indicating the formation has become more resistant. This is likely primarily due to the bedrock containing less water than the alluvial formation above.



Cased-hole geophysical surveys were conducted to evaluate the cement seal, the casing-cement bond, to document baseline fluid temperature and conductivity and to evaluate the plumbness of the well. The cement-bond is discussed in Section VII.

Copies of all the open-hole geophysical logs and cased-hole temperature, fluid conductivity, and natural gamma are included in Appendix E; a figure summarizing the open-hole logs used to evaluate geology is included as Figure 3. The cased-hole logs used to evaluate cement bond are included in Appendix F.

VI. Well As-Built Diagram

An as-built diagram for well O-04 is included as Figure 2.

VII. Demonstration of Mechanical Integrity

A demonstration of Part I mechanical integrity of the well was completed using a standard annular pressure test (SAPT) in accordance with Part II.E.3.a.i.A of the UIC Permit. Mechanical integrity will be demonstrated every 2 years during operations and will be confirmed by daily injection pressure monitoring that will be conducted per the UIC Permit once the well is operational. Well O-04 SAPT is summarized below.

The mechanical integrity of the blank well casing was tested by performing a SAPT on 28 March 2018. The SAPT was conducted by installing an inflatable straddle packer assembly in the well. The bottom packer was installed near the bottom of the FRP-cased portion of the well and the top packer was near the surface. The packers were inflated to form a seal against the casing. The bottom 5 feet of the packer drop pipe was perforated to allow for communication between the tubing and the annulus of the packer assembly. The drop pipe extended through the wellhead and a high pressure/low volume pump was attached to the drop pipe to pressurize the test interval. A valve on the drop pipe at the surface was used to isolate the test interval once the planned test pressure was achieved.

An In-Situ LevelTROLL® pressure transducer with a data logger was installed at the well head and was connected to the packer assembly annulus interval via a National Pipe Thread adapter. The LevelTROLL was used to monitor and record pressure inside the well during the SAPT. To conduct the SAPT, water was pumped from a nearby well immediately prior to testing. Before the water was pumped into the test well, the water temperature was measured to ensure that it was similar to the ambient groundwater temperature of the test well to reduce the potential of differential temperature effects on the well casing. The SAPT for the Class III well was conducted by applying hydraulic pressure to the well casing and shutting in pressure between the packer and wellhead assembly, monitoring the shut-in pressure for a 30-minute period, then measuring the volume of water returned from the well casing after the pressure was released.



On 28 March 2018, the packer was installed to approximately 480 feet and the SAPT was conducted successfully two times. The USEPA SAPT form, a table of the data, and a chart of the data is provided in Appendix G.

Part II mechanical integrity is demonstrated by the cementing records included in this report in accordance with Part II.E.3.ii.C of the UIC Permit and will be demonstrated during operations by annular conductivity monitoring on the observation and multi-level sampling wells in accordance with Part II.E.3.a.ii.A of the UIC Permit.

Cemented Interval	Cement Type	Calculated Grout Volume (cubic yards)	Installed Grout Volume (cubic yards)
Surface Casing	Type V 21 sack neat cement slurry	3.1	7
Well Casing	Type V 21 sack neat cement slurry	19.7	26.2

On 22 March 2018, a suite of geophysical logs was run over the entire length of the completed well to verify the grout seal. A summary of the logs completed to demonstrate cement bond are included in Appendix F.

There is not a bond log tool designed to evaluate cement bond with FRP casing, so the cement interval with FRP casing of well O-04 was evaluated using density logs. The logs collected included sonic, focused density, and 4pi density. Based on the measured density of the FRP cased interval of well O-04, no significant cement deficiencies were noted in the sonic data collected from approximately 228 feet (static water level) to 471 feet, and no significant deficiencies were noted in the 4pi density data collected from 44 to 471 feet. There were some very localized, low density intervals identified in the 4pi density logs but they were insignificant, only extending 2 to 4 feet. A summary of the FRP cased data is included in the well completion summary in Appendix F.

VIII. Compatibility of Injected Waste

The Florence Copper Project is a Class III mineral extraction project and does not include the injection of any waste products of any kind. The injected fluid (lixiviant) is a carefully constituted in-situ copper recovery solution that will be recovered and recycled following injection.

The compatibility of the lixiviant was evaluated as part of the geochemical modeling completed by Florence Copper and summarized in the *Geochemical Evaluation to Forecast Composition of Process Solutions for In-Situ Copper Recovery Pilot Test Facility at Florence Copper, Florence Arizona* (Daniel B. Stephens Inc., 2014) which was included in Attachment H of the UIC Permit Application.



IX. Status of Corrective Action on Defective Wells in the Area of Review

There are not currently any defective wells in the AOR.

X. Maximum Pressures and Flow Rates for O-04

Maximum Operating Pressure	Maximum Flow				
Atmospheric	Not applicable – observation well				

This well is an observation well used to monitor hydraulic control of the PTF; no fluids will be injected and only fluid to measure specific conductivity will be extracted using the installed low-flow pump.

XI. Well Development

Well O-04 was developed by the airlift method, followed by pumping, and was completed by Hydro Resources using a workover rig. To purge drilling fluids and solids, the well was air-lift developed from 27 February through 2 March 2018 at various depths ranging from approximately 425 to 1,200 feet. During development, the airlift pump was turned on and off to surge the well. On 28 February 2018, approximately 3 gallons of AquaClear PFD® polymer dispersant was swabbed into the screened interval of the well. The discharge was relatively clear and sand-free at the end of the airlift development period.

On 3 March 2018, a submersible pump was temporarily installed to approximately 1,164 feet to pump develop the well. Pump development was conducted at approximately 60 to 75 gallons per minute (gpm) over a period of 3 days (3 to 5 March 2018), during which time the submersible pump was raised to 900 feet and 600 feet (both on 4 March 2018), and periodically turned off to surge the well. The pumping water level at the end of each pumping period was approximately 250 to 255 feet, with water levels rebounding to approximately 210 to 215 feet prior to the next pumping period. In general, the discharge was visually clear and sand-free throughout the pump development period, with turbidity values less than 5 Nephelometric Turbidity Unit at the end of the development period. Well development forms are included in Appendix H.

XII. Well Completion

A well video survey was conducted on 21 March 2018. The video log report is included as Appendix I. The video log depths are presented in feet below the top of the casing and so vary slightly from what is recorded, but with the correction for stick up are the same.

The video log indicates the top of fill in the well is at 1,195 feet.



The surveyed location for well O-04 is:

Northing (feet)	Easting (feet)	Measuring Point Elevation (feet amsl)
745988.60	847624.06	1477.92

Notes:

Northing and easting locations provided in State Plane North American Datum 1983, vertical location provided in North American Vertical Datum 1988. amsl – feet above mean sea level

XIII. Downhole Equipment

The equipment installed in well O-04 includes:

- QED® low-flow sampling pump hung on drop tubing pump at 600 feet; and
- Pressure transducer.

The type and depth of equipment installed in each well is not constrained by the UIC Permit or Aquifer Protection Permit (APP). This information is provided in accordance with Section 2.7.4.3 of the APP. Operational consideration may require that the type and depth of equipment may need to be changed in response to conditions observed during operations.

XIV. References

Brown and Caldwell, Inc., 2018. PTF Mine Block Ambient Groundwater Concentrations and Initial Discharge Characterization of the Underground Workings. September.

Daniel B. Stephens, Inc., 2014. *Geochemical Evaluation to Forecast Composition of Process Solutions for In-Situ Copper Recovery Pilot Test Facility at Florence Copper, Florence Arizona*. May.

Haley & Aldrich, Inc., 2017. *Bid Specification: Drilling, Installation, and Testing of Class III Observation Wells, Production Test Facility, Florence, Arizona*. Revised September 2017.



Enclosures:

Figure 1 – Well Locations

Figure 2 – O-04 Well As-Built Diagram

Figure 3 – Geophysical Data and Lithologic Log

Appendix A – Arizona Department of Water Resources Well Registry Report

Appendix B – Lithologic Log

Appendix C – Chemical Characteristics of Formation Water

Appendix D – Well Completion Documentation

Appendix E – Geophysical Logs

Appendix F – Cement Bond Log Summary


Appendix G - SAPT Documentation


Appendix H – Well Development Field Forms


Appendix I – Well Video Log and Gyroscopic Survey Reports

G:\Projects\Florence Copper\129687 PTF Well Drilling\Deliverables\Well Summary Reports\0-04\2018-0914_0-04 Well Install Comp Letter Report_EPA vers_F.docx









NOTES

- 1. WELL REGISTRATION NO.: 55-227233
- 2. CADASTRAL LOCATION: D (4-9) 28 CBD
- 3. MEASURING POINT ELEVATION: 1478.05' AMSL
- 4. I.D. = INSIDE DIAMETER
- 5. O.D. = OUTSIDE DIAMETER
- 6. PVC = POLYVINYL CHLORIDE
- 7. FRP = FIBERGLASS REINFORCED PLASTIC
- 8. ACD = ANNULAR CONDUCTIVITY DEVICE
- 9. EC = ELECTRICAL CONDUCTIVITY
- 10. ERT = ELECTRICAL RESISTIVITY TOMOGRAHY




PRODUCTION TEST FACILITY FLORENCE COPPER, INC. FLORENCE, ARIZONA

OBSERVATION WELL O-04 AS-BUILT DIAGRAM




SCALE: NOT TO SCALE OCTOBER 2017

FIGURE 2





OBSERVATION WELL 0-04 GEOPHYSICAL DATA AND LITHOLOGIC LOG



APPENDIX A Arizona Department of Water Resources Well Registry Report

Arizona Department of Water Resources Water Management Division P.O. Box 36020 Phoenix, Arizona 85067-6020 (602) 771-8627 • (602) 771-8690 fax · www.azwater.gov ·

Well Driller Report and AUG 2 0 2018

Well Log



THIS REPORT MUST BE FILED WITHIN 30 DAYS OF COMPLETING THE WELL.

PLEASE PRINT CLEARLY USING BLACK OR BLUE INK.

FILE NUMBER D (4-9) 28 CBD WELL REGISTRATION NUMBER **55** - 227233 PERMIT NUMBER (IF ISSUED)

Drilling	ON 1. DRILLING AUTHORIZ										
	NAME	DWR LICENSE NUMBER									
	Hydro Resources I	nc.	816								
2	ADDRESS		TELEPHONE								
Mail To:	13027 County Rd.) 857-75	544							
	Ft. Lupton, CO 806	21	(303	8) 857-28	326						
SECTIO	N 2. REGISTRY INFORMA										
Well Ov			Location	of Well		-					
FULL NAM Flore	ence Copper Inc.	NDIVIDUAL		TION ADDRE	SS (IF ANY)						
MAILING A	DDRESS		TOWNSHIP	RANGE	SECTION	160 ACRE	40 ACRE	10 ACRE			
1575	W. Hunt Hwy		4S	(E/W)	28	SW 1/4	NW 1/4	SE 1			
	TE / ZIP CODE		LATITUDE	JL	20	LONGITUDE		JOL /			
Flore	ence, AZ 85132		33 ° Degrees	2 Minutes	Seconds	Degrees	26 Minutes	5.51 "\ Second			
	PERSON NAME AND TITLE		METHOD OF LATITUDE/LONGITUDE (CHECK ONE)								
	Ream - Sr. Hydrologist			X *GPS: Hand-Held							
(520) 374-3984 FAX			LAND SURFACE ELEVATION AT WELL 1492 Feet Above Sea Level								
WELL NAM	IE (e.g., MW-1, PZ-3, Lot 25 Well, Smith	Well, etc.)	METHOD OF ELEVATION (CHECK ONE)								
	0 - 04		X *GPS: H	land-Held	THE DATUM (C	vey-Grade					
			COUNTY	☐ Other	(please specif						
			PINAL		BOOK	DR'S PARCEL MAP		ARCEL			
SECTIO	N 3. WELL CONSTRUCTIO	N DETAILS									
Drill Met		Method of Well D	evelopment		Method	of Sealing	at Reducti	on Points			
CHECK ALL	THAT APPLY	CHECK ALL THAT APP	PLY		CHECK O						
☐ Air R	Rotary				☐ No	ne					
	ed or Augered	☐ Bail			☐ Pac	cked					
	e Tool	☐ Surge Block		Swedged							
	Rotary	Surge Pump				Welded					
			e specify):		Other (please specify):						
	erse Circulation										
☐ Driven ☐ Jetted		0 - 10 - 110 11									
	ercussion / Odex Tubing	Condition of Well				iction Date					
☐ Other (please specify):		☐ Capped	CHECK ONE Capped			DATE WELL CONSTRUCTION STARTED 01/20/2018					
☐ Pump Ins			ed		DATE WE	LL CONSTRUC	CTION COMPL	ETED			
					05/2	2/2018					
state that	t this notice is filed in compliance	with A.R.S. § 45-596	and is complete	and correc	t to the hest	of my know	vledge and	holiof			
GNATURE	OF QUALIFYING PARTY	3	io compicte	and borrec	DATE	or my knov	vieuge and i	oellel.			
/					1/	2/20	in				

SECTION 4. WELL CONSTRUCTION DESIGN (AS BUILT) (attach additional page if needed)							
Depth							
DEPTH OF BORING 1225	Feet Below Land Surface	DEPTH OF COMPLETED WELL 1200	Feet Below Land Surface				

Water Level Information							
STATIC WATER LEVEL 229	Feet Below Land Surface	03/22/2018	1 PM	IF FLOWING WELL, METHOD OF FLOW REGULATION Valve Other:			

Borehole								In	stalled Cas	sing								
DEPTH FROM SURFACE				DEPTH FROM		DEPTH FROM SURFACE			MA	ERIA	L TYPE (T)		PE	RFO	RAT	ION	TYPE (T)	
FROM (feet)	TO (feet)	BOREHOLE DIAMETER (inches)	FROM (feet)	TO (feet)	OUTER DIAMETER (inches)	STEEL	PVC	ABS	IF OTHER TYPE, DESCRIBE	BLANK OR NONE	WIRE WRAP	SHUTTER SCREEN	MILLS KNIFE	SLOTTED	IF OTHER TYPE, DESCRIBE	SLOT SIZE IF ANY (inches)		
0	40	30	0	40	24.5	×				×								
40	473	20	0	473	14.5	×			=	X								
473	1225	12.25	0	499	5.44				FRP	X								
			499	1200	5.56		×							X		.020		
								4		Н								

								In	stalled Annular Material					
	H FROM	ANNULAR MATERIAL TYPE (T)												
SUF	RFACE			~	ш	BE	NTON	IITE						
FROM (feet)	TO (feet)	NONE	CONCRETE	NEAT CEMENT OF CEMENT GROUT	CEMENT-BENTONITE GROUT	GROUT	CHIPS	PELLETS	IF OTHER TYPE OF ANNULAR MATERIAL, DESCRIBE	SAND	GRAVEL	SIZE		
0	40			×										
0	473			X										
473	485							X						
485	1225									×		6-9		

SUR	FACE	Description	Check (T) ever interval where
FROM (feet)	TO (feet)	Describe material, grain size, color, etc.	water was encountered (if known)
0	280	UPPER BASIN FILL UNIT	
280	302	MIDDLE FINE GRAINED UNIT	
302	430		
430	1225	BEDROCK OXIDE UNIT	

WELL REGISTRATION NUMBER

SECTION 6. WELL SITE PLAN								
NAME OF WELL OWNER	COUNTY ASSESS	COUNTY ASSESSOR'S PARCEL ID NUMBER						
Florence Copper Inc.	воок	MAP	PARCEL					

- Please draw the following: (1) the boundaries of property on which the well was located; (2) the well location; (3) the locations of all septic tank systems and sewer systems on the property or within 100 feet of the well location, even if on neighboring properties; and (4) any permanent structures on the property that may aid in locating the well.
- Please indicate the distance between the well location and any septic tank system or sewer system.

	W E
SEE ATTCHED MAP	1" = ft

Run Date: 02/21/2018

AZ DEPARTMENT OF WATER RESOURCES WELL REGISTRY REPORT - WELLS55

Well Reg.No

Location D 4.0 9.0 28 55 - 227233

AMA PINAL AMA

Registered Name

AZ STATE LAND DEPT.

1616 W. ADAMS ST.

ATTN: LISA ATKINS

PHOENIX

0.00

AZ 85007

Owner OWNER

Well Type ENV - MONITOR

Application/Issue Date 04/19/2017

SubBasin ELOY

Driller No. 816

Well Depth

Driller Name HYDRO RESOURCES - ROCKY MOUNTAIN, INC.

Watershed UPPER GILA RIVER

Driller Phone 303-857-7540

Registered Water Uses MONITORING

County PINAL

Registered Well Uses MONITOR

Discharge Method NO DISCHARGE METHOD LISTED

0.00

File Type NEW WELLS (INTENTS OR APPLICATIONS)

Power NO POWER CODE LISTED

Log

Intended Capacity GPM

0.00

Case Diam 0.00 **Tested Cap** CRT

Pump Cap. 0.00 Case Depth 0.00 **Draw Down** 0.00 Water Level 0.00

> Acres Irrig 0.00 Finish NO CASING CODE LISTED

Contamination Site: NO - NOT IN ANY REMEDIAL ACTION SITE

Tribe: Not in a tribal zone

Comments NP

AZ State Land Dept. Mineral Lease #11-026500

Current Action

2/21/2018 869 CHANGE OF DRILLER PACKET ISSUED

Action Comment: NTP

Action History

2/16/2018 CHANGE OF DRILLER RECEIVED 865

Action Comment: NTP

4/25/2017 DRILLING AUTHORITY ISSUED 550

Action Comment: TNV

DRILLER & OWNER PACKETS MAILED 4/25/2017 555

Action Comment: TNV

4/19/2017 155 NOI RECEIVED FOR A NEW NON-PRODUCTION WELL

Action Comment: TNV

ARIZONA DEPARTMENT OF WATER RESOURCES 1110 W. Washington St. Suite 310 Phoenix, Arizona 85007

REISSUE

THIS AUTHORIZATION SHALL BE IN POSSESSION OF THE DRILLER DURING ALL DRILLING OPERATIONS

WELL REGISTRATION NO: 55-227233 WELL OWNER ID: 0-04

AUTHORIZED DRILLER: HYDRO RESOURCES - ROCKY MOUNTAIN, INC.

NOTICE OF INTENTION TO DRILL ENV - MONITOR WELL(S) HAS BEEN FILED WITH THE DEPARTMENT BY:

LICENSE NO: 816

WELL OWNER: AZ STATE LAND DEPT. 1616 W. ADAMS ST. ATTN: LISA ATKINS PHOENIX, AZ, 85007

THE WELL(S) IS/ARE TO BE LOCATED IN THE:

Range 9.0 EAST SE 1/4 of the NW 1/4 of the SW 1/4 Section 28 Township 4.0 SOUTH

NO. OF WELLS IN THIS PROJECT:

THIS AUTHORIZATION EXPIRES AT MIDNIGHT ON THE DAY OF April 19, 2018



GROUNDWATER PERMITTING AND WELLS

THE DRILLER MUST FILE A LOG OF THE WELL WITHIN 30 DAYS OF COMPLETION OF DRILLING.



ARIZONA DEPARTMENT of WATER RESOURCES

1110 W. Washington St. Suite 310 Phoenix, AZ 85007 602-771-8500 azwater.gov

February 21, 2018

AZ STATE LAND DEPT. 1616 W. ADAMS ST. ATTN: LISA ATKINS PHOENIX, AZ 85007

Registration No. 55- 227233 File Number: D(4-9) 28 CBD

Dear Well Applicant:



DOUGLAS A. DUCEY Governor

THOMAS BUSCHATZKE Director

Enclosed is a copy of the Notice of Intention to Drill (NOI) a well which you or your driller recently filed with the Department of Water Resources. This letter is to inform you that the Department has approved the NOI and has mailed, or made available for download, a drilling authorization card to your designated well drilling contractor. The driller may not begin drilling until he/she has received the authorization, and must keep it in their possession at the well site during drilling. Although the issuance of this drill card authorizes you to drill the proposed well under state law, the drilling of the well may be subject to restrictions or regulations imposed by other entities.

Well drilling activities must be completed within one year after the date the NOI was filed with the Department. If drilling is not completed within one year, a new NOI must be filed and authorization from this Department received before proceeding with drilling. If the well cannot be successfully completed as initially intended (dry hole, cave in, lost tools, etc.), the well must be properly abandoned and a Well Abandonment Completion Report must be filed by your driller [as required by A.A.C. R12-15-816(F)].

If you change drillers, you must notify the Department of the new driller's identity on a Request to Change Well Information (form 55-71A). Please ensure that the new driller is licensed by the Department to drill the type of well you require. A new driller may not begin drilling until he/she receives a new drilling authorization card from the Department.

If you find it necessary to change the location of the proposed well(s), you may not proceed with drilling until you file an amended NOI with the Department. An amended drilling authorization card will then be issued to the well drilling contractor, which must be in their possession before drilling begins.

Arizona statute [A.R.S. § 45-600] requires registered well owners to file a Pump Installation Completion Report (form 55-56) with the Department within 30 days after the installation of pumping equipment, if authorized. A blank report is enclosed for your convenience. State statute also requires the driller to file a complete and accurate Well Drillers Report and Well Log (form 55-55) within 30 days after completion of drilling. A blank report form was provided to your driller with the drilling authorization card. You should insist and ensure that all of the required reports are accurately completed and timely filed with the Department.

Please be advised that Arizona statute [A.R.S. § 45-593(C)] requires a registered well owner to notify the Department of a change in ownership of the well and/or information pertaining to the physical characteristics of the well in order to keep this well registration file current and accurate. Any change in well information or a request to change well driller must be filed on a Request to Change Well Information form (form 55-71A) that may be downloaded from the ADWR Internet website at www.azwater.gov.

Sincerely,

notan Pawer

Groundwater Permitting and Wells Section

Arizona Department of Water Resources Groundwater Permitting and Wells Section P.O. Box 36020 Phoenix, Arizona 85067-6020 (602) 771-8500 • (602) 771-8690 · www.azwater.gov ·

\$150 Notice of Intent to FEE Drill, Deepen, or Modify a Monitor / Piezometer / Environmental Well

Review instructions prior to completing form in black or blue ink, You must include with your Notice:

\$150 check or money order for the filing fee.

Well construction diagram, labeling all specifications listed in Section 6 and Section 7.


Authority for fee: A.R.S. § 45-596 and A.A.C. R12-15-104.

PINZ PIN SB 11	FILE NUMBER
4/19/2017 00 11/20	WELL REGISTRATION NUMBER
ISSUED DATE REMEDIAL ACTION SITE	55 - 227253

SECTION 1. REGISTRY	INFORMATION								-						
To determine the location of well, pleat (http://www.earthpoint.us/Townships.	ase refer to the Well Registry Map (https://doi.org/10.1016/10	ps://giswe	b.azwater.gov/M	/ellRegistry/Defau	lt.aspx) an	d/or Googl	le Earti	h							
Well Type	Proposed Action	PA S	Location												
CHECK ONE	CHECK ONE	= 1011	WELL LOCATION ADDRESS (IF ANY)												
⊠ Monitor	Drill New Well 4P	7	5/19	7											
Piezometer	☐ Deepen	192	TOWNSHIP(N/S	RANGE (E/W)	SECTION	160 A	CRE	40 ACRE	10 A	CRE					
☐ Vadose Zone	☐ Modify	-	74.0 S	9.0 E	28	sw	1/4	NW 1/4	SE	1/4					
☐ Air Sparging	200		COUNTY AS	SESSOR'S PAR	CEL ID NU	MBER									
☐ Soil Vapor Extraction	WELL REGISTRATION NUMBER (if Deepening or Modifying)		воок	1001											
Other (please specify):	55 -		BOOK MAP PARCEL 100 COUNTY WHERE WELL IS LOCATED												
			PINAL												
SECTION 2. OWNER INF	ORMATION					11.			160						
Land Owner			Well Owner (check this box if Land Owner and Well Owner are same)												
FULL NAME OF COMPANY, ORGAN			FULL NAME OF COMPANY, GOVERNMENT AGENCY, OR INDIVIDUAL												
AZ State Land Dept (Mine	ral Lease # 11-026500)		Florence Copper, Inc.												
MAILING ADDRESS			MAILING ADDRESS												
1616 W Adams St			1575 W Hunt Hwy												
Phoenix, AZ 85007			CITY/STATE/ZIP CODE Florence, AZ 85132												
CONTACT PERSON NAME AND TITI	.E			CONTACT PERSON NAME AND TITLE											
Lisa Atkins, State Land Co	mmissioner		Ian Ream	Ian Ream, Senior Hydrogeologist											
TELEPHONE NUMBER	FAX			TELEPHONE NUMBER FAX											
(602) 542-4631			(52	0) 374-3984		1	(520) 374-	3999						
SECTION 3. DRILLING A	UTHORIZATION				e l'arri	7	PATE.			7					
Drilling Firm			Consulta	nt (if applicable))										
NAME National EWP			CONSULTING FIRM												
DWB HCENSE	ROC LICENSE		Haley & Aldrich, Inc. CONTACT PERSON NAME												
NUMBER 823	CATEGORY A-4			Mark Nicholls											
TELEPHONE NUMBER (480) 558-3500 EMAIL	FAX 480-558-3525		TELEPHONE NUMBER 602-760-2423 FAX 602-760-2448												
ADDRESS jstephens@nation	alewp.com		ADDRESS I												
SECTION 4.															
Questions		Yes	No Ex	No Explanation:											
Are all annular spaces between the placement of grout at least 2		\boxtimes	2-ir in a	2-inch annular spaces are special standards required for wells loca in and near groundwater contamination sites (such as CERCLA, WQARF, DOD, LUST).											
Is the screened or perforated interfeet in length?	erval of casing greater than 100	\boxtimes	CE	100-foot maximum screen intervals are a special standard for wells located in and near groundwater contamination sites (such as CERCLA, WQARF, DOD, LUST).											
Are you requesting a variance to of steel casing in the surface sea			The R12	The wells must be constructed in a vault. Pursuant to A.A.C.											
 Is there another well name or ide with this well? (e.g., MW-1, PZ2 		X	lf ye	If yes,											
 Have construction plans been construction plans be a plan between construction plans because the construction plans because the construction plans because the construction plan between construction plans because the construction plan because the	ordinated with the Arizona	X	If ye	If yes, please state agency contact & phone number David Haag, 602-771-4669											
6. For monitor wells, is dedicated p			If ye (Gal	If yes, please state design pump capacity (Gallons per Minute)											
7. Is this well a new well located in AND intended to pump water for groundwater?	the purpose of remediating		V unle	You must also file a supplemental form A.R.S. § 45-454(c) & (f) unless the well is a replacement well and the total number of operable wells on the site is not increasing. (See instructions)											
8. Will the well registration number on the upper part of the casing?	be stamped on the vault cover or	X		If no, where will the registration number be placed?											

	ON 6. WE												r / Environn	Torrida Won	55 -	72	27233
Drill M							_	100000000000000000000000000000000000000	od of Well D)eı	velo	me	nt	Grout Emp	alacan	ant	Mothed
CHECK O	NE							HECK			10101	,,,,,		CHECK ONE	Jiacen	ient	Method
☐ Cat	ed or Aug ole Tool al Rotary d Rotary							☐ Su		pec	eify):			☐ Tremie☐ Gravity☐ Pressu☐ Other @	re Gro	ut	ecommended)
☐ Rev	erse Circ	ulati	on				V			ng at Reduction Points Surface o						ucto	r Casing
☐ Jett	ed						C	HECK (ONE								
☐ Air I	Percussio er (please s	n / C specif	Odex y):	Tul	bing			None Welded Swedged Swedged Flush Mount in a Extends at least						n a v ast 1'	ault above grade		
DATE CON	O5/0]] Pa	cked her (please sp	ec	ifv):						
SECTIO	N 7. PR	OPO	SEL) W	ELL	COI	NST	RUC	TION PLAN	(a	ttach	add	litional page in	f needed)			
Attach a	well cons	struc	tion	diag	ram	labe	ling	all sp	ecifications	be	low.						
	Boreho	le						THE					Casing				
	FACE						H FR			-	MA	TER	IAL TYPE (T)	PERFORAT	ION TYP	E(T)	
FROM (feet)	TO (feet)	DI	REHC AMET	ER		OM ret)		TO (feet)	OUTER DIAMETER (inches)		STEEL	ABS	IF OTHER TYPE, DESCRIBE	BLANK OR NONE WIRE WRAP SHUTTER SCREEN MILLS KNIFF	SLOTTED	TYPE ESCRI	SLOT SIZ
0	20		18			0		20	14								
20	1210		10		()		500	5 X Pintored X								
					50	00	1	1200	5						X		0.020
DEDT	FROM	1	_	_					Annula NNULAR MATE								
	FACE		T	T~	1	BE	NTO		INNULAR MATE	RIA	LIYP	E (T)		-	F	ILTER PACK
FROM (feet)	TO (feet)	NONE	CONCRETE	NEAT CEMENT OR	CEMENT GROUT	GROUT	CHIPS	PELLETS	IF	от	HER T	YPE C	OF ANNULAR M DESCRIBE	ATERIAL,	SAND	GRAVEL	SIZE
0	490			X													
490	495														X		No. 30-7
495	1210														X		No.10-20
THIS WEL	L HAS NEST	ED C	ASING	SS, SF	PECIF	Y NUI	MBER	OF CA	SING STRINGS		EXP	CTE	D DEPTH TO WA	ATER (Feet Below G	round Su	rface)	
ECTION	8. PER	MIS	1012	V TC) AC	CES	SS							- 10119-000			
By m	checking easuremen	this I	box, this	l her	eby p	orovi e inst	de A	DWR	permission to	ое	nter t	he p	property for th	e purpose of tak	ing wa	ter lev	/el
ECTION	9. LAN	D O	WNE	R A	AND	WE	LL (OWN	ER SIGNAT				-6.90				10000
												d cor	rrect to the bes	t of my knowledge	and		
					wne									lifferent from Land O		e instr	ections)
INT NAME D TITLE											RINT ND TI	NAME		Senior Hydro			
NATURE O											IGNAT ÆLL O						
TE										D	ATE		0	1-17-20	17		
By che	cking this te tronic mail.	box, y	you a	gree	to a	llow .	ADW	R to c	contact you	[x B	che ele	ecking this box ctronic mail.	c, you agree to a	allow AE	WR 1	to contact you
AIL DRESS											MAIL			orenceconner	Name of		

ECTION 5. Well Construction Diagram ovide a well construction diagram showing all existing well construction features listed in Section	6 and Section 7.
See attached well diagram.	



SECTI	ON 6. W	ELL	COI	NSTI	RUC	TIOI	N D	ETAII	LS			101	r / Environn	SIL	H		55 -		R III	
Drill M	ethod			241			1	Metho	od of Well D)ev	elop	me	nt	Gro	out E	mpla	асеп	ent	Met	nod
☐ Air ☐ Bo ☐ Ca ☐ Du	Rotary red or Aug ble Tool al Rotary d Rotary							☐ Su	rlift	pecif	·у):			CHE	Trei Gra Pres	NE mie P	ump	ed (F	Recomi	mended)
☐ Re	verse Circ	culati	on				N	/letho	d of Sealin	ing at Reduction Points Surface or						or C	Conductor Casing			
☐ Jett☐ Air☐ Oth	ted Percussioner (please	on / C	Odex y):	(Tub	oing					CHECK ONE ☐ Flush Mount in a vault ☑ Extends at least 1' above										
	NSTRUCTION 05/0	1/20	17					☐ Pa	cked ner (please sp	ecif	<i>(</i>):									
SECTIO	ON 7. PR	OPO	SEI) WE	LL	CON	IST	RUC	TION PLAN	(att	ach	ado	itional page if	needed	d)				100	100
Attach a	Boreho	struc	tion	diag	ram	labe	ling	all sp	ecifications	bel	ow.									
	H FROM	le l				DEPT				T	MA	TER	Casing AL TYPE (T)	D	EDEC	RATIO	U TVP	- /		
FROM (feet)	TO (feet)	DV	REH(AMET	ER	FRI	OM	FAC	TO (feet)	OUTER DIAMETER (inches)	STEEL		ABS	IF OTHER TYPE, DESCRIBE	BLANK OR NONE WIRE WRAP	SCREEN		OTTED	OTH TYPE		SLOT SIZ
0	20		18		()		20	14											
20	1210		10		C)		500	5	DDD FRP XDDD										
					50	0	1	1200	5		X						3			0.020
DEPTH	H FROM	-	-					^	Annula NNULAR MATE											
	FACE			۳.	5	BE	NTO	NITE	NNOLAK WATE	KIAL	TYPE	(1			-			F	LTER	PACK
FROM (feet)	TO (feet)	NONE	CONCRETE	NEAT CEMENT OR CEMENT GROUT	CEMENT- BENTONITE GROUT	GROUT	CHIPS	PELLETS	IF	ОТН	ER TY	PE	OF ANNULAR MA ESCRIBE	TERIAL,			SAND	GRAVEL		SIZE
0	490			X	П											_				
490	495							Ħ									X		No	. 30-70
495	1210																			.10-20
THIS WEI	LL HAS NEST	ED CA	ASING	SS, SP	ECIFY	NUM	BER	OF CA	SING STRINGS	E	XPE	CTE	DEPTH TO WAT	TER (Fee		w Grou	nd Sur	face)		
ECTIO	8. PER	MISS	101	OT I	AC	CES	S		بالسنان								- Iran		23	
- 111	- and an online	no or	uno	WOII.	1000	mon	ucuc	ms.)				e p	roperty for the	purpos	e of	taking	wate	er lev	rel	
tate that	this notice	D OV	VNE	RA	ND I	WEL	LC	OWNE	R SIGNAT	URI										
ato mat i	ins nouce is	nied	Lan	mplial	NDE	iin A.	ĸ.S.	9 45-5	96 and is com	plete			rect to the best							
NT NAME TITLE											NT N.	AME	lan Ream, S						ctions)	
DOWNER											NATU L OV		OF .		, ,	3-1	-5"			
E										DAT	E									
via elec	By checking this box, you agree to allow ADWR to contact you via electronic mail.								ontact you	By checking this box, you agree to allow ADWR to contact you via electronic mail.										
IL RESS										EMA ADD	IL RESS	: 12	nReam@flo	rencec	onn	er co	m			



Arizona Department of Water Resources

Groundwater Permitting and Wells
PO Box 36020 • Phoenix, Arizona 85067-6020

(602) 771-8527 • 602-771-8500

www.azwater.gov

Well Driller Report and Well Log

THIS REPORT MUST BE FILED WITHIN 30 DAYS OF COMPLETING THE WELL. PLEASE PRINT CLEARLY USING BLACK OR BLUE INK

FILE NUMBER
D(4-9) 28 CBD
WELL REGISTRATION NUMBER
55 - 227233

PERMIT NUMBER (IF ISSUED)

	ION 1. DRILLING AL	THORIZATION							
Drillin	ig Firm								
	NAME		NITAIN INC	DWR LICENSE NUM	MBER				
ö	HYDRO RESOURCE	S - ROCKY MOU	NTAIN, INC.	816					
=	ADDRESS			TELEPHONE NUME	BER				
Mail To:	13027 COUNTY ROA	AD 18, UNIT C		303-857-7540					
7	CITY / STATE / ZIP			FAX					
-1	FORT LUPTON, CO.	, 80621-9217							
SECT	ION 1. REGISTRY II	NFORMATION	Harry Land		No LE				
Well (Owner			Location of W	/ell				
FULL NA	AME OF COMPANY, ORGANIZA	TION, OR INDIVIDUAL		WELL LOCATION AD	DRESS (IF ANY)				
AZ ST	ATE LAND DEPT.								
MAILING	ADDRESS			TOWNSHIP (N/S)	RANGE (EA	N) SECTION	160 ACRE	40 ACRE	10 ACRE
1616 V	W. ADAMS ST.						1/4	1/4	1/
CITY / S	TATE / ZIP			LATITUDE			LONGITUDE		
PHOE	NIX, AZ, 85007			DEGREES	MINUTES	"N SECONDS	DEGREES	MINUTES	"V SECONDS
CONTAC	CT PERSON NAME AND TITLE			METHOD OF LATITU			DEGREES	MINOTES	SECONDS
				*GPS: Hand-Held	Г	Conventional Survey		*GPS: Surve	v-Grade
TELEPH	IONE NUMBER	FAX		LAND SURFACE ELE				_ Or or ourve	y Oldde
602 54	12-4631	1.000			THIOTH TIEL			Feet Above	Sea Level
WELL N	AME (e.g., MW-1, PZ-3, lot 25 We	ell. Smith Well. etc.)		METHOD OF ELEVA	TION (CHECK ON	IF)			
0-04	(-10)			METHOD OF ELEVA		A contract of			
0-04				*GPS: Hand-Held		Conventional Survey		*GPS: Surve	y-Grade
				*IF GPS WAS USED,	GEOGRAPHIC C	OORDINATE DATUM	CHECK ONE)		
				□NAD-83 □O	ther (please specif	6.0			
					trier (please speci				COLUMN TO THE
				COUNTY			PARCEL ID NUM		
						BOOK	MAP	PAF	RCEL
CECT	ION 2 WELL CONG	TRUCTION DE	TAUC						
SECI	ION 3. WELL CONS	TRUCTION DE	AILS						
			the second secon	II Davidanmant		Mach and a f	2 II4 F	N - 41 - 41 - 1	
Drillin			Method of Wel	II Development		Method of S	Sealing at F	Reduction	Points
Drillin CHECK	ONE		Method of Wel	Il Development		CHECK ONE	Sealing at F	Reduction	Points
Drillin CHECK (ONE Rotary		Method of Wel	II Development		CHECK ONE None	Sealing at F	Reduction	Points
Drillin CHECK (Air I Bore	ONE Rotary ed or Augered		Method of Wel	II Development		CHECK ONE None Packed	Sealing at F	Reduction	Points
Drillin CHECK (Air I Bore	ONE Rotary ed or Augered lle Tool		Method of Wel CHECK ONE Airlift Bail Surge Block	II Development		CHECK ONE None Packed Swedged	Sealing at F	Reduction	Points
Drillin CHECK (Air I Bore Cab Dua	ONE Rotary ed or Augered lle Tool Il Rotary		Method of Wel CHECK ONE Airlift Bail Surge Block Surge Pump			CHECK ONE None Packed Swedged Welded		Reduction	Points
Drillin CHECK (Air Bore Cab Dua Mud	ONE Rotary ed or Augered le Tool Il Rotary I Rotary		Method of Wel CHECK ONE Airlift Bail Surge Block			CHECK ONE None Packed Swedged		Reduction	Points
Drillin CHECK (Air I Bore Cab Dua Mud Reve	ONE Rotary ed or Augered ble Tool il Rotary I Rotary erse Circulation		Method of Wel CHECK ONE Airlift Bail Surge Block Surge Pump Other (please	specify)		CHECK ONE None Packed Swedged Welded Other (plea	ase specify)	Reduction	Points
Drillin CHECK (Air I Bore Cab Dua Mud Revo	ONE Rotary ed or Augered ble Tool il Rotary il Rotary erse Circulation en		Method of Wel CHECK ONE Airlift Bail Surge Block Surge Pump Other (please	specify)		CHECK ONE None Packed Swedged Welded Other (plea	nse specify)		Points
Drillin CHECK (Air Bore Cab Dua Mud Rev Drive	ONE Rotary ed or Augered ble Tool il Rotary il Rotary erse Circulation en		Method of Wel CHECK ONE Airlift Bail Surge Block Surge Pump Other (please Condition of Well CHECK ONE	specify)		CHECK ONE None Packed Swedged Welded Other (plea	nse specify)		Points
Drillin CHECK (Air I Bore Cab Dua Mud Reve Drive Jette Air F	ONE Rotary ed or Augered ble Tool Il Rotary Rotary erse Circulation en ed Percussion / Odex Tubing		Method of Wel CHECK ONE Airlift Bail Surge Block Surge Pump Other (please Condition of Well CAPPED	specify) VeII		CHECK ONE None Packed Swedged Welded Other (please) Construction DATE WELL CON	use specify) on Dates STRUCTION STA	ARTED	Points
Drillin CHECK (Air I Bore Cab Dua Mud Reve Drive Jette Air F	ONE Rotary ed or Augered ble Tool il Rotary il Rotary erse Circulation en		Method of Wel CHECK ONE Airlift Bail Surge Block Surge Pump Other (please Condition of Well CHECK ONE	specify) VeII		CHECK ONE None Packed Swedged Welded Other (plea	use specify) on Dates STRUCTION STA	ARTED	Points
Drillin CHECK (Air I Bore Cab Dua Mud Reve Drive Jette Air F	ONE Rotary ed or Augered ble Tool Il Rotary Rotary erse Circulation en ed Percussion / Odex Tubing		Method of Wel CHECK ONE Airlift Bail Surge Block Surge Pump Other (please Condition of Well CAPPED	specify) VeII		CHECK ONE None Packed Swedged Welded Other (please) Construction DATE WELL CON	use specify) on Dates STRUCTION STA	ARTED	Points
Drillin CHECK (Air Bore Cab Dua Mud Revo Drivo Jette Air F	Rotary ed or Augered ble Tool Il Rotary I Rotary erse Circulation en ed Percussion / Odex Tubing er (please specify)		Method of Well CHECK ONE Airlift Bail Surge Block Surge Pump Other (please Condition of Well CHECK ONE Capped Pump Installed	specify) Vell	ct to the best o	CHECK ONE None Packed Swedged Welded Other (plea	on Dates STRUCTION STA	ARTED	Points
Drillin CHECK (Air I Bore Cab Dua Mud Revu Drivu Jette Air F Othe	ONE Rotary ed or Augered ble Tool Il Rotary Rotary erse Circulation en ed Percussion / Odex Tubing		Method of Well CHECK ONE Airlift Bail Surge Block Surge Pump Other (please Condition of Well CHECK ONE Capped Pump Installed	specify) Vell	ct to the best o	CHECK ONE None Packed Swedged Welded Other (plea	on Dates STRUCTION STA	ARTED	Points

Well Driller Report and Well Log

WELL REGISTRATION NUMBER 55 - 227233

	TION DESIGN	(AS BL	JILD) (att	ach additional page if needed)	
Depth DEPTH OF BORING			DEPTH OF C	OMPLETED WELL	
	Feet Below Land				Feet Below Land Surface
Water Level Information			SIE-		
STATIC WATER LEVEL Feet Below Land Surface	DATE MEASURED	TIME M	EASURED	IF FLOWING WELL, METHOD OF FLOW REGULATION Valve Other:	


	Boreh	ole						In	stalled Casi	na		1 6100				
FRI SURF			DEF FR	OM		- 1	MATER				PERF	ORATIO	ON TYP	PE (X	()	
FROM (feet)	TO (feet)	BOREHOLE DIAMETER (inches)	FROM (feet)	TO (feet)	OUTER (inches)	STEEL	PVC	ABS	IF OTHER TYPE, DESCRIBE	BLANK OR NONE	WIRE WRAP	SHUTTER SCREEN	MILLS KNIFE	SLOTTED	IF OTHER TYPE, DESCRIBE	SLOT SIZE (inches)
		•														

5.23									Installed Annular Material			
DEPTH								ANNU	LAR MATERIAL TYPE (X)	FI	ILTE	R PACK
SURF	ACE			~	ш BEN					T		
FROM (feet)	TO (feet)	NONE	CONCRETE	NEAT CEMENT OR CEMENT GROUT	CEMENT-BENTONITE GROUT	GROUT	CHIPS	PELLETS	IF OTHER TYPE OF ANNULAR MATERIAL, DESCRIBE	SAND	GRAVEL	SIZE
										1		
										+		
										+		
										+	+	
										+		
										T		

		GEOLOGIC LOG OF WELL	
FROM (feet)	TO (feet)	Description Describe material, grain size, color, etc.	Check (X) every interval where water was encountered (if known)
		· · · · · · · · · · · · · · · · · · ·	

SECTION 6. WELL SITE PLAN				
NAME OF WELL OWNER	COUNTY ASSESSOR	R'S PARCEL ID NUMBER (MOST	RECENT)	
AZ STATE LAND DEPT.	воок	MAP	PARCEL	

- Required for all wells, please draw the following: (1) the boundaries of property on which the well was located; (2) the well location; (3) the locations of all septic tank systems and sewer systems on the property or within 100 feet of the well location, even if on neighboring properties; and (4) any permanent structures on the property that may aid in locating the well.
- Please indicate the distance between the well location and any septic tank system or sewer system.





Arizona Department of Water Resources Groundwater Permitting and Wells Section P.O. Box 36020 Phoenix, Arizona 85067-6020 (602) 771-8527 · www.azwater.gov

Request to Change Well Information

Review instructions prior to completing form in black or blue ink.

You must include with your Notice:

check or money order for any required fee(s)

Authority for fee: A.R.S. § 45-113 and A.A.C. R12-15-104

Well ID: 0-04

FILE NUMBER

WELL REGISTRATION NUMBER

55 - 227233

SECTION 4 DECISTOR		******	10. 0 01							
SECTION 1. REGISTRY Well Owner	INFORMATION	I t a a still a	- 6 VA/ - II							
FULL NAME OF COMPANY, ORGA	ANIZATION OR INDIVIDUAL	Location	TION ADDRESS	C/IE ANIVA / O	D CDOCC CT	DEETC				
Florence Copper Compar		WELL LOCA	I ION ADDRES	S (IF ANY) / O	K CRUSS 511	KEEIS				
MAILING ADDRESS	•	TOWNSHIP (N/S)	RANGE (E/W)	SECTION	160 ACRE	40 ACRE	10 ACRE			
1575 W Hunt Hwy		4.0 S	9.0 E	28	SW 1/4					
CITY / STATE / ZIP CODE		LATITUDE			LONGITUDE	/4				
Florence, AZ 85132		33 ° Degrees	2 '	59.29 "N	1 2 4 4 4	26 '	3.87 "v			
CONTACT PERSON NAME AND T	TLE		Minutes LATITUDE/LO	Seconds NGITUDE (CH	Degrees	Minutes *GPS: Ha	Seconds			
Ian Ream, Senior Hydrog		☐ Google I		Convention	nal Survey	T *GPS: S	urvey-Grade			
TELEPHONE NUMBER	FAX	☐ NAD-83	Other (p	lease specif	fy):					
520-374-3984	520-374-3999	COUNTY ASS	SESSOR'S PAR			IS LOCATED	HERE WELL			
		BOOK	IVIA	,	1001	PINAL				
Type of Request (CHECK C	ONE				1001	ITIVAL				
Change of Well Drilling		Vell Ownership		Change o	of Well Info	rmation				
(Fill out Section 2)	(Fill out Sect				use, etc.)		ection 4)			
SECTION 2. REQUEST	TO CHANGE WELL DRILLING	CONTRACTO			- Table 19		per Well			
 If drilling or abandoning 	a well, the Department must receiv	e this request ar	nd issue aut	horization t	to the new	FEE \$120	per weii			
Current Well Drilling Co	he commencement of well drilling of		I Drilling C	ontracto						
FULL NAME OF COMPANY, ORGA	NIZATION, OR INDIVIDUAL	FULL NAME	OF COMPANY,	ORGANIZAT	ION, OR INDIV	VIDUAL				
National EWP					esources	VIDOAL				
DWR LICENSE NUMBER 823		DWR LICENS	SE NUMBER 816		ROC LICENS	NSE CATEGORY				
TELEPHONE NUMBER (480) 558-3500	FAX (480) 558-3525	TELEPHONE (30	NUMBER 03) 857-754	10	FAX					
SECTION 3. STATEMEN	T OF CHANGE OF WELL OW		e jane		F	EE \$30 per	r Well			
Previous Well Owner		New Well	Owner							
FULL NAME OF COMPANY, ORGA	NIZATION, OR INDIVIDUAL	1 1 2 1 2 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2	OF COMPANY,	ORGANIZAT	ION, OR INDIV	VIDUAL				
MAILING ADDRESS				-	-					
MAILING ADDRESS		MAILING ADD	DRESS	KE(EIV	FN				
CITY / STATE / ZIP CODE		CITY / STATE	ZIP CODE							
				FEI	B 1 6 2018					
CONTACT PERSON NAME AND TI	TLE	CONTACT PE	ERSON NAME	AND TITLE	DEDADT	PARPAGE.				
TELEPHONE NUMBER	FAX	TELEPHONE	NUMBER OF	WATE	PAXESOL	JRCES				
SECTION 4 CHANGE O	F WELL INFORMATION (No Fee	Domilio d								
							1-1			
NOTE: Applies only to wells t	hat have already been drilled. For	proposed wells,	an amended	d Notice of	Intent to Dr	ill a Well m	ust be filed			
EXPLAIN										
	BY PROPERTY OWNER AND			A (0.555)			78888			
By checking this box measurements at this	, I hereby provide ADWR permissions well. (See instructions.)	n to enter the pr	operty for th	e purpose	of taking wa	ater level				
SECTION 6. WELL OWN			J	S125/1-	3 10 10	C Capación	Epil Ses			
I HEREBY CERTIFY that the	above statements are true to the b	est of my knowle	edge and be	elief.		- de-				
TYPE OR PRINT NAME AND TITLE			OF WELL OWN		-		DATE			
lan Ream, Senior Hydroge	ologist	1/10			2-14-	2018				
		16				-				

Printed: 2/16/2018 9:53:20 AM

Arizona Department of Water Resources

1110 West Washington Street, Suite 310 Phoenix AZ 85007

Customer:

BURLINGTON, MA 01803 LINDA L. DOMBRAWSKI 70 BLANCHARD ROAD SUITE 204

> Receipt #: 18-56793

Office: Engineering and Peri

Receipt Date: 02/16/2018

Sale Type: Mail

CHANGE OF WELL DRILLER CONTRACTOR OR REISSUE Ref ID Cashier: RECEIPT TOTAL: WRPXA Qty w Unit Price 120.00

Ext Price

360.00

360.00

Payment type: CREDIT CARD

91

WRFREV

4439-12 AOBJ

Description

Item No. Function Code

Amount Paid: \$360.00

Authorization 011621

Payment Received Date: 02/16/2018

Notes: Credit Card Payment for \$360.00 is for well registration number 55-227231, 55-227233 and 55-227235 Run Date: 04/25/2017

AZ DEPARTMENT OF WATER RESOURCES

WELL REGISTRY REPORT - WELLS55

Well Reg.No

Location D 4.0 9.0 28 CBD

55 - 227233

AMA PINAL AMA

Registered

AZ STATE LAND DEPT.

Name

1616 W. ADAMS ST.

ATTN: LISA ATKINS

PHOENIX

AZ 85007

File Type NEW WELLS (INTENTS OR APPLICATIONS)

Application/Issue Date 04/19/2017

Owner OWNER

Driller No. 823

Driller Name NATIONAL EWP, INC.

Driller Phone 480-558-3500

County PINAL

Well Type ENV - MONITOR

SubBasin ELOY

Watershed UPPER GILA RIVER

Registered Water Uses MONITORING

Registered Well Uses MONITOR

Discharge Method NO DISCHARGE METHOD LISTED

Power NO POWER CODE LISTED

Intended Capacity GPM

0.00

Case Diam 0.00 0.00

Tested Cap

0.00

Pump Cap. **Draw Down**

Well Depth

0.00 0.00 0.00

Case Depth Water Level Acres Irrig

0.00 0.00 CRT Log

Finish NO CASING CODE LISTED

Contamination Site:

NO - NOT IN ANY REMEDIAL ACTION SITE

Tribe: Not in a tribal zone

Comments Well O-04

AZ State Land Dept. Mineral Lease #11-026500

Current Action

4/25/2017

555 DRILLER & OWNER PACKETS MAILED

Action Comment: TNV

Action History

4/25/2017

550 DRILLING AUTHORITY ISSUED

Action Comment: TNV

4/19/2017

155

NOI RECEIVED FOR A NEW NON-PRODUCTION WELL

Action Comment: TNV

ARIZONA DEPARTMENT OF WATER RESOURCES

1110 W. Washington St. Suite 310 Phoenix, Arizona 85007

THIS AUTHORIZATION SHALL BE IN POSSESSION OF THE DRILLER DURING ALL DRILLING OPERATIONS

WELL REGISTRATION NO: 55-227233 WELL OWNER ID: O-04

AUTHORIZED DRILLER: NATIONAL EWP, INC.

LICENSE NO: 823

NOTICE OF INTENTION TO DRILL ENV - MONITOR WELL(S) HAS BEEN FILED WITH THE DEPARTMENT BY:

WELL OWNER: AZ STATE LAND DEPT. 1616 W. ADAMS ST. ATTN: LISA ATKINS PHOENIX, AZ, 85007

THE WELL(S) IS/ARE TO BE LOCATED IN THE:

SE 1/4 of the NW 1/4 of the SW 1/4 Section 28 Township 4.0 SOUTH Range 9.0 EAST

NO. OF WELLS IN THIS PROJECT:

THIS AUTHORIZATION EXPIRES AT MIDNIGHT ON THE DAY OF April 19, 2018

Sulla murillo

GROUNDWATER PERMITTING AND WELLS

THE DRILLER MUST FILE A LOG OF THE WELL WITHIN 30 DAYS OF COMPLETION OF DRILLING.



ARIZONA DEPARTMENT of WATER RESOURCES

1110 W. Washington St. Suite 310 Phoenix, AZ 85007 602-771-8500 azwater.gov

April 25, 2017

AZ STATE LAND DEPT. 1616 W. ADAMS ST. ATTN: LISA ATKINS PHOENIX, AZ 85007

Registration No. 55- 227233 File Number: D(4-9) 28 CBD

Dear Well Applicant:



DOUGLAS A. DUCEY Governor

THOMAS BUSCHATZKE
Director

Enclosed is a copy of the Notice of Intention to Drill (NOI) a well which you or your driller recently filed with the Department of Water Resources. This letter is to inform you that the Department has approved the NOI and has mailed, or made available for download, a drilling authorization card to your designated well drilling contractor. The driller may not begin drilling until he/she has received the authorization, and must keep it in their possession at the well site during drilling. Although the issuance of this drill imposed by other entities.

Well drilling activities must be completed within one year after the date the NOI was filed with the Department. If drilling is not completed within one year, a new NOI must be filed and authorization from this Department received before proceeding with drilling. If the well cannot be successfully completed as initially intended (dry hole, cave in, lost tools, etc.), the well must be properly abandoned and a Well Abandonment Completion Report must be filed by your driller [as required by A.A.C.

If you change drillers, you must notify the Department of the new driller's identity on a Request to Change Well Information (form 55-71A). Please ensure that the new driller is licensed by the Department to drill the type of well you require. A new driller may not begin drilling until he/she receives a new drilling authorization card from the Department.

If you find it necessary to change the location of the proposed well(s), you may not proceed with drilling until you file an amended NOI with the Department. An amended drilling authorization card will then be issued to the well drilling contractor, which must be in their possession before drilling begins.

Arizona statute [A.R.S. § 45-600] requires registered well owners to file a Pump Installation Completion Report (form 55-56) with the Department within 30 days after the installation of pumping equipment, if authorized. A blank report is enclosed for your convenience. State statute also requires the driller to file a complete and accurate Well Drillers Report and Well Log (form 55-55) within 30 days after completion of drilling. A blank report form was provided to your driller with the drilling authorization card. You should insist and ensure that all of the required reports are accurately completed and timely filed with the Department.

Please be advised that Arizona statute [A.R.S. § 45-593(C)] requires a registered well owner to notify the Department of a change in ownership of the well and/or information pertaining to the physical characteristics of the well in order to keep this well registration file current and accurate. Any change in well information or a request to change well driller must be filed on a Request to Change Well Information form (form 55-71A) that may be downloaded from the ADWR Internet website at www.azwater.gov.

Sincerely.

Groundwater Permitting and ₩ells Section

Arizona Department of Water Resources Groundwater Permitting and Wells Section P.O. Box 36020 Phoenix, Arizona 85067-6020 (602) 771-8500 • (602) 771-8690

Notice of Intent to
Drill, Deepen, or Modify a

Monitor / Piezometer / Environmental Well

\$150 FEE

*	Review	instructions	prior t	o completing	form i	in black	or blue ink.

You <u>must</u> include with your Notice:

\$150 check or money order for the filing fee.

, SECTION 1. REGISTRY INFORMATION

· www.azwater.gov ·

 Well construction diagram, labeling all specifications listed in Section 6 and Section 7.
 Authority for fee: A.R.S. § 45-596 and A.A.C. R12-15-104.


Pinal P	IN II	DIA-9 28 CBD
4/19/2017	OB UGR	WELL REGISTRATION NUMBER
4/25/2017 S	MEDIAL ACTION SITE	55-221255


Well Type	Proposed Action	91/1-	Locati	on of Well										
CHECK ONE	CHECK ONE	-11-11	WELL LO	CATION ADDRE	ESS (IF ANY)									
	☑ Drill New Well 400		100	17										
Piezometer	☐ Deepen	100	TOWNSHIP	(N/S) RANGE (E/	W) SECTION	160 ACRE	40 ACRE	10 ACF						
) 프립싱싱() (1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	D Madis.	0 40	74.0 S	9.0 E	28	SW 1/	NW 1/	SE						
☐ Vadose Zone	☐ Modify		COUNTY	ASSESSOR'S F		/4	NW 1/4	313						
☐ Air Sparging	WELL REGISTRATION NUMBER		COUNTY	ASSESSOR'S I	ARCEL ID NUM	MBER	1							
Soil Vapor Extraction	(if Deepening or Modifying)		воок		MAP		PARCEL	1001						
Other (please specify):	55 -		COUNTY	WHERE WELL	IS LOCATED		-							
				PIN	VAL									
SECTION 2. OWNER INF	ORMATION													
Land Owner			Well C	wner (check	this box if Land	Owner and We	Il Owner are sa	me						
FULL NAME OF COMPANY, ORGAN	IZATION, OR INDIVIDUAL		FULL NA	ME OF COMPAN	Y, GOVERNM	ENT AGENCY	OR INDIVIDUA	AL						
AZ State Land Dept (Mine	ral Lease # 11-026500)		FULL NAME OF COMPANY, GOVERNMENT AGENCY, OR INDIVIDUAL Florence Copper, Inc.											
MAILING ADDRESS			MAILING ADDRESS											
1616 W Adams St			1575 W	/ Hunt Hwy										
CITY / STATE / ZIP CODE			CITY/ST	TATE / ZIP CODE	1									
Phoenix, AZ 85007				e, AZ 8513										
CONTACT PERSON NAME AND TITI			The second second second	T PERSON NAM										
Lisa Atkins, State Land Co	mmissioner			am, Senior I	Hydrogeolog	gist								
TELEPHONE NUMBER	FAX			ONE NUMBER		FAX	26 043 2040	at land						
(602) 542-4631			(520) 374-39	984		(520) 374-	3999						
SECTION 3. DRILLING A	UTHORIZATION													
Drilling Firm			Const	Iltant (if applic	able)									
NAME National EWP				TING FIRM										
	ROC LICENSE		CONTAC	& Aldrich, Inc. T PERSON NAM	C.									
DWR LICENSE NUMBER 823	CATEGORY A-4		Mark N		-									
TELEPHONE (480) 558-3500	FAX 480-558-3525		TELEPHO	ME	60-2423	FAX CO	0.700.044	2						
NUMBER (400) 556-5500	FAX 480-558-3525		NUMBER	602-7	60-2423	60	2-760-2448	3						
ADDRESS jstephens@nation	nalewp.com		EMAIL ADDRESS	mnicholls	@haleyaldi	rich.com								
SECTION 4.														
Questions		Yes	No	Explanatio	n			_						
				2-inch annular		cial standard	s required for v	vells loca						
 Are all annular spaces between the placement of grout at least 2 		\boxtimes		in and near gro WQARF, DOD	undwater conta , LUST).	amination site	s (such as CE	RCLA,						
Is the screened or perforated in feet in length?	terval of casing greater than 100	\boxtimes		100-foot maxim located in and CERCLA, WQA	near groundwa	ter contamina	pecial standard tion sites (suc	l for wells n as						
Are you requesting a variance to of steel casing in the surface se			\boxtimes	The wells must R12-15-801 (2)	be constructed 7) a "vault" is d	d in a vault. P efined as a ta	mper-resistant							
 Is there another well name or id with this well? (e.g., MW-1, PZ2 		X		structure used to complete a well below the land surface. If yes, please state O-04										
Have construction plans been c Department of Environmental Q	oordinated with the Arizona	X		If yes, please state agency contact & phone number David Haag, 602-771-4669										
6. For monitor wells, is dedicated p	oump equipment to be installed?		If yes, please state design pump capacity (Gallons per Minute)											
7. Is this well a new well located in AND intended to pump water fo groundwater?			\boxtimes	You must also file a supplemental form A.R.S. § 45-454(c) & (f) unless the well is a replacement well and the total number of operable wells on the site is not increasing. (See instructions)										
Will the well registration number on the upper part of the casing?	be stamped on the vault cover or	X		If no, where will the registration number be placed?										


	N 6. WE	LL C	ONS	STR	UCT	ION	$\overline{}$										-				
Drill Me									of Well De	evel	op	ne	nt			Emp	lace	me	nt N	/leth	od
☐ Bore ☐ Cabl ☐ Dual ☑ Mud	☐ Dual Rotary ☑ Mud Rotary						1	Sur	ift	ecify):				Gra		e Gr	out		comm	ended)
		ılatio	n				IV	ethod	l of Sealing	at	Re	duc	tion Points	Su	rfac	e or	Con	du	ctor	Cas	sina
☐ Drive							4	HECK O			-	6140			СКО						3
☐ Air P☐ Othe	☐ Air Percussion / Odex Tubing ☐ Other (please specify): DATE CONSTRUCTION TO BEGIN								lded edged							sh M ends					e grade
DATE COM	05/01						۱Ł	Pac Oth	:кеа er (please spe	ecify)):										
								RUCT	ION PLAN	(atta	ich :	add	itional page if	neede	ed)						
Attach a			ion c	liagi	am I	abel	ing	all spe	ecifications l	pelo	w.										
DEPTH	Borehol	е				EPTH	LED	264		_	111	reni	Casing AL TYPE (T)		DEDE	ODATI	O. 1. T.	/DE	/ m 1	_	
SURF					1	SUR					MA	ERI	AL TYPE (T)			ORATI		YPE	(1)	-	
FROM (feet)	TO (feet)	DIA	REHO METE nches)	R	FRO		i G	TO (feet)	OUTER DIAMETER (inches)	STEEL	PVC	ABS	IF OTHER TYPE, DESCRIBE	BLANK OR NONE	SHUTTER	MILLS	SLOTTED	T	OTHE TYPE, SCRII		SLOT S IF AN
0	20		18		C).		20	14	X				\times							
20	1210		10		0		1	500	5	X			reinforced	X							
					50	0	1	200	5	12	X	Į.					X				0.02
									Annula												
DEPTH						BE	NTO		NNULAR MATER	RIAL	TYPI	(T)					_	FI	LTER	PACK
FROM (feet)	TO (feet)	NONE	CONCRETE	NEAT CEMENT OR CEMENT GROUT	CEMENT- BENTONITE GROUT	GROUT	CHIPS	100	IF	OTHE	ER T		OF ANNULAR MA DESCRIBE	ATERIA	L,			SAND	GRAVEL		SIZE
0	490			X				П									+	1			
490	495							Ħ									-			No	o. 30-
495	1210							Ħ									Ī		R		0.10-2
F THIS WE	LL HAS NEST	ED C	ASING	S, SF	ECIF	Y NUN	ABEF	OF CA	SING STRINGS	F	XPE	CTE	D DEPTH TO WA			elow G	round	Surt	face)		
CECTION	U.O. DED	MALO	2101	i i me		050				1		_		2	20						
By		this I	oox,	l her	eby p	orovi	de A		permission to	en	ter t	he j	property for the	e purp	ose	of tak	ing v	vate	er lev	/el	-
	easureme								-D 010111-		_										
					_				ER SIGNAT	_		d co	rrect to the best	of m	kna	ulo d=					
are with				-	wne	-		. 3 70-	oo ana is con	Piet	o dil		ell Owner (if di					_	Insta	iction	-1
RINT NAME											INT D TI	MAI			- Y,					1000118	2/
GNATURE										SIG	NAT	URE	OF 1/)	on!!	,	J-01	-3"	- T. T.		
ATE				7	Ŧ					100	TE	ANIAI	de	1-1	7	70	1-7				
	ecking this ctronic mail		you a	agree	to a	llow	ADV	VR to d	contact you	x	B	y ch	necking this box	, you	agre		17 allow		WR	to co	ntact yo
MAIL DDRESS	<u> </u>									EM	AIL		lanReam@fl	oreno	eco	nner	com	1			

WELL REGISTRATION NUMBER


ECTION 5. Well Construction Diagram	
ovide a well construction diagram showing all existing well construction features listed in Section 6 and Section 7.	
See attached well diagram.	








Arizona State Land Department



April 25, 17



Source: Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS, AeroGRID, IGN, and the GIS User

Torren Valdez

From: Justina Speas <jspeas@nationalewp.com>
Sent: Wednesday, April 26, 2017 10:10 AM

To: Torren Valdez
Subject: FW: ADWR Issue
Attachments: Rev_pg3_FRP.pdf

Please see below.

Thank you,

Justina Speas
Office Manager
National EWP, Inc.
1200 W. San Pedro St.
Gilbert, AZ 85233
480-558-3500 PH
480-798-4722 CL
480-558-3525 FX
ispeas@nationalewp.com

From: Candreva, Lauren [mailto:LCandreva@haleyaldrich.com]

Sent: Wednesday, April 26, 2017 10:05 AM

To: Justina Speas < jspeas@nationalewp.com

Cc: lan Ream < jspeas@nationalewp.com

Subject: RE: ADWR Issue

Hi Justina,

Please see the attached pg 3 of the NOI form, this form will be the same for all 7 wells since it does not contain any of the well names or locations. However, it is also the page that has the signature block, so please confirm with your ADWR contact that it will not require a signature to complete this file.

Thanks, Lauren

From: Justina Speas [mailto:jspeas@nationalewp.com]

Sent: Tuesday, April 25, 2017 2:09 PM

To: Candreva, Lauren < LCandreva@haleyaldrich.com>

Cc: Ian Ream < IanReam@florencecopper.com>

Subject: ADWR Issue

Good Afternoon,

I just spoke with Torren Valdez with ADWR, and he informed me of an error with some of the NOI's we just turned in. On O-01 through O-07 the well construction plan shows 0 to 500' as steel, but that is not what the diagram shows.

He said we can just fix the page with the construction plan and email him a copy, and he will put it with the file.

Justina Speas Office Manager National EWP, Inc. 1200 W. San Pedro St. Gilbert, AZ 85233 480-558-3500 PH 480-798-4722 CL 480-558-3525 FX jspeas@nationalewp.com

the transfer with the contract	ON 6. WE	LL C	ON	STF	RUCT	ION	DE	TAIL	S				2193		700					
Drill Me									d of Well Do	eve	lop	mei	nt			mpla	cem	ent l	Vieth	od
☐ Bord ☐ Cab ☐ Dua ☑ Mud	☐ Dual Rotary						100	Su	lift	ecify):			CHECK ONE ☑ Tremie Pumped (Recommended) ☐ Gravity ☐ Pressure Grout ☐ Other (please specify):						ended)
☐ Rev		ulatio	n				M	letho	d of Sealing	at	Re	duc	tion Points	Sur	face	or C	ondı	icto	Cas	ing
☐ Jett							CH	HECK O	NE					CHEC	KON	E				
	Percussio er (please s			Tub	ing				lded							h Moi nds a				e grade
DATE CON	ISTRUCTION 05/01			Ī] Pad	edged oked ier (<i>please sp</i> e	cify):									
SECTIO	N 7. PR	OPO	SED	WE	ELL (CON	STI	RUCT	ION PLAN	(atta	ach a	addi	tional page if i	needed	i)					
Attach a	well cons	truct	ion (diag	ram l	abel	ing	all sp	ecifications l	belo	w.									
DEDTI	Boreho H FROM	le				COTI	LED	211					Casing							
	FACE					SUR	FACE			H	MA	ERI	AL TYPE (T)		100	RATION	TYPE	(T)		
FROM (feet)	TO (feet)	DIA	REHO METE nches,	R	FR(TO (feet)	OUTER DIAMETER (inches)	STEEL	PVC	ABS	IF OTHER TYPE, DESCRIBE	BLANK OR NONE WIRE WRAP	SCREEN	MILLS		OTHE TYPE, SCRI		SLOT SIZE IF ANY (inches)
0	20		18		C)		20	14	X				X						
20	1210		10		C		18	500	5				FRP	X						
					50	0	1	200	5		\boxtimes									0.020
DED.	res at a	_							Annula											
	FACE			1~	T .	BE	NTON		NNULAR MATER	KIAL	TYPE	(1)		-	-		+	FI	LTER	PACK
FROM (feet)	TO (feet)	NONE	CONCRETE	NEAT CEMENT OR	CEMENT- CEMENT- BENTONITE GROUT	GROUT	CHIPS	PELLETS	IF (OTHE	R T	PE (DF ANNULAR MA ESCRIBE	TER I AL,			SAND	GRAVEL		SIZE
0	490			X																
490	495																X		No	. 30-70
495	1210																X		No	.10-20
F THIS WE	LL HAS NEST	TED C	ASING	S, SI	PECIF	NUN	MBER	OF CA	SING STRINGS	E	XPE	CTE	D DEPTH TO WA	TER (Fee		w Grou	ind Sui	face)		
SECTIO	N 8. PER	MIS	SION	V TC) AC	CES	SS			_					_					
В	y checking	this I	oox,	her	eby p	rovi	de A	DWR	permission to	ent	er ti	ne p	roperty for the	purpo	se of	takin	g wat	er lev	/el	
	N 9 I AN				_				R SIGNAT	UP'	_									
												100	rect to the best	of must	nol-	alar-			-	
STATE WAS					wne		.,,,,	. y 70-	oso anu is com	ριειι		2000000	Il Owner (if dil						-11	
RINT NAME											INT N	IAME							ctions)	
GNATURE IND OWNE										SIG	NAT	JRE		Seriioi	пус	loge	ologi	St		
ATE										DA	2					-	-			
By che	ecking this ctronic mail.	box,	you a	gree	to a	llow .	ADW	/R to d	contact you	x	By	chi ele	ecking this box ctronic mail.	, you a	gree	to allo	w AD	WR	to cor	tact you
MAIL										EM			anReam@flo							

Torren Valdez

From:

Robert Harding <RHarding@azland.gov>

Sent:

Tuesday, April 25, 2017 9:49 AM

To:

Torren Valdez

Subject:

ASLD (Landowner) Approval for NOI's - Lease #11-26500

FYI

From: Robert Harding

Sent: Wednesday, March 15, 2017 2:31 PM

To: samurillo@azwater.gov

Cc: Fred Breedlove <FBreedlove@azland.gov>; Joe Dixon <jdixon@azland.gov>; Heide Kocsis <HKocsis@azland.gov>

Subject: ASLD (Landowner) Approval for NOI's - Lease #11-26500

Stella,

As you are aware, Florence Copper is in the presence of registering a number of existing wells on State Trust Lease #11-26500 which were originally installed using single registration numbers to permit multiple monitor well installations. A number of these wells will then be permanently abandoned in accordance with Arizona Department of Water Resources (ADWR) requirements. The lessee, Florence Copper, has discussed the specifics of this registration/abandonment process with the Arizona State Land Department (ASLD), and the Department has no objection to the proposed activities.

Please accept this email as documentation of Landowner's approval for the Notice of Intent (NOI) application filings for well registration and abandonment, currently being submitted to ADWR by Florence Copper on ASLD Lease #11-26500, Section 28, T4S, R9E.

Thank you. Best regards,

Bob Harding
Hydrologist
Water Rights Section
Arizona State land Department
602.542.2672
rharding@azland.gov



Torren Valdez

From:	Ian Ream <ianream@florencecopper.com></ianream@florencecopper.com>
Sent:	Friday, January 13, 2017 9:06 AM
To:	Torren Valdez
Subject:	Re: Map of monitor well locations
Subject.	ne. map of moment near recursors
Hi Torren,	
The pumps will be QEC samples. The flow rate foot.	micro purge. They typically do a liter or two a minute. Very low flow. Looking for discreet interval is based on drawdown. The goal is not to draw down the well much more than a half a foot or 1
Thanks,	
Ian Ream	
Senior Hydrogeologist	
Florence Copper	
On Jan 13, 2017, at 8:5	6 AM, Torren Valdez < <u>tvaldez@azwater.gov</u> > wrote:
lan,	
Would you hap those monitor	open to know the pump capacity (gpm) for the low-flow pumps that will be installed on ing wells?
Thank you,	
Torren Valdez Water Planning Arizona Departi 602.771.8614	& Permitting Division nent of Water Resources
<image002.jpg< td=""><td>></td></image002.jpg<>	>
Sent: Thursday To: Torren Val	m [<u>mailto:lanReam@florencecopper.com</u>] v, January 12, 2017 11:13 AM dez < <u>tvaldez@azwater.gov</u> > of monitor well locations
Hi Torren,	
Here is a map	with the well locations.
Please don't he	esitate to contact me if you need anything else or have any questions.
Cheers,	
lan	

lan Ream Senior Hydrogeologist

<image003.jpg>

Florence Copper Inc.
1575 W. Hunt Highway Florence AZ USA 85132
C 520-840-9604 T 520-374-3984 F 520-374-3999
E ianream@florencecopper.com Web florencecopper.com

*Notice Regarding Transmission

This message is intended only for the person(s) to whom it is addressed and may contain information that is privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination or copying of this communication is prohibited. Please notify us of the error in communication by telephone (778-373-4533) or by return e-mail and destroy all copies of this communication. Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent those of Taseko Mines Limited or any affiliated or associated company. The recipient should check this email and any attachments for the presence of viruses. Neither Taseko Mines Limited nor any affiliated or associated company accepts any liability for any damage caused by any virus transmitted by this email. Thank you."

*Notice Regarding Transmission

This message is intended only for the person(s) to whom it is addressed and may contain information that is privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination or copying of this communication is prohibited. Please notify us of the error in communication by telephone (778-373-4533) or by return e-mail and destroy all copies of this communication. Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent those of Taseko Mines Limited or any affiliated or associated company. The recipient should check this email and any attachments for the presence of viruses. Neither Taseko Mines Limited nor any affiliated or associated company accepts any liability for any damage caused by any virus transmitted by this email. Thank you."

NOTICE

A.R.S. § 41-1030(B), (D), (E) and (F) provide as follows:

- B. An agency shall not base a licensing decision in whole or in part on a licensing requirement or condition that is not specifically authorized by statute, rule or state tribal gaming compact. A general grant of authority in statute does not constitute a basis for imposing a licensing requirement or condition unless a rule is made pursuant to that general grant of authority that specifically authorizes the requirement or condition.
- D. This section may be enforced in a private civil action and relief may be awarded against the state. The court may award reasonable attorney fees, damages and all fees associated with the license application to a party that prevails in an action against the state for a violation of this section.
- E. A state employee may not intentionally or knowingly violate this section. A violation of this section is cause for disciplinary action or dismissal pursuant to the agency's adopted personnel policy.
- F. This section does not abrogate the immunity provided by section 12-820.01 or 12-820.02.

ARIZONA DEPARTMENT of WATER RESOURCES 1110 W. Washington St. Suite 310 Engineering and Permits Division Phoenix, AZ 85007 602-771-8500

NOTICE TO WELL DRILLERS

This is a reminder that a valid drill card be present for the drilling of each and every well constructed on a site.* The problem seems to occur during the construction of a well when an unexpected problem occurs. Either the hole collapses, the hole is dry, a drill bit is lost and can't be recovered, or any number of other situations where the driller feels that he needs to move over and start another well. If you encounter this type of scenario, please be aware drillers do not have the authority to start another well without first obtaining drilling authority for the new well. Please note the following statutes and regulations pertaining to well drilling and construction:

ARIZONA REVISED STATUTE (A.R.S.) A.R.S. § 45-592.A.

A person may construct, replace or deepen a well in this state only pursuant to this article and section 45-834.01. The drilling of a well may not begin until all requirements of this article and section 45-834.01, as applicable, are met.

A.R.S. § 594.A.

The director shall adopt rules establishing construction standards for new wells and replacement wells, the deepening and abandonment of existing wells and the capping of open wells.

A.R.S. § 600.A

A well driller shall maintain a complete and accurate log of each well drilled.

ARIZONA ADMINISTRATIVE CODE (A.A.C.)

A.A.C. R12-15-803.A.

A person shall not drill or abandon a well, or cause a well to be drilled or abandoned, in a manner which is not in compliance with A.R.S. Title 45, Chapter 2, Article 10, and the rules adopted thereunder.

A.A.C. R12-15-810.A.

A well drilling contractor or single well licensee may commence drilling a well only if the well drilling contractor or licensee has possession of a drilling card at the well site issued by the Director in the name of the well drilling contractor or licensee, authorizing the drilling of the specific well in the specific location.

A.A.C. R12-15-816.F.

In the course of drilling a new well, the well may be abandoned without first filing a notice of intent to abandon and without an abandonment card.

* THIS REQUIREMENT DOES NOT PERTAIN TO THE DRILLING OF MINERAL EXPLORATION, GEOTECHNICAL OR HEAT PUMP BOREHOLES

DWR 37-61 (02-13)

Transaction Receipt - Success

Arizona Water Resources Arizona Water Resources MID:347501639533 1700 W Washington St Phoenix, AZ 85012 602-771-8454

04/19/2017 11:49AM Remittance ID Arizona041917144729704Chr Transaction ID: 183294013

KELSEY SHERRARD 500 Main Street WOODLAND, California 95695 United States Visa - 3420 Approval Code: 050257

Sale

Amount: \$1,650.00

multiple
N/A
Cash receipts
0
dgchristiana@azwater.gov

Cardmember acknowledges receipt of goods and/or services in the amount of the total shown hereon and agrees to perform the obligations set forth by the cardmember's agreement with

the issuer.

Signature click here to continue

Printed: 4/19/2017 12:26:46 PM

Arizona Department of Water Resources

1110 West Washington Street, Suite 310

Phoenix AZ 85007

Customer:

KELSEY SHERRARD NATIONAL EWP **500 MAIN STREET** WOODLAND, CA 95695

Receipt #:

17-50968

Office:

MAIN OFFICE

Receipt Date: 04/19/2017

Sale Type:

Mail

Cashier:

WRDGC

Item No.	Function Code	AOBJ	Description	Ref ID	Qty	Unit Price	Ext Price
8505	122221	4439-6F	MONITOR, PIEZOMETER, AIR SPARGING, SOIL VAPOR EXTR	multiple wells	11	150.00	1,650.00
		54555			RECEIPT	TOTAL:	1,650.00

Payment type: CREDIT CARD

Amount Paid: \$1,650.00

Payment Received Date: 04/19/2017

Authorization 183294013

Notes:

APPENDIX B

Lithologic Log

HALEY ALDRICH	LITHOLOGIC LOG	O-04
Client Florence C	Test Facility, Florence, Arizona Copper, Inc. rilling LLC	File No. 129687 Sheet No. 1 of 15 Cadastral Location D (4-9) 28 CB
Borehole Diameter(s) 2	Reverse Rotary Land Surface Elevation 1476.94 feet, amsl 20/12.25 in. Datum State Plane NAD 83 Location N 745,989 E 847,624	Start 4 January 2018 Finish 20 January 2018 H&A Rep. S. Kaney
Depth (ft) Elevation USCS Symbol Stratum Change Depth (ft)	VISUAL-MANUAL IDENTIFICATION AND DESCRIPTION	COMMENTS
- 0	(0-50 feet)UBFU	Well Registry ID: 55-2527233 Surface Completion: Locking Well Vault & Concrete Pad Well casing stickup: 2.36 feet al COLOR IDENTIFICATION MADE WITH WET SAMPLES USING MUNSELL CHART
-40	WELL GRADED SAND (50-60 feet) Primarily fine to coarse sand with ~5% fines and trace gravel up to 4mm. Sand is subrounded to angular. Fines are nonplastic, no toughness, low dry strength, (7.5YR 5/4), and no reaction to HCL. UBFU SILTY SAND with GRAVEL (60-75 feet) Primarily fine to medium sand with ~15% fines and ~5% gravel up to 6mm. Sand is subrounded to angular and gravel is	Surface Casing: 14-inch mild steel; 0 - 40 feet Well Casing: Nominal 5-inch diameter Fiberglass Reinforced; -2.36 - 501 feet Unit Intervals: UBFU: 0 - 280 feet
- 65	subangular to subrounded. Fines have low plasticity, low toughness, medium dry strength, (7.5YR 5/4), and no reaction to HCL. UBFU s, group symbols, and grain-size determinations based on the USCS visual-manual method (Haley	MGFU: 280 - 302 feet LBFU: 302 - 390 feet Oxide Bedrock: 390 - 1224 feet

HZ	XFB	Y	Н	LITHOLOGIC LOG	O-04 File No. 129687 Sheet No. 2 of 15
Depth (ft)	Elevation	USCS Symbol	Stratum Change Depth (ft)	VISUAL-MANUAL IDENTIFICATION AND DESCRIPTION	
- 75 	1400-	CL	80	SANDY CLAY with GRAVEL (80-90 feet) Primarily fines with $\sim 10\%$ sands and	
- - - 85 -	1395 - - 1390-			$\sim\!25\%$ gravel up to 4mm. Sand and gravel is subrounded to angular. Fines have medium plasticity, low toughness, high dry strength, (7.5YR 5/4), and strong reaction to HCL. UBFU	
95	1385- 1385- 1 1 1380-	SW	90	WELL GRADED SAND (90-100 feet) Primarily medium to fine sand with ~5% gravel up to 10mm. Sand is subrounded to angular and gravel is subangular to subrounded. Fines are nonplastic, no toughness, no dry strength, (7.5YR 4/6), and no reaction to HCL. UBFU	
- -	1375	CL	100	<u>FAT CLAY < B > ></u> (100-105 feet) Primarily fines ~15% sands. Sand is subrounded. Fines have medium plasticity, medium toughness, high dry strength, (7.5YR 4/6), and moderate reaction to HCL. UBFU	Seal: Type V neat cement 0 - 473 feet Fine sand/bentonite 473 - 48 feet
- -110-	1370- 1370- 1365-	SW	105	WELL GRADED SAND (105-115 feet) Primarily medium to coarse sand with ~5% fines and trace gravel up to 5mm. Sand is subrounded to angular. Fines are nonplastic, no toughness, no dry strength, (7.5YR 5/4), and no reaction to HCL. UBFU	
120	1360- 1355-	СН	115	CLAY with SILT (115-125 feet) Primarily fines with ~15% sands. Sand is subrounded to angular. Fines have high plasticity, low toughness, high dry strength, and strong reaction to HCL. UBFU	
- - -130	1350- 1345-	SP- SM	125	POORLY GRADED SAND with CLAY and SILT (125-135 feet) Primarily fine to medium sand with ~30% fines and trace gravel up to 3mm. Sand and gravel is subrounded to angular. Fines have low plasticity, low toughness, medium dry strength, (7.5YR 4/6), and strong reaction to HCL. UBFU	
-135 135 	1340-	SP	135	POORLY GRADED SAND (135-140 feet) Primarily fine to medium sand with ~5% fines and ~5% gravel up to 4mm. Sand is subrounded to angular and gravel is subrounded. Fines are nonplastic, no toughness, no dry strength, (7.5YR 4/6), and weak reaction to HCL. UBFU	
- - - - -145	1335- 1335- 1 1330-	эW		<u>WELL GRADED SAND</u> (140-150 feet) Primarily medium to fine sand with $\sim 5\%$ fines and trace gravel up to 4mm. Sand is subrounded to angular. Fines are nonplastic, no toughness, no dry strength, (7.5YR 4/4), and no reaction to HCL. UBFU	
- -	1325	СН	150	<u>CLAY with SILT</u> (155-155 feet) Primarily fines with $\sim 30\%$ sands and trace gravel. Sand and gravel is subangular to subrounded. Fines have medium plasticity, medium toughness, high dry strength, (7.5YR 5/4), and strong reaction to HCL. UBFU	
-155 - - - - - -160	1320-	SW	155	WELL GRADED SAND (155-165 feet) Primarily fine to medium sand with $\sim 5\%$ fines and $\sim 10\%$ gravel up to 3mm. Sand is subrounded to angular and gravel is subangular to subrounded. Fines are nonplastic, no toughness, no dry strength, (7.5YR 5/4), and weak reaction to HCL. UBFU	
NOTE				is, group symbols, and grain-size determinations based on the USCS visual-manual method (Haley Field Practice for Soil Identification and Description).	O-04

Н		Y	ALI	LITHOLOGIC LOG	O-04 File No. 129687
	NLL.	/RIC	П		Sheet No. 3 of 15
h (#)	ation	SS	tum nge n (ft)		
Depth (ft)	Elevation	USCS Symbol	Stratum Change Depth (ft)	VISUAL-MANUAL IDENTIFICATION AND DESCRIPTION	
+	1315				
_ -165-	_	SM	165	CH TV CAND with CDAVEL (1/5 170 f. a) Driverily for a problem and with 200	
- - - -170-	- -1310- -		170	SILTY SAND with GRAVEL (165-170 feet) Primarily fine to medium sand with $\sim 20\%$ fines and $\sim 10\%$ gravel up to 5mm. Sand is subrounded to angular and gravel is subrounded. Fines have low plasticity, no toughness, medium dry strength, (7.5YR 5/4), and strong reaction to HCL. UBFU	
-	- -1305 - -	СН	0	CLAY with SAND and GRAVEL (170-180 feet) Primarily fines with $\sim 30\%$ sands and $\sim 15\%$ gravel up to 10mm. Sand is subrounded to angular and gravel is subangular to subrounded. Fines have medium plasticity, low toughness, medium dry strength, (7.5YR 5/4), and moderate reaction to HCL. UBFU	
-175- - - -	_ -1300-			5/1), and indicate reaction to 1752. CD2 C	
-180- - - - - - - -185-	- -1295- - -	SW	180	WELL GRADED SAND with SILT and GRAVEL (180-200 feet) Primarily coarse to fine sand with $\sim 10\%$ fines and $\sim 10\%$ gravel up to 10mm. Sand is subrounded to angular and gravel is subangular to subrounded. Fines have low plasticity, low toughness, no dry strength, (7.5YR 5/4), and weak reaction to HCL. UBFU	
-	1290				
-190- - -	- -1285				
- -195-	-				
-	-1280 - -		200		
-200- - -	- - -1275- -	МН	200	<u>CLAYEY SILT with SAND</u> (200-205 feet) Primarily fines with $\sim 35\%$ fines. Sand is subangular to subrounded. Fines have medium plasticity, low toughness, medium dry strength, (7.5YR 5/4), and strong reaction to HCL. UBFU	
-205 - -	- -1270- -	SM	205	SILTY SAND with CLAY (205-210 feet) Primarily fine to medium sand with ~30% fines and trace gravel up to 6mm. Sand is subrounded to subangular and gravel is subrounded. Fines are nonplastic, no toughness, low dry strength, (7.5YR 5/4), and weak	
-210- - - - -	_ - -1265 -	SW	210	reaction to HCL. UBFU WELL GRADED SAND (210-225 feet) Primarily medium to fine sand with ~5% fines and ~5% gravel up to 4mm. Sand is subrounded to angular and gravel is subangular to subrounded. Fines are nonplastic, no toughness, no dry strength, (7.5YR 3/4), and no	
-215-	- -1260-			reaction to HCL. UBFU	
-	-				
-220- - -	- -1255-				
- - -225-	-		225		
-	- -1250- - -	SC	220	CLAYEY SAND (225-250 feet) Primarily fine to medium sand with ~45% fines and trace gravel up to 4mm. Sand is subrounded to angular. Fines have medium plasticity, low toughness, no dry strength, (7.5YR 5/4), and weak reaction to HCL. UBFU	
-230- - -	- -1245				
235	- - -1240-				
- -240-	-				
-	- -1235 -				
-245 - -	- - -1230-				
+					1

H&ALITHOLOG-PHOENX-NO WELL HA-LIB09-PHX.GLB LITHOLOGIC REPORT DATATEMPLATE+GDT WHALEYALDRICH.COM/SHAREBOS_COMMON/129687/GINT/129687-LITH_KF.GPJ 31 Aug 18

H	HALEY			LITHOLOGIC LOG	O-04 File No. 129687 Sheet No. 4 of 15
Depth (ft)	Elevation	USCS Symbol	Stratum Change Depth (ft)	VISUAL-MANUAL IDENTIFICATION AND DESCRIPTION	
-255- -260- -265- -270- -275- -280-	- 1225- - 1220- 1220- 1215- 1210- 1200- 1200-	СН	250	POORLY GRADED SAND (250-280 feet) Primarily fine to coarse sand with ~5% fines and ~10% gravel up to 21mm. Sand is subrounded to angular and gravel is subangular to subrounded. Fines are nonplastic, no toughness, no dry strength, (7.5YR 3/4), and no reaction to HCL. UBFU FAT CLAY (280-302 feet) Primarily fines with ~5% sands up to 2mm. Sand is	ACD Sensor Depths: 272, 275 feet
-285- -290- -295- -300-	- -1180- - - -		302	subangular. Fines have high plasticity, high toughness, high dry strength, (7.5YR 5/6), and no reaction to HCL. MGFU	
-305- -305- -310- -315-	-1175 - - - -1170 - - -1165 - - - - -1160	SP	310	CLAYEY SAND (302-310 feet) Primarily fine to medium sand with ~35% fines up to 4mm. Sand is subrounded to angular. Fines have medium plasticity, medium toughness, high dry strength, (7.5YR 5/4), and no reaction to HCL. LBFU POORLY GRADED SAND with GRAVEL (310-375 feet) Primarily fine to coarse sand with ~5% fines and ~20% gravel up to 20mm. Sand is subrounded to angular and gravel is subangular to subrounded. Fines are nonplastic, no toughness, no dry strength, (7.5YR 4/4), and no reaction to HCL. LBFU	
-325- -325- - - - -330-	- -1155- - - -1150- - - - - - - - - - - - - - - - - - -				
+-	ΓΕ: Lith	nologic Idrich C	descrption DP2001A -	ns, group symbols, and grain-size determinations based on the USCS visual-manual method (Haley Field Practice for Soil Identification and Description).	O-04

HALEY ALDRICH				LITHOLOGIC LOG	O-04 File No. 129687 Sheet No. 5 of 15
			_		Sheet No. 5 of 15
Depth (ft)	Elevation	USCS Symbol	Stratum Change Depth (ft)		
Dep	Elev	Syr	Stra Cha Dep	VISUAL-MANUAL IDENTIFICATION AND DESCRIPTION	
+	-				
-	-1140- -				
340					
-	1135				
- -345	-				
-	1130				
_ -350-					
-	_ -1125-				CS Sensor Depths: 350, 370, 390, 410 feet
-	-				
355	- -1120-				
-	_				
-360 -	⊢				
-	-1115 -				
-365	[
-	1110				
- -370-	-				
-	1105				
_ -375-					
-	- -1100-				
-	-				
- 380-	- -1095-				
	Ė				
-385 -	⊢				
-	-1090- -				
390			390	QUARTZ MONZONITE (390-405 feet) Consists of quartz at approximately 35%,	
-	1085			potassium feldspars at approximately 35%, plagioclase at approximately 25%, and biotite at approximately 5%. Cu minerals present.	
- -395-	<u> </u>				
-	1080				
-400-	-				
-	- -1075-				
<u> </u>	ļ.		405		
-405 -	- -1070-		TU3 .	GRANODIORITE (405-480 feet) Contains mostly plagioclase in a gray aphanitic matrix with biotite crystals composing approximately 10%. Clay present 410-415 feet.	
_				To a confidence of the confide	
- 410-	-				
	1065				
-415	-				
-	1060				
- -420-	Ė				
<u> </u>	1055		422		
NOT	ΓE: Lith	nologic o	descrption	is, group symbols, and grain-size determinations based on the USCS visual-manual method (Haley	0-04

H&ALITHOLOG-PHOENX-NO WELL HA-LIB09-PHX.GLB LITHOLOGIC REPORT DATATEMPLATE+.GDT \(\text{NHALEYALDRICH.COM/SHAREBOS_COMMON/129887/GINT/129887-LITH_KF.GPJ 31 Aug 18\)

HALEY				LITHOLOGIC LOG	O-04 le No. 129687 heet No. 6 of 15
_					Sheet No. 6 of 15
Depth (ft)	Elevation	USCS Symbol	Stratum Change Depth (ft)		
Dept	Eleva	Syn	Stra Cha Dept	VISUAL-MANUAL IDENTIFICATION AND DESCRIPTION	
				GRANODIORITE (405-480 feet) Continued	
425				GREET (402 400 rect) Continued	
- }	- -1050-				
- -430					
-	_ -1045-				
-	-				
435	_ -1040-				
-	-				
440	- -1035-				
-	-1035 - -				
445	-				
-	1030- - -				
450	-				
-	-1025- -				
455					
	-1020- -				
460	-				
-	1015				
- 465	-				
-	1010				
470-	_				
-	- -1005-				
- -475-					
- }	_ -1000-				
-	-		480		
480	_ -995-		-100	QUARTZ MONZONITE (480-495 feet) Consists of quartz at approximately 35%, potassium feldspars at approximately 35%, plagioclase at approximately 25%, and biotite at	
	_			approximately 5%. Cu minerals present.	
485	- -990-				Filter Pack: 8 - 12 CO Silica Sand; 485 - 1225 feet
	-				Thread Adapter: Stainless Steel, SCH 80 F480 PVC to API; 498
490	- 1				feet
	-985- - -				
495	- 1		495	GRANODIORITE (495-755 feet) Contains mostly plagioclase in a gray aphanitic matrix	
	-980- -			with biotite crystals composing approximately 10% . Clay present 500-510 feet and 615-625 feet.	
500	<u> </u>				Well Screen: Nominal 5-inch
	-975- -				diameter, SCH 80 PVC Screen (0.020-inch slots); 498 - 1200 feet
505					ERT Sensor Depths: 516, 591, 666, 742, 817, 892, 967, 1041,
-	970-				1117, 1193 feet
	L				

31 Aug 18

H&A-LITHOLOG-PHOENIX-NO WELL HA-LIB09-PHX.GLB LITHOLOGIC REPORT DATATEMPLATE+.GDT WHALEYALDRICH.COM/SHAREBOS_COMMON/129887/GINT/129887-LITH_KF.GPJ

HALEY ALDRICH			Н	LITHOLOGIC LOG	O-04 File No. 129687 Sheet No. 7 of 15	
Depth (ft)	Elevation	USCS Symbol	Stratum Change Depth (ft)	VISUAL-MANUAL IDENTIFICATION AND DESCRIPTION		
510	_		509	GRANODIORITE (495-755 feet) Continued		
- ŀ	_ -965-					
-	-					
-515 -	-					
- [-960- -					
520	_					
-	-955- -					
- 525	-					
_ [- -950-					
_ -530	-					
	- -945-					
- - -535						
- H	_ -940-					
_	- -					
540	- -					
-	-935- -					
545						
-	-930- -					
- -550-	-					
-	- -925-					
- -555	_					
- H	- -920-					
- 	-					
560	- - -915-					
_	- - -					
-565 -	-					
-	-910- -					
570						
_	-905-					
- -575	-					
- H	- -900-					
- ŀ	_ -895-					
_	-					
-585 -	- - -890-					
-	_ _ _					
-590 -	<u>-</u>					
-	-885- -					
595						
NOT	NOTE: Lithologic descrptions, group symbols, and grain-size determinations based on the USCS visual-manual method (Haley & Aldrich OP2001A - Field Practice for Soil Identification and Description).					

H	HALEY			LITHOLOGIC LOG	O-04 File No. 129687 Sheet No. 8 of 15	
Depth (ft)	Elevation	USCS Symbol	Stratum Change Depth (ft)	VISUAL-MANUAL IDENTIFICATION AND DESCRIPTION		
-	000		596	GRANODIORITE (495-755 feet) Continued		
F	-880-			GRANGSTORITE (DE 166) Commune		
600						
-	-875-					
605	-					
	870-					
- -610-	-					
-	- -865-					
615						
Ė	- -860-					
620	-					
	_ -855-					
25 -	-					
625	- -850-					
129087	-030-					
630	F					
1	-845- -					
-635- -635- -635- -635- -635- -640- -645-	-					
5 -	-840-	-				
640	[
	-835-					
	-					
WALETALL	-830-					
Hoou-	-					
	-825-					
655	-					
	- -820-					
-655- -660- -665-						
	- -815-					
-	-					
1	- -810-					
- K	F					
	1					
	-805-					
675	-					
	-800					
680-	£					
	-795-		682			
-675- -675- 	NOTE: Lithologic descrptions, group symbols, and grain-size determinations based on the USCS visual-manual method (Haley & Aldrich OP2001A - Field Practice for Soil Identification and Description).					

Depth (ft)		RIC			File No. 129687
Depth (ft)	n				Sheet No. 9 of 15
Dept	ı≅	SS	um nge		
	Elevation	USCS Symbol	Stratum Change Depth (ft)	VISUAL-MANUAL IDENTIFICATION AND DESCRIPTION	
\dashv	Ш				
685	-			GRANODIORITE (495-755 feet) Continued	
. +	- -790-				
	- -				
690	-				
.	-785- -				
695	-				
.	-780- -				
700	-				
. +	- -775-				
	-				
705	- - -770-				
	-770- - -				
710	-				
	-765- -				
715	-				
. +	- -760-				
700	-				
720	- - -755-				
.	- - -				
725	-				
.	-750- -				
730	-				
.	- -745-				
735	-				
. +	- -740 <i>-</i>				
	-				
740	-				
.	-735- -				
745	-				
. [-730- -				
750	- -				
. +	- -725-				
<u></u>	-		755		
755	- - -720-		133	QUARTZ MONZONITE (755-990 feet) Consists of quartz at approximately 35%, potassium feldspars at approximately 35%, plagioclase at approximately 25%, and biotite at	
. [120- - -			approximately 5%.	
760	-				
,	-715- -				
765	_				
	- -710-				
•	-				

H&A-LITHOLOG-PHOENIX-NO WELL HA-LIB09-PHX.GLB LITHOLOGIC REPORT DATATEMPLATE+.GDT WHALEYALDRICH.COM/SHAREBOS_COMMON/129887/GINT/129887-LITH_KF.GPJ 31 Aug 18

H	ALE	Y	:H	LITHOLOGIC LOG	O-04 File No. 129687 Sheet No. 10 of 15
					Sheet No. 10 01 15
Depth (ft)	Elevation	USCS Symbol	Stratum Change Depth (ft)		
		⊃⊗	ស្ន	VISUAL-MANUAL IDENTIFICATION AND DESCRIPTION	
-770 ⁻	- - -705-		770	QUARTZ MONZONITE (755-990 feet) Continued	
	-				
-775 -	- -700-				
-	_				
-780- - -	- -695-				
705	-				
-785- - -	_ -690-				
- -790-	_				
-	_ -685-				
- - -795-					
-	_ -680-				
-800					
-	- -675-				
- 805	-				
	- 670-				
- -810-	_				
	-665-				
815					
-	-660-				
820	F				
	-655- -				
825	F				
-	-650- - -				
830	H				
	-645- - -				
-835 -	- - -640-				
E	-				
-840- - -	- - -635-				
-	-				
-845 - -	- -630-				
-	_				
-850 - -	- 625-				
- - -855-	_				
-	<u> </u>		856	s group symbols, and grain-size determinations based on the USCS visual-manual method (Haley	0.04

H&ALITHOLOG-PHOENX-NO WELL HA-LIB09-PHX.GLB LITHOLOGIC REPORT DATATEMPLATE+.GDT \(\text{NHALEYALDRICH.COM/SHAREBOS_COMMON/129887/GINT/129887-LITH_KF.GPJ 31 Aug 18\)

HALEY ALDRICH				LITHOLOGIC LOG	O-04 File No. 129687 Sheet No. 11 of 15
+	Ι				Sheet No. 11 of 15
Depth (ft)	Elevation	USCS Symbol	Stratum Change Depth (ft)		
Dep	Ele	S) (S	Sp. Cp. Cp. Cp. Cp. Cp. Cp. Cp. Cp. Cp. C	VISUAL-MANUAL IDENTIFICATION AND DESCRIPTION	
-	-620-			QUARTZ MONZONITE (755-990 feet) Continued	
- -860-	-				
-	- -615-				
865					
-	- -610-				
870	-				
-	- -605-				
875	-				
E	- 600-				
880	Ė				
-	- -595-				
885	-				
Ė	- 590-				
_ -890-	-				
E	-585-				
- -895-	-				
	580-				
900-	-				
	575-				
905	-				
	570-				
910	-				
E	-565-				
915	_				
-	-560-				
920	_				
-	-555-				
925	_				
-	-550-				
930	-				
-	-545- -				
935	F				
Ė	-540- -				
940	F				
<u> </u>	-535-		943		
l NO	TT. 1 :46	مامجام ا	daaaratiaa	is group symbols, and grain-size determinations based on the USCS visual-manual method (Haley	0.04

H&ALITHOLOG-PHOENX-NO WELL HA-LIB09-PHX.GLB LITHOLOGIC REPORT DATATEMPLATE+.GDT \(\text{NHALEYALDRICH.COM/SHAREBOS_COMMON/129887/GINT/129887-LITH_KF.GPJ 31 Aug 18\)

H	ALE	Y	Н	LITHOLOGIC LOG	O-04 File No. 129687 Sheet No. 12 of 15
Depth (ft)	Elevation	USCS Symbol	Stratum Change Depth (ft)	VISUAL-MANUAL IDENTIFICATION AND DESCRIPTION	
945				QUARTZ MONZONITE (755-990 feet) Continued	
-	-530- - -				
-950- - - -	- - -525- -				
- -955-	- - - -520-				
960	-520- - -				
- -	- -515- -				
965	_ - -510-				
- -970-	- - -				
-	-505- - -				
-975 - - -	- - -500-				
- -980-	- - - -495-				
- -985	-495- - -				
-	- -490- -				
-990- - -	- - -485-		990	GRANODIORITE (990-1005 feet) Contains mostly plagioclase in a gray aphanitic matrix with biotite crystals composing approximately 10%.	
- -995	- - -				
1000	-480- - - -				
-	- -475- -				
1005	- - -470-		1005	QUARTZ MONZONITE (1005-1225 feet) Consists of quartz at approximately 35%, potassium feldspars at approximately 35%, plagioclase at approximately 25%, and biotite at	
1010	-			approximately 5%.	
	- -465- - -				
1015 - -	- - -460-				
- 1020	-				
1025	-455- - - -				
	- -450- -				
NOT	E: Lith	nologic	descrption	is, group symbols, and grain-size determinations based on the USCS visual-manual method (Haley	O-04

H&A-LITHOLOG-PHOENIX-NO WELL HA-LIB09-PHX.GLB LITHOLOGIC REPORT DATATEMPLATE+.GDT WHALEYALDRICH.COM/SHAREBOS_COMMON/129887/GINT/129887-LITH_KF.GPJ 31 Aug 18

Н	ALE	Y	Н	LITHOLOGIC LOG	O-04 File No. 129687 Sheet No. 13 of 15
Depth (ft)	Elevation	USCS	Stratum Change Depth (ft)	VISUAL-MANUAL IDENTIFICATION AND DESCRIPTION	
1030			1030	QUARTZ MONZONITE (1005-1225 feet) Continued	
E	-445-			(1906-1220-1001) communica	
_ 1035	- -				
-	- -440-	-			
1040					
1040	_ -435-				
-	-				
1045	-430-				
E	-430				
1050	F				
1055	-425- -				
T 033	-				
1069 - 1065 - 1079 - 1075	-420-	-			
1060					
-	-415-				
1065	- -				
E	410-				
_ 1070	- -				
-	- -405-				
1075					
1073	′_ -400-				
	-				
1080	-395-				
108 0 - - -	-				
1085	H				
E	-390-				
1090	F				
-	-385-				
1085 - - 1090 - - 1095 - - 1100	-				
-	-380-				
	+				
- - - 1105	-375-				
- 1105	- -				
E	370-				
1110	<u> </u>				
ļ .	 -365	-			
- - 1115					
-	}				
1110 - - - - 1115 - NO	TE: Litl & A	nologic Ildrich (descrption DP2001A -	ns, group symbols, and grain-size determinations based on the USCS visual-manual method (Haley Field Practice for Soil Identification and Description).	O-04

H	XLE	Y	H	LITHOLOGIC LOG	O-04 File No. 129687 Sheet No. 14 of 15
+					SHEELING. 14 OF 15
Depth (ft)	Elevation	USCS Symbol	Stratum Change Depth (ft)		
De	Ele	⊃⊗	Scr	VISUAL-MANUAL IDENTIFICATION AND DESCRIPTION	
-	-360 -		1117	QUARTZ MONZONITE (1005-1225 feet) Continued	
1120					
F	-355- -				
1125	F				
	-350- - -				
1130	⊢				
Ė	-345- -				
1135	- - -340-				
1140	Ė				
1140	- -335-				
-	-				
1145	- -330-				
1450					
1150	_ -325-				
115 5	Ĺ				
- 133	_ -320-				
1160					
-	- -315-				
1165	-				
-	- -310-				
- 1170	-				
	305-				
1175	-				
F	300-				
1180	_				
-	-295-				
1185	<u>-</u>				
-	-290-				
1190	F				
E	-285- -				
1195	-				
Ė	-280- -				
1200	-				
<u> </u>	-275- -				
NO	FF. 1 :44	ماممام	daaaratiaa	is group symbols, and grain-size determinations based on the USCS visual-manual method (Haley	0.04

H&ALITHOLOG-PHOENX-NO WELL HA-LIB09-PHX.GLB LITHOLOGIC REPORT DATATEMPLATE+.GDT \(\text{NHALEYALDRICH.COM/SHAREBOS_COMMON/129887/GINT/129887-LITH_KF.GPJ 31 Aug 18\)

H	ALE	Y	Н	LITHOLOGIC LOG	O-04 File No. 129687 Sheet No. 15 of 15
Depth (ft)	Elevation	USCS Symbol	Stratum Change Depth (ft)	VISUAL-MANUAL IDENTIFICATION AND DESCRIPTION	
- 1205	 		1204	QUARTZ MONZONITE (1005-1225 feet) Continued	
1205 - - - 1210 - - 1215 - - - 1220 - 1225	-270- -265- -260- -255-		1225	QUARTZ MONZONITE (1005-1225 feet) Continued	Total Borehole Depth: Driller = 1225 feet; Geophysical Logging = 1220 feet
NO1	TE: Lith	nologic (descrption	ns, group symbols, and grain-size determinations based on the USCS visual-manual method (Haley Field Practice for Soil Identification and Description).	O-04

APPENDIX C

Chemical Characteristics of Formation Water



May 23, 2018

Barbara Sylvester Brown & Caldwell 201 E. Washington Suite 500 Phoenix, AZ 85004

TEL (602) 567-3894 FAX -

Work Order No.: 18D0619
RE: PTF
Order Name: Florence Copper

Dear Barbara Sylvester,

Turner Laboratories, Inc. received 2 sample(s) on 04/25/2018 for the analyses presented in the following report.

All results are intended to be considered in their entirety, and Turner Laboratories, Inc. is not responsible for use of less than the complete report. Results apply only to the samples analyzed. Samples will be disposed of 30 days after issue of our report unless special arrangements are made.

The pages that follow may contain sensitive, privileged or confidential information intended solely for the addressee named above. If you receive this message and are not the agent or employee of the addressee, this communication has been sent in error. Please do not disseminate or copy any of the attached and notify the sender immediately by telephone. Please also return the attached sheet(s) to the sender by mail.

Please call if you have any questions.

Respectfully submitted,

Turner Laboratories, Inc. ADHS License AZ0066

Kevin Brim Project Manager

Client: Brown & Caldwell

Project: PTF Work Order: 18D0619

Date Received: 04/25/2018

Order: Florence Copper

Work Order Sample Summary

Date: 05/23/2018

Lab Sample IDClient Sample IDMatrixCollection Date/Time18D0619-01R-09Ground Water04/23/2018 1555

18D0619-02 TB Ground Water 04/25/2018 0000

Client: Brown & Caldwell

 Project:
 PTF

 Work Order:
 18D0619

 Date Received:
 04/25/2018

Case Narrative

Date: 05/23/2018

The 8015D analysis was performed by TestAmerica Laboratories, Inc. in Phoenix, AZ.

The radiochemistry analysis was performed by Radiation Safety Engineering, Inc. in Chandler, AZ.

D5 Minimum Reporting Limit (MRL) is adjusted due to sample dilution; analyte was non-detect in the

sample.

H5 This test is specified to be performed in the field within 15 minutes of sampling; sample was

received and analyzed past the regulatory holding time.

M3 The spike recovery value is unusable since the analyte concentration in the sample is

disproportionate to the spike level. The associated LCS/LCSD recovery was acceptable.

All soil, sludge, and solid matrix determinations are reported on a wet weight basis unless otherwise noted.

ND Not Detected at or above the PQL

PQL Practical Quantitation Limit

DF Dilution Factor

PRL Project Reporting Limit

Client: Brown & Caldwell Client Sample ID: R-09

Project:PTFCollection Date/Time: 04/23/2018 1555Work Order:18D0619Matrix: Ground WaterLab Sample ID:18D0619-01Order Name: Florence Copper

Analyses	Result	PRL	PQL	Qual	Units	DF	Prep Date	Analysis Date	Analyst
ICP Dissolved Metals-E 200.7 (4.4)									
Calcium	140		4.0	M3	mg/L	1	04/27/2018 144	0 05/04/2018 115	0 MH
Iron	ND		0.30		mg/L	1	04/27/2018 144	0 05/04/2018 115	0 MH
Magnesium	27		3.0		mg/L	1	04/27/2018 144	0 05/04/2018 115	0 MH
Potassium	6.8		5.0		mg/L	1	04/27/2018 144	0 05/04/2018 115	0 MH
Sodium	170		5.0	M3	mg/L	1	04/27/2018 144	0 05/04/2018 115	0 MH
ICP/MS Dissolved Metals-E 200.8 (5.4)									
Aluminum	ND		0.0800	D5	mg/L	2	04/27/2018 144	0 05/07/2018 113	9 MH
Antimony	ND		0.00050		mg/L	1	04/27/2018 144	0 05/07/2018 113	3 MH
Arsenic	0.0016		0.00050		mg/L	1	04/27/2018 144	0 05/07/2018 113	3 MH
Barium	0.071		0.00050		mg/L	1	04/27/2018 144	0 05/07/2018 113	3 MH
Beryllium	ND		0.00050	D5	mg/L	2	04/27/2018 144	0 05/07/2018 113	9 MH
Cadmium	ND		0.00025		mg/L	1	04/27/2018 144	0 05/07/2018 113	3 MH
Chromium	0.0051		0.00050		mg/L	1	04/27/2018 144	0 05/07/2018 113	3 MH
Cobalt	ND		0.00025		mg/L	1	04/27/2018 144	0 05/07/2018 113	3 MH
Copper	0.011		0.00050		mg/L	1	04/27/2018 144	0 05/07/2018 113	3 MH
Lead	ND		0.00050		mg/L	1	04/27/2018 144	0 05/07/2018 113	3 MH
Manganese	0.0020		0.00025		mg/L	1	04/27/2018 144	0 05/07/2018 113	3 MH
Nickel	0.0033		0.00050		mg/L	1	04/27/2018 144	0 05/07/2018 113	3 MH
Selenium	ND		0.0025		mg/L	1	04/27/2018 144	0 05/07/2018 113	3 MH
Thallium	ND		0.00050		mg/L	1	04/27/2018 144	0 05/07/2018 113	3 MH
Zinc	ND		0.040		mg/L	1	04/27/2018 144	0 05/07/2018 113	3 MH
CVAA Dissolved Mercury-E 245.1									
Mercury	ND		0.0010		mg/L	L 1	04/26/2018 095	5 04/26/2018 163	9 MH
рН-Е150.1									
pH (pH Units)	7.8			Н5	-	- 1	04/26/2018 161	5 04/26/2018 161	6 AP
Temperature (°C)	22			Н5	-	- 1	04/26/2018 161	5 04/26/2018 161	6 AP
ICP/MS Total Metals-E200.8 (5.4)									
Uranium	0.016		0.00050		mg/L	L 1	04/27/2018 123	0 04/30/2018 134	8 MH

Client: Brown & Caldwell Client Sample ID: R-09

Project:PTFCollection Date/Time: 04/23/2018 1555Work Order:18D0619Matrix: Ground WaterLab Sample ID:18D0619-01Order Name: Florence Copper

Anions by Ion Chromatography-E300.0 (2.1) Chloride 316 Fluoride NI Nitrogen, Nitrate (As N) 8.8 Nitrogen, Nitrite (As N) NI Sulfate 196 Cyanide-E335.4 Cyanide NI	O 3 O 0		25 0.50 0.50 0.10 130	mg/L mg/L mg/L	1 1 1	04/25/2018 120 04/25/2018 120 04/25/2018 120	25 04/26/2018 141 08 04/25/2018 154 08 04/25/2018 154 08 04/25/2018 154 25 04/26/2018 141	4 AP 4 AP 4 AP
Fluoride NI Nitrogen, Nitrate (As N) 8.8 Nitrogen, Nitrite (As N) NI Sulfate 196 Cyanide-E335.4	O 3 O 0		0.50 0.50 0.10 130	mg/L mg/L mg/L	1 1 1	04/25/2018 120 04/25/2018 120 04/25/2018 120	08 04/25/2018 154 08 04/25/2018 154 08 04/25/2018 154	4 AP 4 AP 4 AP
Nitrogen, Nitrate (As N) 8.8 Nitrogen, Nitrite (As N) NI Sulfate 196 Cyanide-E335.4	8 D 0		0.50 0.10 130	mg/L mg/L	1 1	04/25/2018 120 04/25/2018 120	08 04/25/2018 154 08 04/25/2018 154	4 AP 4 AP
Nitrogen, Nitrite (As N) NE Sulfate 196 Cyanide-E335.4	O 0		0.10 130	mg/L	. 1	04/25/2018 120	08 04/25/2018 154	4 AP
Nitrogen, Nitrite (As N) NI Sulfate 19 Cyanide-E335.4	0		130	•				
Cyanide-E335.4				mg/L	25	04/26/2018 122	25 04/26/2018 141	5 AP
·	D)		0.10					
Cyanide NI	D		0.10					
			0.10	mg/L	. 1	04/26/2018 084	5 04/30/2018 154	5 AP
Alkalinity-SM2320B								
Alkalinity, Bicarbonate (As 150 CaCO3)	0		2.0	mg/L	. 1	05/03/2018 103	0 05/03/2018 121	0 EJ
Alkalinity, Carbonate (As CaCO3) NI	D		2.0	mg/L	. 1	05/03/2018 103	0 05/03/2018 121	0 EJ
Alkalinity, Hydroxide (As CaCO3) NI	D		2.0	mg/L	. 1	05/03/2018 103	0 05/03/2018 121	0 EJ
Alkalinity, Phenolphthalein (As NI CaCO3)	D		2.0	mg/L	. 1	05/03/2018 103	0 05/03/2018 121	0 EJ
Alkalinity, Total (As CaCO3) 150	0		2.0	mg/L	. 1	05/03/2018 103	0 05/03/2018 121	0 EJ
Specific Conductance-SM2510 B								
Conductivity 176	00		0.20	μmhos/cm	2	05/09/2018 131	5 05/09/2018 133	0 AP
Total Dissolved Solids (Residue, Filterable)-SM	M2540 C							
Total Dissolved Solids (Residue, 10) Filterable)	00		20	mg/L	. 1	04/26/2018 082	26 05/01/2018 160	0 EJ
Volatile Organic Compounds by GC/MS-SW8	8260B							
Benzene NI	D		0.50	ug/L	. 1	05/07/2018 182	24 05/07/2018 194	3 KP
Carbon disulfide NI			2.0	ug/L			4 05/07/2018 194	
Ethylbenzene NI			0.50	ug/L			4 05/07/2018 194	
Toluene NI	D		0.50	ug/L			4 05/07/2018 194	
Xylenes, Total NI	D		1.5	ug/L		05/07/2018 182	4 05/07/2018 194	3 KP
Surr: 4-Bromofluorobenzene 95		70-130		%REC	1	05/07/2018 182	24 05/07/2018 194	3 KP
Surr: Dibromofluoromethane 10.	1	70-130		%REC	1	05/07/2018 182	24 05/07/2018 194	3 KP
Surr: Toluene-d8 77	,	70-130		%REC	1	05/07/2018 182	24 05/07/2018 194	3 KP

Client: Brown & Caldwell Client Sample ID: TB

Project:PTFCollection Date/Time: 04/25/2018 0000Work Order:18D0619Matrix: Ground WaterLab Sample ID:18D0619-02Order Name: Florence Copper

Analyses	Result	PRL	PQL	Qual	Units]	DF	Prep Date	Analysis Date	Analyst
Volatile Organic Compounds by GC	/MS-SW8260B								
Benzene	ND		0.50		ug/L	1	05/07/2018 182	4 05/07/2018 234	4 KP
Carbon disulfide	ND		2.0		ug/L	1	05/07/2018 182	4 05/07/2018 234	4 KP
Ethylbenzene	ND		0.50		ug/L	1	05/07/2018 182	4 05/07/2018 234	4 KP
Toluene	ND		0.50		ug/L	1	05/07/2018 182	4 05/07/2018 234	4 KP
Xylenes, Total	ND		1.5		ug/L	1	05/07/2018 182	4 05/07/2018 234	4 KP
Surr: 4-Bromofluorobenzene	101	70-130			%REC	1	05/07/2018 182	4 05/07/2018 234	4 KP
Surr: Dibromofluoromethane	110	70-130			%REC	1	05/07/2018 182	4 05/07/2018 234	4 KP
Surr: Toluene-d8	103	70-130			%REC	1	05/07/2018 182	4 05/07/2018 234	4 KP

Client: Brown & Caldwell

 Project:
 PTF

 Work Order:
 18D0619

 Date Received:
 04/25/2018

QC Summary

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC	RPD	RPD Limit	Qual
Batch 1804269 - E 245.1										
Blank (1804269-BLK1)				Prepared &	Analyzed: (04/26/2018				
Mercury	ND	0.0010	mg/L	•						
LCS (1804269-BS1)				Prepared &	Analyzed: (04/26/2018				
Mercury	0.0049	0.0010	mg/L	0.005000	-	98	85-115			
LCS Dup (1804269-BSD1)				Prepared &	Analyzed: (04/26/2018				
Mercury	0.0048	0.0010	mg/L	0.005000	-	95	85-115	2	20	
Matrix Spike (1804269-MS1)	So	urce: 18D0394-	-01	Prepared &	Analyzed: (04/26/2018				
Mercury	0.0050	0.0010	mg/L	0.005000	0.00020	97	85-115			
Matrix Spike Dup (1804269-MSD1)	So	urce: 18D0394-	-01	Prepared &	Analyzed: (04/26/2018				
Mercury	0.0050	0.0010	mg/L	0.005000	0.00020	96	85-115	1	20	
Batch 1804292 - E200.8 (5.4)										
Blank (1804292-BLK1)				Prepared &	Analyzed: (04/30/2018				
Uranium	ND	0.00050	mg/L	1						
LCS (1804292-BS1)				Prepared &	Analyzed: (04/30/2018				
Uranium	0.046	0.00050	mg/L	0.05000		92	85-115			
LCS Dup (1804292-BSD1)				Prepared &	Analyzed: (04/30/2018				
Uranium	0.046	0.00050	mg/L	0.05000		92	85-115	0.2	20	
Matrix Spike (1804292-MS1)	So	urce: 18D0614-	-01	Prepared &	Analyzed: (04/30/2018				
Uranium	0.051	0.00050	mg/L	0.05000	0.0015	99	70-130			
Batch 1805051 - E 200.7 (4.4)										
Blank (1805051-BLK1)				Prepared &	Analyzed: (05/04/2018				
Calcium	ND	4.0	mg/L							
Iron	ND	0.30	mg/L							
Magnesium	ND	3.0	mg/L							
Potassium	ND	5.0	mg/L							
Sodium	ND	5.0	mg/L							
LCS (1805051-BS1)				Prepared &	Analyzed: (05/04/2018				
Calcium	11	4.0	mg/L	10.00		109	85-115			
Iron	1.0	0.30	mg/L	1.000		104	85-115			
Magnesium	10	3.0	mg/L	10.00		105	85-115			
Potassium	10	5.0	mg/L	10.00		105	85-115			
Sodium	10	5.0	mg/L	10.00		105	85-115			
LCS Dup (1805051-BSD1)				Prepared &	Analyzed: (05/04/2018				
Calcium	11	4.0	mg/L	10.00		110	85-115	1	20	
Iron	1.0	0.30	mg/L	1.000		105	85-115	0.5	20	
Magnesium	10	3.0	mg/L	10.00		105	85-115	0.06	20	
Potassium	10	5.0	mg/L	10.00		105	85-115	0.05	20	
Sodium	11	5.0	mg/L	10.00		109	85-115	4	20	

Client: Brown & Caldwell

 Project:
 PTF

 Work Order:
 18D0619

 Date Received:
 04/25/2018

QC Summary

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Qual
Batch 1805051 - E 200.7 (4.4)										
Matrix Spike (1805051-MS1)	So	urce: 18D0619	-01	Prepared &	Analyzed: (05/04/2018				
Calcium	150	4.0	mg/L	10.00	140	59	70-130			M3
Iron	1.1	0.30	mg/L	1.000	0.028	105	70-130			
Magnesium	38	3.0	mg/L	10.00	27	108	70-130			
Potassium	17	5.0	mg/L	10.00	6.8	105	70-130			
Sodium	170	5.0	mg/L	10.00	170	30	70-130			M3
Matrix Spike (1805051-MS2)	So	urce: 18E0021-	-01	Prepared &	Analyzed: (05/04/2018				
Calcium	64	4.0	mg/L	10.00	54	103	70-130			
Iron	1.0	0.30	mg/L	1.000	0.0060	101	70-130			
Magnesium	21	3.0	mg/L	10.00	11	99	70-130			
Potassium	15	5.0	mg/L	10.00	4.7	104	70-130			
Sodium	99	5.0	mg/L	10.00	90	87	70-130			
Batch 1805069 - E 200.8 (5.4)										
Blank (1805069-BLK1)				Prepared &	Analyzed: (05/07/2018				
Aluminum	ND	0.0400	mg/L	-	-					
Antimony	ND	0.00050	mg/L							
Arsenic	ND	0.00050	mg/L							
Barium	ND	0.00050	mg/L							
Beryllium	ND	0.00025	mg/L							
Cadmium	ND	0.00025	mg/L							
Chromium	ND	0.00050	mg/L							
Cobalt	ND	0.00025	mg/L							
Copper	ND	0.00050	mg/L							
Lead	ND	0.00050	mg/L							
Manganese	ND	0.00025	mg/L							
Nickel	ND	0.00050	mg/L							
Selenium	ND	0.0025	mg/L							
Thallium	ND	0.00050	mg/L							
Zinc	ND	0.040	mg/L							
LCS (1805069-BS1)				Prepared &	Analyzed: (05/07/2018				
Aluminum	0.104	0.0400	mg/L	0.1000		104	85-115			
Antimony	0.048	0.00050	mg/L	0.05000		96	85-115			
Arsenic	0.050	0.00050	mg/L	0.05000		100	85-115			
Barium	0.050	0.00050	mg/L	0.05000		100	85-115			
Beryllium	0.049	0.00025	mg/L	0.05000		97	85-115			
Cadmium	0.050	0.00025	mg/L	0.05000		100	85-115			
Chromium	0.051	0.00050	mg/L	0.05000		102	85-115			
Cobalt	0.051	0.00025	mg/L	0.05000		101	85-115			
Copper	0.051	0.00050	mg/L	0.05000		103	85-115			
Lead	0.049	0.00050	mg/L	0.05000		98	85-115			
Manganese	0.050	0.00025	mg/L	0.05000		101	85-115			
Nickel	0.051	0.00050	mg/L	0.05000		102	85-115			
Selenium	0.051	0.0025	mg/L	0.05000		103	85-115			
Thallium	0.050	0.00050	mg/L	0.05000		101	85-115			
Zinc	0.10	0.040	mg/L	0.1000		101	85-115			
•	0.10	0.0.0								

Client: Brown & Caldwell

 Project:
 PTF

 Work Order:
 18D0619

 Date Received:
 04/25/2018

QC Summary

		Reporting		Spike	Source		%REC		RPD	
Analyte	Result	Limit	Units	Level	Result	%REC	Limits	RPD	Limit	Qual
Batch 1805069 - E 200.8 (5.4)										
LCS Dup (1805069-BSD1)				Prepared &	Analyzed: 0	5/07/2018				
Aluminum	0.115	0.0400	mg/L	0.1000		115	85-115	10	20	
Antimony	0.048	0.00050	mg/L	0.05000		96	85-115	0.7	20	
Arsenic	0.050	0.00050	mg/L	0.05000		101	85-115	0.8	20	
Barium	0.051	0.00050	mg/L	0.05000		102	85-115	1	20	
Beryllium	0.049	0.00025	mg/L	0.05000		97	85-115	0.2	20	
Cadmium	0.050	0.00025	mg/L	0.05000		100	85-115	0.2	20	
Chromium	0.051	0.00050	mg/L	0.05000		102	85-115	0.4	20	
Cobalt	0.050	0.00025	mg/L	0.05000		101	85-115	0.5	20	
Copper	0.052	0.00050	mg/L	0.05000		105	85-115	2	20	
Lead	0.049	0.00050	mg/L	0.05000		98	85-115	0.1	20	
Manganese	0.050	0.00025	mg/L	0.05000		101	85-115	0.09	20	
Nickel	0.051	0.00050	mg/L	0.05000		103	85-115	0.8	20	
Selenium	0.052	0.0025	mg/L	0.05000		104	85-115	2	20	
Γhallium	0.050	0.00050	mg/L	0.05000		101	85-115	0.06	20	
Zinc	0.10	0.040	mg/L	0.1000		104	85-115	3	20	
Matrix Spike (1805069-MS1)	Sou	ırce: 18D0693-	-01	Prepared &	Analyzed: 0	5/07/2018				
Aluminum	0.239	0.0400	mg/L	0.1000	0.166	74	70-130			
Antimony	0.045	0.00050	mg/L	0.05000	0.00024	90	70-130			
Arsenic	0.056	0.00050	mg/L	0.05000	0.0035	104	70-130			
Barium	0.16	0.00050	mg/L	0.05000	0.12	94	70-130			
Beryllium	0.045	0.00025	mg/L	0.05000	0.000029	90	70-130			
Cadmium	0.047	0.00025	mg/L	0.05000	ND	94	70-130			
Chromium	0.049	0.00050	mg/L	0.05000	0.00052	98	70-130			
Cobalt	0.048	0.00025	mg/L	0.05000	0.00097	95	70-130			
Copper	0.051	0.00050	mg/L	0.05000	0.0020	98	70-130			
Lead	0.047	0.00050	mg/L	0.05000	0.00016	94	70-130			
Manganese	0.054	0.00025	mg/L	0.05000	0.0075	94	70-130			
Nickel	0.049	0.00050	mg/L	0.05000	0.0018	94	70-130			
Selenium	0.057	0.0025	mg/L	0.05000	ND	114	70-130			
Γhallium	0.048	0.00050	mg/L	0.05000	0.000038	96	70-130			
Zinc	0.11	0.040	mg/L	0.1000	ND	109	70-130			

Client: Brown & Caldwell

 Project:
 PTF

 Work Order:
 18D0619

 Date Received:
 04/25/2018

QC Summary

		Reporting		Spike	Source		%REC		RPD	
Analyte Charles of Cha	Result	Limit	Units	Level	Result	%REC	Limits	RPD	Limit	Qual
Batch 1804261 - SM2540 C										
Duplicate (1804261-DUP1)		rce: 18D0606		Prepared: 04		nalyzed: 0	4/27/2018			
Total Dissolved Solids (Residue, Filterable)	630	20	mg/L		630			0.3	5	
Duplicate (1804261-DUP2)	Sou	rce: 18D0606	5-02	Prepared: 04	1/26/2018 A	nalyzed: 0	4/27/2018			
Total Dissolved Solids (Residue, Filterable)	610	20	mg/L		620			0.8	5	
Batch 1804268 - E335.4										
Blank (1804268-BLK1)				Prepared: 04	1/26/2018 A	nalyzed: 0	4/30/2018			
Cyanide	ND	0.10	mg/L							
LCS (1804268-BS1)				Prepared: 04	1/26/2018 A	nalyzed: 0	4/30/2018			
Cyanide	2.0	0.10	mg/L	2.000		101	90-110			
LCS Dup (1804268-BSD1)				Prepared: 04	1/26/2018 A	nalyzed: 0	4/30/2018			
Cyanide	2.0	0.10	mg/L	2.000		101	90-110	0.1	20	
Matrix Spike (1804268-MS1)	Sou	rce: 18D0602	2-03	Prepared: 04	1/26/2018 A	nalyzed: 0	4/30/2018			
Cyanide	2.1	0.10	mg/L	2.000	ND	103	90-110			
Matrix Spike Dup (1804268-MSD1)	Sou	rce: 18D0602	2-03	Prepared: 04	1/26/2018 A	nalvzed: 0	4/30/2018			
Cyanide	2.0	0.10	mg/L	2.000	ND	98	90-110	5	20	
Batch 1804272 - E150.1										
Duplicate (1804272-DUP1)	Sou	rce: 18D0662	2-02	Prepared &	Analyzed: 0	4/26/2018				
pH (pH Units)	7.8		-		7.8			0.1	200	H5
Temperature (°C)	21		-		21			2	200	Н5
Batch 1805027 - SM2320B										
LCS (1805027-BS1)				Prepared &	Analyzed: 0	5/03/2018				
Alkalinity, Total (As CaCO3)	240	2.0	mg/L	250.0		96	90-110			
LCS Dup (1805027-BSD1)				Prepared &	Analyzed: 0	5/03/2018				
Alkalinity, Total (As CaCO3)	240	2.0	mg/L	250.0		96	90-110	0	10	
Matrix Spike (1805027-MS1)	Sou	rce: 18D0606	5-02	Prepared &	Analyzed: 0	5/03/2018				
Alkalinity, Total (As CaCO3)	370	2.0	mg/L	250.0	130	96	85-115			
Matrix Spike Dup (1805027-MSD1)	Sou	rce: 18D0606	5-02	Prepared &	Analyzed: 0	5/03/2018				
Alkalinity, Total (As CaCO3)	370	2.0	mg/L	250.0	130	95	85-115	0.5	10	
Batch 1805103 - SM2510 B										
LCS (1805103-BS1)				Prepared &	Analyzed: 0	5/09/2018				
Conductivity	140	0.10	μmhos/cm	141.2		101	0-200			
LCS Dup (1805103-BSD1)				Prepared &	Analyzed: 0	5/09/2018				
Conductivity	140	0.10	μmhos/cm	141.2		101	0-200	0.7	200	
Duplicate (1805103-DUP1)	Sou	rce: 18E0192	-01	Prepared &	Analyzed: 0	5/09/2018				
Conductivity	4.0	0.10	μmhos/cm		4.0			0	10	

Client: Brown & Caldwell

 Project:
 PTF

 Work Order:
 18D0619

 Date Received:
 04/25/2018

QC Summary

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Qual
Batch 1805074 - SW8260B										
Blank (1805074-BLK1)				Prepared &	Analyzed:	05/07/2018	;			
Benzene	ND	0.50	ug/L	•	•					
Carbon disulfide	ND	2.0	ug/L							
Ethylbenzene	ND	0.50	ug/L							
Toluene	ND	0.50	ug/L							
Xylenes, Total	ND	1.5	ug/L							
Surrogate: 4-Bromofluorobenzene	25.0		ug/L	25.00		100	70-130			
Surrogate: Dibromofluoromethane	26.9		ug/L	25.00		107	70-130			
Surrogate: Toluene-d8	25.1		ug/L	25.00		100	70-130			
LCS (1805074-BS1)				Prepared &	Analyzed:	05/07/2018	}			
1,1-Dichloroethene	29		ug/L	25.00		114	70-130			
Benzene	27		ug/L	25.00		109	70-130			
Chlorobenzene	29		ug/L	25.00		115	70-130			
Toluene	25		ug/L	25.00		101	70-130			
Trichloroethene	26		ug/L	25.00		103	70-130			
Surrogate: 4-Bromofluorobenzene	24.6		ug/L	25.00		98	70-130			
Surrogate: Dibromofluoromethane	25.6		ug/L	25.00		102	70-130			
Surrogate: Toluene-d8	24.8		ug/L	25.00		99	70-130			
LCS Dup (1805074-BSD1)				Prepared &	Analyzed:	05/07/2018	;			
1,1-Dichloroethene	27		ug/L	25.00		110	70-130	4	30	
Benzene	26		ug/L	25.00		104	70-130	5	30	
Chlorobenzene	26		ug/L	25.00		105	70-130	9	30	
Toluene	24		ug/L	25.00		96	70-130	5	30	
Trichloroethene	25		ug/L	25.00		98	70-130	4	30	
Surrogate: 4-Bromofluorobenzene	24.4		ug/L	25.00		98	70-130			
Surrogate: Dibromofluoromethane	26.1		ug/L	25.00		104	70-130			
Surrogate: Toluene-d8	25.1		ug/L	25.00		100	70-130			
Matrix Spike (1805074-MS1)	So	urce: 18D0582-	-02	Prepared &	Analyzed:	05/07/2018	;			
1,1-Dichloroethene	27		ug/L	25.00	0.070	109	70-130			
Benzene	26		ug/L	25.00	0.020	104	70-130			
Chlorobenzene	26		ug/L	25.00	0.0	105	70-130			
Toluene	27		ug/L	25.00	3.5	95	70-130			
Trichloroethene	24		ug/L	25.00	0.040	97	70-130			
Surrogate: 4-Bromofluorobenzene	24.4		ug/L	25.00		98	70-130			
Surrogate: Dibromofluoromethane	26.4		ug/L	25.00		106	70-130			
Surrogate: Toluene-d8	24.9		ug/L	25.00		100	70-130			
Matrix Spike Dup (1805074-MSD1)	So	urce: 18D0582-	-02	Prepared &	Analyzed:	05/07/2018	<u> </u>			
1,1-Dichloroethene	27		ug/L	25.00	0.070	108	70-130	0.8	30	
Benzene	25		ug/L	25.00	0.020	101	70-130	2	30	
Chlorobenzene	26		ug/L	25.00	0.0	105	70-130	0.3	30	
Toluene	27		ug/L	25.00	3.5	95	70-130	0.1	30	
Trichloroethene	24		ug/L	25.00	0.040	95	70-130	2	30	
Surrogate: 4-Bromofluorobenzene	24.7		ug/L	25.00		99	70-130			
Surrogate: Dibromofluoromethane	26.4		ug/L	25.00		106	70-130			
Surrogate: Toluene-d8	25.3		ug/L	25.00		101	70-130			

Client: Brown & Caldwell

 Project:
 PTF

 Work Order:
 18D0619

 Date Received:
 04/25/2018

QC Summary

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Qual
Batch 1804245 - E300.0 (2.1)			0.2220			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				Q
Blank (1804245-BLK1)				Prepared &	Analyzed: (04/25/2018				
Chloride	ND	1.0	mg/L							
Fluoride	ND	0.50	mg/L							
Nitrogen, Nitrate (As N)	ND	0.50	mg/L							
Nitrogen, Nitrite (As N)	ND	0.10	mg/L							
Sulfate	ND	5.0	mg/L							
LCS (1804245-BS1)				Prepared &	Analyzed: (04/25/2018				
Chloride	12	1.0	mg/L	12.50		92	90-110			
Fluoride	2.0	0.50	mg/L	2.000		101	90-110			
Nitrogen, Nitrate (As N)	4.7	0.50	mg/L	5.000		95	90-110			
Nitrogen, Nitrite (As N)	2.3	0.10	mg/L	2.500		92	90-110			
Sulfate	12	5.0	mg/L	12.50		96	90-110			
LCS Dup (1804245-BSD1)				Prepared &	Analyzed: (04/25/2018				
Chloride	12	1.0	mg/L	12.50		94	90-110	2	10	
Fluoride	2.0	0.50	mg/L	2.000		101	90-110	0.4	10	
Nitrogen, Nitrate (As N)	4.9	0.50	mg/L	5.000		98	90-110	3	10	
Nitrogen, Nitrite (As N)	2.4	0.10	mg/L	2.500		95	90-110	3	10	
Sulfate	12	5.0	mg/L	12.50		98	90-110	3	10	
Matrix Spike (1804245-MS1)	Sor	ırce: 18D0613-	-08	Prepared &	Analyzed: (04/25/2018				
Fluoride	3.7	0.50	mg/L	2.000	1.7	100	80-120			
Nitrogen, Nitrate (As N)	4.7	0.50	mg/L	5.000	0.22	89	80-120			
Matrix Spike (1804245-MS2)	Sor	ırce: 18D0625-	-01	Prepared &	Analyzed: (04/26/2018				
Nitrogen, Nitrate (As N)	5.0	0.50	mg/L	5.000	0.46	92	80-120			
Nitrogen, Nitrite (As N)	2.2	0.10	mg/L	2.500	ND	88	80-120			
Matrix Spike (1804245-MS3)	Sor	ırce: 18D0614	-01RE1	Prepared &	Analyzed: (04/26/2018				
Chloride	17		mg/L	12.50	6.4	88	80-120			
Sulfate	28		mg/L	12.50	18	85	80-120			
Matrix Spike Dup (1804245-MSD1)	Sou	ırce: 18D0613-	-08	Prepared &	Analyzed: (04/25/2018				
Fluoride	3.7	0.50	mg/L	2.000	1.7	100	80-120	0.4	10	
Nitrogen, Nitrate (As N)	4.7	0.50	mg/L	5.000	0.22	90	80-120	0.6	10	
Matrix Spike Dup (1804245-MSD2)	Sor	ırce: 18D0625-	-01	Prepared &	Analyzed: (04/26/2018				
Nitrogen, Nitrate (As N)	5.1	0.50	mg/L	5.000	0.46	92	80-120	0.2	10	
Nitrogen, Nitrite (As N)	2.2	0.10	mg/L	2.500	ND	88	80-120	0.4	10	
Matrix Spike Dup (1804245-MSD3)	Sor	ırce: 18D0614	-01RE1	Prepared &	Analyzed: (04/26/2018				
Chloride	18		mg/L	12.50	6.4	89	80-120	0.6	10	
Sulfate	29		mg/L	12.50	18	86	80-120	0.6	10	



CHAIN OF CUSTODY/LABORATORY ANALYSIS REQUEST FORM

- DATE \$123 (S TURNER WORK ORDER # 1806 619

QF.

PAGE

PROJECT NAME_Florence Copper#			CIRCI	E AN	4LYSI!	S REQ	UESTED	AND/OR (CHECKT	HE APP	CIRCLE ANALYSIS REQUESTED AND/OR CHECK THE APPROPRIATE BOX	
CONTACT NAME : Barb Sylvester	SA						_		_			
COMPANY NAME: Brown and Caldwell		× 1000000				77<	(¢tə)		_			
ADDRESS: 2 N Central Ave, Suite 1600	CONT	- Annual Control			(qn	edqlA						
CITY Phoenix STATE AZ ZIP CODE 85004	9 1907				is Vaəl	.e if G.						
PHONE_602-567-3894 ,FAX	50V	ı) wn			_	τίνίτγ						
SAMPLER'S SIGNATURE (L.)	NUN sletəM	Urani	· soine;	ide (fro l - soin	у) ' ецс	oe wni	8SS ,8					
SAMPLE I.D. DATE TIME LAB I.D. SAMPLE MATRIX*		Total				Uran						
	101	Y	_	_^	_		_					F
\$260 TB 4-23-18 160c GW	_		_	×								
MS												
MS												F
MS												
MB												
MS GW									-			I
MS GW												
MB												
M9 GM												
M9 GM												
1. RELINQUISHED BY: TURNAF	TURNAROUND REQUIREMENTS:	REMENT		REPO	RT REQU	REPORT REQUIREMENTS:	VTS:	INVOICE INFORMATION:	NFORM/	TION	SAMPLE RECEIPT:	T
200	X Standard (approx10 days)*	*js/i	×	 8	I. Routine Report	ort)		
Signature Signature Next day	V_2 Day_	_S Day*	real	II. Repo	rt (includ	II. Report (includes DUP,MS,MSD	II. Report (includes DUP,MS,MSD, as red. may be charged as samples)	Account X	N ≻		Total Containers	
Printed Name	Email Preliminary Results To:	.To:	All A	III. Date	Validatio	n Report	III. Date Validation Report (Includes	P.O.#			Temperature 7	7
Firm			Add	Add 10% to invoice	woice							
2018 1630	ays		-	×				Bill to: Florence Copper	се Сорр	er	☑ Wet Ice □ BI	Blue Ice
W.	*LEGEND		SP	ECIAL	INSTE	NCTI	ONS/CO	SPECIAL INSTRUCTIONS/COMMENTS:				
1	DW = DRINKING WATER GW = GROUNDWATER	22	Co	Compliance Analysis:	Analys	100	☐ Yes ☐ No	lo Custody Seals	Seals	□ Pre	Preservation Confirmation	Ø
(a) actemo	D		AD	ADEQ Forms:	rms:		☐ Yes ☐ No		Container Intact	App App	Appropriate Head Space	M
Firm TURNER LABORATORIES INC. SG = SUUDGE	JGE		ž	il ADE	Q For	Mail ADEQ Forms: Yes	Yes No		COC/Labels Agree	Z Kee	Received Within Hold Time	
2	ST = STORMWATER											
M-101	BIEWAIEN		1		l						Page	13 of 32



Ask-

www.testamericainc.com

Visit us at:

Expert

TestAmerica

THE LEADER IN ENVIRONMENTAL TESTING

ANALYTICAL REPORT

TestAmerica Laboratories, Inc.

TestAmerica Phoenix 4625 East Cotton Ctr Blvd Suite 189 Phoenix, AZ 85040

Tel: (602)437-3340

TestAmerica Job ID: 550-101943-1

Client Project/Site: 18D0619

For:

Turner Laboratories, Inc. 2445 North Coyote Drive Suite 104 Tucson, Arizona 85745

Attn: Kevin Brim

Authorized for release by: 5/16/2018 12:23:25 PM

Ken Baker, Project Manager II (602)659-7624

ken.baker@testamericainc.com

This report has been electronically signed and authorized by the signatory. Electronic signature is intended to be the legally binding equivalent of a traditionally handwritten signature.

Results relate only to the items tested and the sample(s) as received by the laboratory.

Client: Turner Laboratories, Inc. Project/Site: 18D0619

Table of Contents

Cover Page	1
Table of Contents	2
Definitions/Glossary	3
Case Narrative	4
Sample Summary	5
Detection Summary	6
Client Sample Results	7
Surrogate Summary	8
QC Sample Results	9
QC Association Summary	10
Lab Chronicle	11
Certification Summary	12
Method Summary	13
Chain of Custody	14
Receipt Checklists	15

9

11

12

14

Definitions/Glossary

Client: Turner Laboratories, Inc.

Project/Site: 18D0619

TestAmerica Job ID: 550-101943-1

Qualifiers

GC Semi VOA

Q9 Insufficient sample received to meet method QC requirements.

Glossary

Abbreviation	These commonly used abbreviations may or may not be present in this report.

Listed under the "D" column to designate that the result is reported on a dry weight basis

%R Percent Recovery **CFL** Contains Free Liquid **CNF** Contains No Free Liquid

DER Duplicate Error Ratio (normalized absolute difference)

Dil Fac Dilution Factor

DL Detection Limit (DoD/DOE)

DL, RA, RE, IN Indicates a Dilution, Re-analysis, Re-extraction, or additional Initial metals/anion analysis of the sample

Decision Level Concentration (Radiochemistry) DLC

Estimated Detection Limit (Dioxin) **EDL** LOD Limit of Detection (DoD/DOE) LOQ Limit of Quantitation (DoD/DOE)

MDA Minimum Detectable Activity (Radiochemistry) MDC Minimum Detectable Concentration (Radiochemistry)

MDL Method Detection Limit ML Minimum Level (Dioxin)

NC Not Calculated

Not Detected at the reporting limit (or MDL or EDL if shown) ND

PQL Practical Quantitation Limit

QC **Quality Control**

RER Relative Error Ratio (Radiochemistry)

Reporting Limit or Requested Limit (Radiochemistry) RL

RPD Relative Percent Difference, a measure of the relative difference between two points

TEF Toxicity Equivalent Factor (Dioxin) Toxicity Equivalent Quotient (Dioxin) **TEQ**

3

Case Narrative

Client: Turner Laboratories, Inc.

Project/Site: 18D0619

TestAmerica Job ID: 550-101943-1

Job ID: 550-101943-1

Laboratory: TestAmerica Phoenix

Narrative

Job Narrative 550-101943-1

Comments

No additional comments.

Receipt

The sample was received on 4/27/2018 10:50 AM; the sample arrived in good condition, properly preserved and, where required, on ice. The temperature of the cooler at receipt was 3.8° C.

GC Semi VOA

Method(s) 8015D: Insufficient sample volume was available to perform a matrix spike/matrix spike duplicate/sample duplicate (MS/MSD) associated with preparation batch 550-145985 and analytical batch 550-146884. Affected samples have been added a Q9 qualifier. 18D0619-01 (550-101943-1)

No additional analytical or quality issues were noted, other than those described above or in the Definitions/Glossary page.

Organic Prep

Method(s) 3510C: Insufficient sample volume was available to perform a matrix spike/matrix spike duplicate (MS/MSD) associated with 3510C.

No additional analytical or quality issues were noted, other than those described above or in the Definitions/Glossary page.

2

3

4

<u>၂</u>

7

8

9

10

13

14

Sample Summary

Client: Turner Laboratories, Inc. Project/Site: 18D0619

TestAmerica Job ID: 550-101943-1

Lab Sample ID	Client Sample ID	Matrix	Collected Received
550-101943-1	18D0619-01	Water	04/23/18 15:55 04/27/18 10:50

Detection Summary

Client: Turner Laboratories, Inc.

Client Sample ID: 18D0619-01

Project/Site: 18D0619

TestAmerica Job ID: 550-101943-1

Lab Sample ID: 550-101943-1

Analyte	Result Qualifier	RL	Unit	Dil Fac D	Method	Prep Type
ORO (C22-C32)	0.21 Q9	0.20	mg/L		8015D	Total/NA

3

4

5

6

8

9

11

12

13

41.

Client Sample Results

Client: Turner Laboratories, Inc.

Client Sample ID: 18D0619-01

Project/Site: 18D0619

TestAmerica Job ID: 550-101943-1

Lab Sample ID: 550-101943-1

Matrix: Water

Date Collected: 04/23/18 15:55 Date Received: 04/27/18 10:50

Method: 8015D - Diesel Range Organics (DRO) (GC)

Metriod, 6013D - Dieser Kange Organics (DRO) (GC)									
	Analyte	Result	Qualifier	RL	Unit	D	Prepared	Analyzed	Dil Fac
	ORO (C22-C32)	0.21	Q 9	0.20	mg/L		04/30/18 14:16	05/10/18 23:29	1
	DRO (C10-C22)	ND	Q9	0.10	mg/L		04/30/18 14:16	05/10/18 23:29	1

Surrogate	%Recovery Qualifie	r Limits	Prepared	Analyzed	Dil Fac
o-Terphenyl (Surr)	79	10 - 150	04/30/18 14:16	05/10/18 23:29	1

Surrogate Summary

Client: Turner Laboratories, Inc.

Project/Site: 18D0619

TestAmerica Job ID: 550-101943-1

2

3

Method: 8015D - Diesel Range Organics (DRO) (GC)

Matrix: Water Prep Type: Total/NA

Recovery (Acceptance Limits)
_

TestAmerica Phoenix

Page 21 of 32

QC Sample Results

Client: Turner Laboratories, Inc.

Project/Site: 18D0619

TestAmerica Job ID: 550-101943-1

Method: 8015D - Diesel Range Organics (DRO) (GC)

Lab Sample ID: MB 550-145985/1-A	Client Sample ID: Method Blank
Matrix: Water	Prep Type: Total/NA
Analysis Batch: 146884	Prep Batch: 145985
MR MR	·

	MB MB	3				•	
Analyte	Result Qu	alifier RL	Unit	D	Prepared	Analyzed	Dil Fac
ORO (C22-C32)	ND ND	0.20	mg/L		04/30/18 14:15	05/11/18 11:16	1
DRO (C10-C22)	ND	0.10	mg/L		04/30/18 14:15	05/11/18 11:16	1
	MB MB	3					

	MB	MB				
Surrogate	%Recovery	Qualifier	Limits	Prepared	Analyzed	Dil Fac
o-Terphenyl (Surr)	65		10 - 150	04/30/18 14:15	05/11/18 11:16	1
-						

Lab Sample ID: LCS 550-7 Matrix: Water Analysis Batch: 146884	145985/2-A					Clie	nt Sa	mple ID	Prep Type: Total/NA Prep Batch: 145985
			Spike	LCS	LCS				%Rec.
Analyte			Added	Result	Qualifier	Unit	D	%Rec	Limits
ORO (C22-C32)			1.60	1.59		mg/L		99	69 - 107
DRO (C10-C22)			0.400	0.450		mg/L		113	42 - 133
	LCS	LCS							
Surrogate	%Recovery	Qualifier	Limits						
o-Terphenyl (Surr)	79		10 - 150						

Lab Sample ID: LCSD 550-145985/3-A Matrix: Water			C	Client S	ample	ID: Lab	Control Prep Ty		•
Analysis Batch: 146884							Prep Ba	itch: 14	45985
	Spike	LCSD	LCSD				%Rec.		RPD
Analyte	Added	Result	Qualifier	Unit	D	%Rec	Limits	RPD	Limit
ORO (C22-C32)	1.60	1.59		mg/L		100	69 - 107	0	20
DRO (C10-C22)	0.400	0.447		mg/L		112	42 - 133	1	22

DRO (C10-C22)		0.400	0.447	
	LCSD LCSD			
Surrogate	%Recovery Qualifier	Limits		
o-Terphenyl (Surr)	79	10 - 150		

TestAmerica Phoenix

Page 22 of 32

Page 9 of 15

2

3

1

5

7

8

9

10

11

12

4 4

-

QC Association Summary

Client: Turner Laboratories, Inc.

Project/Site: 18D0619

TestAmerica Job ID: 550-101943-1

2

GC Semi VOA

Prep Batch: 145985

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method Prep Batch	ı
550-101943-1	18D0619-01	Total/NA	Water	3510C	
MB 550-145985/1-A	Method Blank	Total/NA	Water	3510C	
LCS 550-145985/2-A	Lab Control Sample	Total/NA	Water	3510C	
LCSD 550-145985/3-A	Lab Control Sample Dup	Total/NA	Water	3510C	

Analysis Batch: 146884

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
550-101943-1	18D0619-01	Total/NA	Water	8015D	145985
MB 550-145985/1-A	Method Blank	Total/NA	Water	8015D	145985
LCS 550-145985/2-A	Lab Control Sample	Total/NA	Water	8015D	145985
LCSD 550-145985/3-A	Lab Control Sample Dup	Total/NA	Water	8015D	145985

3

4

5

7

0

10

11

40

14

Lab Chronicle

Client: Turner Laboratories, Inc.

Date Received: 04/27/18 10:50

Analysis

Project/Site: 18D0619

TestAmerica Job ID: 550-101943-1

Lab Sample ID: 550-101943-1

Client Sample ID: 18D0619-01 Date Collected: 04/23/18 15:55 Matrix: Water

Batch Batch Dilu **Prep Type** Method Run Fa Type Total/NA Prep 3510C

8015D

ution	Batch	Prepared			
actor	Number	or Analyzed	Analyst	Lab	
	145985	04/30/18 14:16	REM	TAL PHX	
1	146884	05/10/18 23:29	TC1	TAL PHX	

Laboratory References:

Total/NA

TAL PHX = TestAmerica Phoenix, 4625 East Cotton Ctr Blvd, Suite 189, Phoenix, AZ 85040, TEL (602)437-3340

TestAmerica Phoenix

Accreditation/Certification Summary

Client: Turner Laboratories, Inc.

TestAmerica Job ID: 550-101943-1

Project/Site: 18D0619

Laboratory: TestAmerica Phoenix

Unless otherwise noted, all analytes for this laboratory were covered under each accreditation/certification below.

Authority Arizona	Program State Prog	ram	EPA Region	AZ0728	Expiration Date 06-09-18
Analysis Method	Prep Method	Matrix	Analyt	e	

2

Method Summary

Client: Turner Laboratories, Inc.

Project/Site: 18D0619

TestAmerica Job ID: 550-101943-1

Method	Method Description	Protocol	Laboratory
8015D	Diesel Range Organics (DRO) (GC)	SW846	TAL PHX
3510C	Liquid-Liquid Extraction (Separatory Funnel)	SW846	TAL PHX

Protocol References:

SW846 = "Test Methods For Evaluating Solid Waste, Physical/Chemical Methods", Third Edition, November 1986 And Its Updates.

Laboratory References:

TAL PHX = TestAmerica Phoenix, 4625 East Cotton Ctr Blvd, Suite 189, Phoenix, AZ 85040, TEL (602)437-3340

2

4

5

6

a

10

11

12

14

15

Page 26 of 32

SUBCONTRACT ORDER

Turner Laboratories, Inc.

18D0619

SENDING LABORATORY:

Turner Laboratories, Inc.

2445 N. Coyote Drive, Ste #104

Tucson, AZ 85745 Phone: 520.882.5880 Fax: 520.882.9788

Project Manager: Kevin Brim

RECEIVING LABORATORY:

TestAmerica Phoenix

4625 East Cotton Center Boulevard Suite 189

Phoenix, AZ 85540 Phone :(602) 437-3340

Fax:

Please CC Kevin Brim Kbrim@turnerlabs.com

Analysis

Expires

Laboratory ID

Comments

-07

Sample ID: 18D0619-01 Drinking Water Sampled: 04/23/2018 15:55

8015D Sub

04/30/2018 15:55

8015D DRO and ORO Paramaters Only

Containers Supplied:

8015D Sub

o-Terphenyl C10-C32 (Total) C22-C32 (Oil Range Organics) C10-C22 (Diesel Range Organics) C6-C10 (Gasoline Range Organics)



(3,8°2) UPS GR

TA-PHX

Released By

Date

Received By

トコス

Date

Page 1 of 1

Released By

Date

Received

Page 27 of 32

Login Sample Receipt Checklist

Client: Turner Laboratories, Inc.

Job Number: 550-101943-1

Login Number: 101943 List Source: TestAmerica Phoenix

List Number: 1

Creator: Gravlin, Andrea

orcator. Gravini, Anarca		
Question	Answer	Comment
Radioactivity wasn't checked or is = background as measured by a survey meter.</td <td>True</td> <td></td>	True	
The cooler's custody seal, if present, is intact.	True	
Sample custody seals, if present, are intact.	True	
The cooler or samples do not appear to have been compromised or tampered with.	True	
Samples were received on ice.	True	
Cooler Temperature is acceptable.	True	
Cooler Temperature is recorded.	True	
COC is present.	True	
COC is filled out in ink and legible.	True	
COC is filled out with all pertinent information.	True	
Is the Field Sampler's name present on COC?	True	
There are no discrepancies between the containers received and the COC.	True	
Samples are received within Holding Time (excluding tests with immediate HTs)	True	
Sample containers have legible labels.	True	
Containers are not broken or leaking.	True	
Sample collection date/times are provided.	True	
Appropriate sample containers are used.	True	
Sample bottles are completely filled.	True	
Sample Preservation Verified.	True	
There is sufficient vol. for all requested analyses, incl. any requested MS/MSDs	True	
Containers requiring zero headspace have no headspace or bubble is <6mm (1/4").	True	
Multiphasic samples are not present.	True	
Samples do not require splitting or compositing.	True	
Residual Chlorine Checked.	False	Check done at department level as required.



Radiation Safety Engineering, Inc.

3245 N. WASHINGTON ST. + CHANDLER, ARIZONA 85225-1121

(480) 897-9459

Website: www.radsafe.com

FAX (480) 892-5446

Radiochemical Activity in Water (pCi/L)

Turner Laboratories 2445 N. Coyote Drive, Ste. 104 Tucson, AZ 85745

Sampling Date: April 23, 2018 Sample Received: May 01, 2018 Analysis Completed: May 22, 2018

Sample ID	Gross Alpha Activity Method 600/00-02 (pCi/L)	Uranium Activity Method ASTM D6239 (pCi/L)	Adjusted Gross Alpha (pCi/L)	Radium 226 Activity Method GammaRay HPGE (pCi/L)	Radium 228 Activity Method GammaRay HPGE (pCi/L)	Total Radium (pCi/L)
18D0619-01	17.7 ± 0.9	12.9 ± 1.2	4.8 ± 1.5	3.1 ± 0.3	3.1 ± 0.4	6.2 ± 0.5

					T	
Date of Analysis	5/2/2018	5/21/2018	5/21/2018	5/4/2018	5/4/2018	5/4/2018

Robert L. Metzger, Ph.D., C.H.P.

5/22/2018

Laboratory License Number AZ0462

Date



Radiation Safety Engineering, Inc.

3245 N. WASHINGTON ST. + CHANDLER, ARIZONA 85225-1121 Website: www.radsafe.com

(480) 897-9459 FAX (480) 892-5446

Isotopic Uranium Analysis

Turner Laboratories 2445 N. Coyote Drive, Ste. 104 Tucson, AZ 85745

Sampling Date: April 23, 2018 Sample Received: May 01, 2018 Uranium Analysis Date: May 21, 2018

Sample No.	²³⁸ U	²³⁵ U	²³⁴ U	Total	
18D0619-01	6.0 ± 0.6	0.280 ± 0.004	6.6 ± 0.6	12.9 ± 1.2	Activity (pCi/L)
	17.9 ± 1.7	0.131 ± 0.002	0.00106 ± 0.00010	18.0 ± 1.7	Content (μg/L)
	Comments:		Page 11 and 12		

Robert L. Metzger, Ph.D., C.H.P.

5/22/2018

Date

Laboratory License Number AZ0462

Arizona Department of Environmental Quality

Drinking Water Radionuclides-Adjusted Gross Alpha, Radium 226 & 228, Uranium Analysis Report ***Samples To Be Taken At Entry Point Into Distribution System (EPDS) Only***

PWS ID#: AZ04 April 23, 2018				PWS Name:					
		15:55	(24 hour clock)						
Sample Date			me	Owner/Contact Person					
Owner/Contact Fax Number				Owner/Contact Phone Number					
Sample Collection EPDS #	ction Point								
Complianc	e Sample	Type:							
Reduced Monitoring			Date (Q1 collected:					
Quar	terly		¥1	Date (Q2 collected:		_		
Composite of four quarterly samples			Date (Q3 collected:		_			
	1	\$1	.Me	Date (Q4 collected:	19	-		
Per			***RADIOCHEN >>>To be filled out b			• • • • • • • • • • • • • • • • • • • •		2	
		***Coml	pined Uranium must be						
Analysis Method	MCL	Reporting Limit	Contaminant	Cont. Code	Analyses Run Date	Result		Exceed	
	15 pCi/L		Adjusted Gross Alpha	4000	5/21/2018	4.8 ± 1.5		MCL	
600/00-02		3 pCi/L	Gross Alpha	4002	5/2/2018	$\frac{4.8 \pm 1.3}{17.7 \pm 0.9}$	-		
7500 - Rn			Radon	4004	3/2/2016	17.7 ± 0.9	-		
ASTM D6239	30 μg/L	1 μg/L	Combined Uranium	4006	5/21/2018	18.0 ± 1.7	- "		
			Uranium 234	4007	5/21/2018	0.00106 ± 0.00010	μg/L		
			Uranium 235	4008	5/21/2018	0.00708 ± 0.00070 0.131 ± 0.002			
			Uranium 238	4009	5/21/2018	17.9 ± 1.7			
	5 pCi/L	1 pCi/L	Combined Radium (226,228)	4010	5/4/2018	6.2 ± 0.5	-	х	
GammaRay HPGE		1 pCi/L	Radium 226	4020	5/4/2018	3.1 ± 0.3		Λ	
GammaRay HPGE		1 pCi/L	Radium 228	4030	5/4/2018	3.1 ± 0.4			
			***LABORATORY I	NEODMA	TIONALL				
		5	>>>To be filled out by la						
Specimen Numb	er DCEA		>>>To be filled out by la	вогатогу р	ersonner<<				
	-	50312	>>>To be filled out by la	- -	ersonner				
Specimen Numb Lab ID Number: Lab Name: R.	AZ04	60312 62		- - -	ersonner				
Lab ID Number: Lab Name: R	AZ04 adiation Safe	60312 62 ty Engineering	, Inc.	-		50			
Lab ID Number: Lab Name: R Printed Name an	AZ04 adiation Safe	60312 62 ty Engineering	, Inc.	-	C.H.P. (480) 897-94	59			

DWAR 6: 11/2007

SUBCONTRACT ORDER

Turner Laboratories, Inc. 18D0619

SENDING LABORATORY:

Turner Laboratories, Inc.

2445 N. Coyote Drive, Ste #104

Tucson, AZ 85745

Phone: 520.882.5880 Fax: 520.882.9788

Project Manager:

Kevin Brim

RECEIVING LABORATORY:

Radiation Safety Engineering, Inc.

3245 N. Washington St.

Chandler, AZ 85225-1121

Phone: (480) 897-9459

Fax: (480) 892-5446

Please CC Kevin Brim Kbrim@turnerlabs.com

Analysis

Expires

Laboratory ID

Comments

Sample ID: 18D0619-01 Drinking Water Sampled:04/23/2018 15:55

Radiochemistry, Gross Alpha

Radiochemistry, Radium 226/228

10/20/2018 15:55

Analyze Uranium and Adjusted Alpha if G. Alpha is > 12

Containers Supplied:

05/23/2018 15:55

tt 60312

Received By

Released By

Date

Received By

Date

APPENDIX D

Well Completion Documentation

PIPE TALLY

Project Name.: FCT	Project No.: 12968フーののフ
Well No.: 〇~0日	Date: -15-18
Location: Toxence	Pipe Talley for: C. Price &
Total Depth: 12.00	Geologist: WP// IN5tal/

Type of Connections: Welded T+C Flush Thread Other

	Pipe	V	Length (ft)	Length ∑		: Туре	Dist. from sensor bottom to bottom of pipe (feet)	Sensor Type (ACD, CS, ERT)	Sensor ID	Wire Lead ID	Depth of Sensor (feet bgs)
	(V.	0,35	0.35	316	5.5. E	ndcop				
	\mathbb{Z}	V	20,03	20.38	0.020	Screet	6,24	ERT	10		1193,41
K.	7	£.	20-03	40.41			f	'			
	Ч	Y/	20.05	60.46							
Χ.	5	V	20.05	80.51							
	le	V	20.03	100,54		-	. 2.10	ERT	9		1117.39
۲	7		20,04	120.58							
	6	1/	20.03	140.61			- A A D				
	d	2	20.04	160.65			18.10	FIRT	_8		1041.29
₹	10	i/	20.05	180.70			•	·'			
×	11	V	30.04	200.74					***************************************		
	12			220.78			. 1. 4.2	y	-	'	015 50
X.	13	V	0 1,25	240-81	-	•	-11.92	Ent			967.30
.	14	•	20.05	260.86		and the second					
X	15 16	1	20.05	280,91							
	10			300.94- 320.98			7	ERT	1.1		812.15
X	18	1/	20.04	341.02			6.91	1211	4		0 12.15
	19	<u> </u>	20.04	361.06							
kg.	20		20.04	381.10							
	21	V		401.14			1.93	Ferr	13		816.97
۱,	22	. /	20.03	451.15	 		11.12	70100			010/1/
	23	V	20.03	441.20							
`∥	24	V.	20,04	461.24			16,94	EPT	A		741.86
<i>i</i> -	25	./	20.03	481.27		· ·					
٠	26	W	20.03	501.30							
	25	1	20.03	52133	 						
78	28	1	20.03	541.36		Wilderson	12.23	Kent	3		666.41
	2.9	V	20.03	561.39							
.	S Ò	V	20.03	581.42							

Notes:	ll .	SUMMARY OF TALLY
Y/ENTERLIGHTS STEPPED AD, STEPPED	Total Length tallied:	1202.36
N 100 6 12 7/4	Casing Stick-Up:	2.36
CARRIER TOWN TO DITTALL CARRIER, LEADS	Length of Casing Cut-0	Off:
EYERA IN	Bottom of Well:	1200.00
	Screened Interval:	12-00.00 - 498.41
EASING 15 43/420, 5200 Schropuc, 9,020;	্বাক্তাal Screen in Hole:	701.59
	Sensor Types: Ar	nnular Conductivity Device (ACD), installed as pairs with 3 ft spacing
Endono - 316L Stainless Steel	Co	onductivity Sensor (CS) 4 sensors with sing lead 20 ft spacing
Scipen - SCH 60 5.56" OD. 4.77"	ID, El	ectrical Resistivity Tomography (ERT)
0.020" 510+		
FRP- 5.44" OD 4.74" ID 6.5	59" OD ON	couplers HALEY
PUC/FRP Transition -		ALDRIC
	septem . V	

Project I	Name.:	,			Project No.:	~~~			
Nell No.		-04			Date: 1-15-1	<u> </u>			
ocatio		2 1			Pipe Talley for:	Well i	nstall		
Total De	pth:				Geologist:	L = 1 =			
Type of	Connect	ions: 🚨	Welded 🚨	T+C 🚨 Flush	Thread 🛭 Other				
Pipe	V	Length	Length Σ	Pipe Type	Dist. from sensor bottom to bottom of	Sensor Type (ACD, CS,	Sensor ID	Wire Lead ID	Depth of Senso
		(ft)	(ft)		pipe (feet)	ERT)			(feet bgs)
3/	V	2004	601,46	0.020 Scheen					591,40
32	V	20.02	621.48		7.14	ERT	2		39090
33	2	20.03	641,51						
34.	V,	20:03	661.54						
35	1	20,02	681.56				-		611.00
36.	V	20.03	701.59	l	2015	KZT			516.29
37	1	0.50	702.09		nansition.				
38	V	29,24	731.33	FNP					
39	V	29.08	760.41			A State of the Sta			11.101.01
40	V	29.03	789.44		i		1		409,96
41.	V	29.07	818,51		0,60,0	65	14,3		390.14
42	V	29.12	847.63		11.49	CS'	2		370.00
43	V	29.08			2,20	C-S_			350117
44	VS.	29.07	905,78		,	,	2k)		
45	11/	29.14	934.92		19 10 121	ALD	1 1 22.24		<u></u>
46		59.14	964.06		1.1.17		<u> </u>		
47	1	29.22	993,26						
48		29.20	1022.48	1					
Ua	1	29.18	1051.66						
50	1	29.17	1080.83						
51		28.98							
52	1,	2910	1138,91						
53	 	29.09	1168,00						
54.	1	29.21	1197,21	1					
55	1.7	5,15	1202,74	*					<u></u>
5 6	1-4-	10	100000						
30	60.00	110	 						
	+	 	 						
		. 4	<u> </u>						
7 (2 (28) 7 (2)	1			 					
	<u> </u>	<u></u>	<u></u>						
Notes:					Total Length tallied	,	SUMMARY OF T	ALLY 	s 6 _
				<u> </u>	Casing Stick-Up:	•		2.36	
8,375					Length of Casing C	Cut-Off:			
602					Bottom of Well:	•		1200,00	2
					Screened Interval:				
					Total Screen in Ho	le:			
					Sensor Types:	Annular Cor	nductivity Device (A	CD), installed as p	pairs with 3 ft spac
							Sensor (CS) 4 sen		u zu it spacing
						Flantstool D.	sainthuibr Tomogran	nv (FRI)	

10' - 9.33 18" - 0.72 coupler = 0.81

HALBRICH

Casing Layout

Project Name.: Florence Copper INC	Project No.: 129687-007
Well No.: O-04	Date: 1-15-18 Through 1-16-18
Location: Florence AZ	Layout for: Well Install
Total Depth: 1200	Geologist: C Price and G Foushee

Pipe Length		Depth BGS	Pipe Length		Depth BGS	Pipe Length		Depth BGS
		758.80			235.94		i	
20.03	23	778.83	29.14	46	265.08			
20.03	22		29.14	45				
20.04	21	798.86	29.07	44	294.22			
20.04	20	818.90	29.08	43	323.29			
20.04	19	838.94	29.12	42	352.37			
20.04	18	858.98	29.07	41	381.49			
20.04	17	879.02	29.03	40	410.56			
		899.06			439.59			
20.03	16	919.09	29.08	39	468.67			
20.05	15	939.14	29.24	38	497.91			
20.05	14	959.19	0.50	37	498.41			
20.03	13	979.22	20.03	36	518.44			
20.04	12		20.02	35				
20.04	11	999.26	20.03	34	538.46			
20.05	10	1019.30	20.03	33	558.49	10.00	56	-12.36
20.04	9	1039.35	20.02	32	578.52	5.15	55	-2.36
20.03	8	1059.39	20.04	31	598.54	29.21	54	2.79
20.04	7	1079.42	20.03	30	618.58	29.09	53	32.00
		1099.46			638.61			61.09
20.03	6	1119.49	20.03	29	658.64	29.10	52	90.19
20.05	5	1139.54	20.03	28	678.67	28.98	51	119.17
20.05	4	1159.59	20.03	27	698.70	29.17	50	148.34
20.03	3	1179.62	20.03	26	718.73	29.18	49	177.52
20.03	2	1199.65	20.03	25	738.76	29.20	48	206.72
0.35	1		20.04	24		29.22	47	
		1200.00			758.80			235.94

Sensor Type	Sensor ID	Pipe #	Distance from Bottom of Sensor to Bottom of Pipe	Depth of Sensor (BGS)					
ERT	10	2	6.24	1193.41					
ERT	9	6	2.10	1117.39					
ERT	8	9	18.10	1041.29					
ERT	7	13	11.92	967.30					
ERT	6	17	6.91	892.15					
ERT	5	21	1.93	816.97					
ERT	4	24	16.94	741.86					
ERT	3	28	12.23	666.44					
ERT	2	32	7.14	591.40					
ERT	1	36	2.15	516.29					
CS	4	41	0.60	409.96					
CS	3	41	20.42	390.14					
CS	2	42	11.49	370.00					
CS	1	43	2.20	350.17					
ACD	2	45	19.19	275.03					
ACD	1	45	22.19	272.03					

Pipe Number	Туре
1	SS End Cap
2 - 36	PVC SCH 80 Screen 0.020
37	SS: PVC/Fiberglass Transition
38-55	5" FRP



ESTIMATED ANNULAR MATERIAL RECORD

ed in the character of	
1 1 1 1 2 2 1 1 2 2 2 2 2 2 2 2 2 2 2 2	1,100.00
.9	Francis (C. 1203.9.9. C. 1203.9.9. C. 1203.9.9. C. 1203.9.9. C. 1209.9.9. C. 1209.9.9. C. 1209.9. C
1/5/1/2 12.00.00 feet 1.1: 3.20 feet feet - feet - feet - inches t Ft³/Lin. Ft ck = 3000 lbs.	S. pur Sack
ME CALCULATIONS Total Cased Depth: Rat Hole Volume [R=(D²) 0.005454*L; ** 10.00.00	Tagged Comments Depth (ft bls) 1105
	5. Calculated (ft bepth? (ft
Project #:: Geologist: Ge	ed depth - (v/A) e
ne (A _s): (D²-d _s ?) 0. nular Volume (A _c): nular volume (A _c): EQUATIONS = bag weight/100	ious Calculated Volume of Bag¹ (v) 30 30 30 30 30 30 30 30 30 3
Project Name: $\overrightarrow{FC} \setminus \overrightarrow{PTDF}$ ANNULAR VC Total Depth of Borehole [T]: 13.30 feet Borehole Diameter [D]: 14.30 feet Screen Length [L _s]: $70^{1}, 59$ feet Screen Diameter [d _s]: $70^{1}, 59$ feet Casing Length [L _s]: $70^{1}, 59$ feet $70^{1}, 59$ feet $90^{1}, 59$ feet $90^{1},$	2 Calculated depth = Previous Calculated depth - (v/A) No.
Project Name: = C Well No.: 0 - 54 Well No.: 0 - 54 Total Depth of Borehc Borehole Diameter [D] Screen Length [L _a]: Screen Diameter [d _a]: Casing Length [L _a] Casing Annular Volur Casing Annular Volur Casing/Cam. Tube An Casing/Cam. Tube An 1 Volume of bag (Ft³)	Calculated No.

*pulked 12) them is 3.1 as grave loss up to the tream is pipe. Esten 115to

a bottom at borehale teg entitle 118 that was 1213 bgs.
Original culculations were based in a borehale Lipta of
1220 bys from Sw Exploration log. *** Update with comed bushave diameter of 14 walker

** SIL 1/18/18-1/cat hale volume update due to information about

K:\Templates\Field Forms\Well Inst & Testing Forms.xls




Project Name.	, Carel			ESTIMATED ANNULAR		ATERIAL	(Continued)	
Well No.:				Project No.: 39 &	0 2	730 0	Geologist: Artaosana / J. Janes	
No	>	Weight	Volume	Total Vol.	llated	Tagged	Comments	ST 1
		of Bag	of Bag¹(v)	of Bags	Depth ²	Depth		
		(lbs.)	(ff³)	(ff)	(ft bls)	(ft bis)		8
T)	7	2000	60 E	0.80	100 T			
S	>	3000	040	01,77	3	780		
<u> </u>	Samuel Sa		0	90 00 00	0 15			
sandar Remission		7000	No.	000	TO TO	\$ 00 0	なさの マングー 変 第二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十	
(3)	and the same	2,000		000	00 17		115 11	
	7	500C	0/2	0 10 - 00		000		
7	>	1000 C	2 %	0 5 4				
C	7,							
9	1	10 00 00		000				
7	1	3000	30	016		Sarah.	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	9
<u>%</u>	>	3680	30	のない	*		COOL A MAN DOO DOO TOWN A COOL OF THE COOL	503 + 50 - 60 -
0	>	3000	30	015	* ~ ~ ~	100)		
90	>	3220	.30	2000	× 695		(a) a (b) a (c) a	
2	7	3000	30	630	× 122	534	950.00	
33	>	3000	30	000	* 60%	503		
25	7	1500	15	510	* 1.85	195	(ACO.) (ACO.)	
	>	750	7.5	U825	* 125	490	1	
7	>	16.6.7	0.667	1,85.5	* 685	488	1.	
2	\prod	1000	0	12334	×		O POTAN TYTH SOUTH	
J.	Ĺ	37000 E	1/21/5+37.5	4048-55ch	* 505 x 75		Travel 13 8 months	
),					49.2	14 6 6 5	
						100	The State of the S	
Notes:	* 00	2(502 109	Nas	DAMNELL DIE METER	10	+ 14 in clus	(0.93 43)	
,	-	-						
				705				
/							· ·	

WEEKEN .								



E.

·0					N FINE		Children IV					1		Control of the Contro								100							
ESTIMATED ANNULAR MATERIAL RECORD (Continued) Project No.: i3のiocーフ Geologist: ノー・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・	100000000000000000000000000000000000000	Comments			TO BILLY BUILDS OFFI	0 5 WIN 10 10 10 10 10 10 10 10 10 10 10 10 10	とのでうったれる		JANGELINIS NI SPANIS	Dioces of 10 15 x 10 april 10 10 1 10 10 10 10 10 10 10 10 10 10 1	The state of the s		TOREST APPROPRIES	「ロン他ラ	was now of the state of the sta	THE DAYNE BUCKETS.	そうと できるいののころのにい かるまらしににって		Solto ora-son comis	1	575-500-1510 - M	AND G BUCKER THEN SURG IS	10 more. My Notes	REPORT OF ENSTALL COMORRE	# Sand Stolle bags (XV)	#605cmd 5016 6405 (x4)	7		
TERIAL RE		Tagged	Depth	(ft bls)				7	1				400	420	402-10	40	400 F	7 50	407	1.63	164	404	. 1		\dashv	中 220			
NNULAR MA	- 81	Calculated	Depth ²	(ft bls)		1	4			*	*		,					2						** <u></u>	62	1. 0.85			
MATED AN Project No.:		Total Vól.	of Bags	(ff ³)	T)												Ø				1	0			a	(X)			
EST	ľ	Volume	of Bag¹(v)	(作3)	Nessio.																				が	٥٠٠			
776 175	<u> </u>				1 1 1 1 1												20 × 20 × 20				i c	2 2 2 2				20			
Project Name: そく	-	>			+	+		\downarrow					\downarrow	1		- F							_	1	>	>			
roject	Well No.:	2			2										STATIS - OTTE	C.	200				1	2			الم) kg/	Notes:		



35.2





Plant:	Begin Loadin	ig:	To Job:	Arrive Job:	Start Unload:	Finish Unload:	Leav	e Job:	Return Plant:
007.441.03		mu j		policy of the	auranicultus	ank promes top	SEE Y	Fresh	(Samuel)
Customer Code:	Customer Name:	to a	PER INC		Cust	omer Job Number:	C C	order Code / Date:	18/15/1
Project Code:	Project Name:				Proje	ct P.O. Number:	C	order P.O. Number:	
Ticket Date:	Delivery Address:	HUNT	HIGHWAY		BATCH RECOR	DS TYPE	Мар	Page: Map/R	ow/Column:
Delivery Instructions:							Dispa	atcher:	
							Ticke	et Number:	
Due On Job;	Slump:	Truck	Number:	Driver Number:	Driver Name:	KENNETH	End Use:	BLDNG	DTHER
	UMULATIVE OR QUANTITY QUA	DERED ANTITY	MATERIAL CODE	distribution of the	PRODUCTION DESCRIPT	ION THE STATE OF T	UOM	UNIT PRICE	AMOUNT
			13/33/64	TYPE TI	OF THERY	SEN SIL	LIPS.	ino activistical	X (SAMOLIA)
					AND AMILIE				
6.4000				HENVIRON	TENTAL FRE				
1000			1575-891	EFERIGHT	NON ITO XARE	EUARIZONA am zono ever			
								4 de 0.0259	
								DEC 15 AM)	
ton day	A STATE OF S	in on the	10 May 10 1 10 1	ent ale trafacións	an shipeles have	(a./resch y/o cel	rispined e	Neggurid	Peligros
Cash Check	ck # / Auth Code:	Signature of I	Oriver Receiving Cas	h:		Cash Received:		Total COD Order Without Standby	Amount to Collect Charges:
Charge			Schright 1		Manufacture (Manufacture)	e premer nessun	zalnya z	d'agoilis	
Comments:					WATER ADDED	GAL GAL	YARDS	S IN DRUM:	NAME OF THE OWNER OWN
er in the su					1.46 to 1100 to 1.10 To 1.00 To	ivel de la exposi		ADDED.	
gger z vindire Mandar						DSSED AT OWNER	'S/AGENT	'S REQUEST:	SIGNATURE
			OF THOMSE OF		or second sol so	im jakka nem	ची कि छंड	Z zayloti.	auxilioxi
seather in a			ong tank si Makatanka		□ LOAD WAS TES	STED BY:	Zonienie Zien sie	Prometers	SIGNATURE
Company assumes no rems of sale and delive control after delivery, thing turned concrete. Buy	ery and accepts concre s Company will not acce	es inside cur te as is. Du ept any respo ms shall be o	b or property line. (ue to important facto	Customer agrees to the	SPECIAL TERMS: Any vis no longer guaranteed. may be hazardous to you safety handling information AUTHORIZED SIGNATUR	WARNING: Product may ir safety and health. Ple in, and to the material safet	cause skin ar	nd/or eye irritation. he backside of this	CAUTION: Materia

68UNIVERSAL

X

41 0 8 2 803 3451 LeTourneau Gillette, WY 82718

Cementing Ticket No. 1719

21371A

EN EN	ERGY SERVICES		30	7-682-52	258							Joh Co.	mpleted
oate 01-20-18	Customer Order No.		Sect.	Twp.	Range	1	alled Out 7:45	On Locat 8:	00 00	Job B	3:30	l l	15:30
	ance Coppe	er Mine		Contractor	Hydro	Res	ources		Charge '	To	Hydro	West	
Mailing Address				City					State				
Vell No. & Form	0-	04			Plac	e c	opper n	nine		County	Pin	al	State AZ
Depth of Well 1205	Depth of Job	Casing	New)	Size	5.5	— An	e of Hole nt. and Kind Cement	14	(l	ent Left	Request Necessity_	0 feet
Kind of Job	 Moni	toring		vveigin		Dri	llpipe	7/8	- 1	ary)	Truck No.	28	8983
		sa'	fety n	neeting	held								
Price Reference	4040	rig	up to	tubing	g with		and val	ve					
Price of Job			-		clear								
Second Stage _	3825				500		type 2/	5 cem	ent				
Pump Truck Mile	age				thru n		A11-1						
P.U. Mileage		_		in cel	tubing								
Other Charges _	= 000 00				o surfa	ace						*****	
Total Charges _	5,800.00	90	ou oc		IANK Y								
	Bryan Hamm	nond	Lead Vis				vt. 14	1.6	Lead Wa	ter	6.8	sv _	120
		n	Tail Yield			- Tail W			Lead Wa	iter		sv _	
Helper	Oom orana	Gillette								Wy			
District The above job w	as done under super												
(110 00010)== (•			Mari	Bure						
			e. Wasie Miles		ale protection and the second		singling agency and a line of	Venda in Golden Problem		Salatan day	Ą	gent of cont	ractor or operator
	State of the state			Sales	Ticket f	or Mat	erials Only	У					
QUANTITY SAC	CKS				ND TYPE				-	PRICE	500	1	8,000.00
16					<u>istanc</u>					7	150		1,800.00
12		Tr	anspo	ortator	of ce	ment	-		+		130		0.00
		<u> </u>							-				0.00
				- /					-				0.00
				O. # 1	52611								0.00
			г.	O. # 1	<u> </u>								0.00
		···				,			1				0.00
													0.00
													0.00
													0.00
													0.00
													0,00
Plugs													0.00
E	Equipment#	HRS				500	Handling & I	Dumping			2.44		1,220.00
	28983	1.5					Mileage)	0.00
	84127	1					Sub Total						16,820.00
							Discount		<u> </u>		· ·	<u> </u>	
	[1][]						Sales Tax						
Signature of one	erator / T						Total						

APPENDIX E

Geophysical Logs


	í					
X COL	Se	Southwest Exploration Services, LLC	StE	Cxploi	ation	
	bore	borehole geophysics & video services	ysics (¾ video s	ervices	î
	COMPANY	FLORENCE COPPER	OPPER			
	WELL ID	O-04				
	FIELD	FLORENCE COPPER	OPPER			
	COUNTY	PINAL		STATE	ARIZONA	
	TYPE OF I	TYPE OF LOGS: E-LOG	Ğ		OTHER SERVICES	/ICES
	MORE:	NAT.	NAT. GAMMA		TEMPERATURE	PER
	LOCATION				FLUID RESISTIVITY SONIC DEVIATION	STIVITY
	SEC	TWP	RGE			
PERMANENT DATUM			ELEVATION	,	K.B.	
LOG MEAS. FROM	GROUND LEVEL		ABOVE PERM. DATUM	JM	D.F.	
DRILLING MEAS. FROM GROUND LEVEL	GROUND LEVEI	[-			G.L.	
DATE	1-15-18		TYPE FLUI	TYPE FLUID IN HOLE	MUD	
RUN No	1 & 2		MUD WEIGHT	EIGHT	N/A	
TYPE LOG	E-LOG - N.	E-LOG - NAT. GAMMA	VISCOSITY	ITY	N/A	
DEPTH-DRILLER	1220 FT.		LEVEL		FULL	
DEPTH-LOGGER			MAX. REC. TEMP.	. TEMP.	26.76 DEG. C	
TOP LOGGED INTERVAL	SURFACE		SAMPLE INTERVAL	SAMPLE INTERVAL	0.2 FT.	
DRILLER / RIG#		HYDRO RESOURCES	LOGGING TRUCK	TRUCK	TRUCK #200	
RECORDED BY / Logging Eng.	Н	A. OLSON / D. BEAM	TOOL STRING/SN	ING/SN	MSI E-LOG 4	MSI E-LOG 40GRP SN 5019
WITNESSED BY	CHAD - H&A	ěΑ	LOG TIME	LOG TIME:ON SITE/OFF SITE	TE 6:45 A.M.	
RUN BOREHOLE RECORD	CORD		CASING RECORD	ECORD		
NO. BIT F	FROM	ТО	SIZE	WGT. FI	FROM	ТО
1 ? IN. S	SURFACE	40 FT.	14 IN.	STEEL SU	SURFACE	40 FT.
2 12 1/4 IN. 4	40 FT.	TOTAL DEPTH				
COMMENTS:			•	•		


Tool Summary:					
Date	1-15-18	Date	1-15-18	Date	1-15-18
Run No.	1	Run No.	2	Run No.	3
Tool Model	MSI COMBO TOOL	Tool Model	MSI E-LOG 40GRP	Tool Model	MSI 60MM SONIC
Tool SN	5543	Tool SN	5019	Tool SN	5050
From	SURFACE	From	SURFACE	From	SURFACE
То	1220 FT.	То	1220 FT.	То	1220 FT.
Recorded By	A. OLSON	Recorded By	A. OLSON	Recorded By	A. OLSON
Truck No	200	Truck No	200	Truck No	200
Operation Check	1-12-18	Operation Check	1-12-18	Operation Check	
Calibration Check	1-12-18	Calibration Check	1-12-18	Calibration Check	N/A
Time Logged	8:20 A.M.	Time Logged	9:30 A.M.	Time Logged	10:20 A.M.
Date	1-15-18	Date	-	Date	6
Date	1-15-18	Date		Date	
Run No.	4	Run No.	5	Run No.	6
Tool Model	MSI DEVIATION	Tool Model		Tool Model	
Tool SN	3082	Tool SN		Tool SN	
From	SURFACE	From		From	
<u>To</u>	1220 FT.				
Recorded By	A. OLSON	Recorded By		Recorded By	
Truck No	200	Truck No		Truck No	
Operation Check		Operation Check		Operation Check	
Calibration Check		Calibration Check		Calibration Check	
Time Logged		Time Logged		Time Logged	
Additional Comm	nents:				
Caliper Arms Use	d:15 IN	Calibr	ration Points: 8	N. & 23 IN.	
	- 44000 011				


|--|


Disclaimer:


All interpretations of log data are opinions based on inferences from electrical or other measurements. We do not guarantee the accuracy or correctness of any interpretations or recommendations and shall not be liable or responsible for any loss, costs, damages, or expenses incurred or sustained by anyone resulting from any interpretation made by any of our employees or agents. These interpretations are also subject to our general terms and conditions set out in our current Service Invoice.














Not Commo	1in:20π Denth	16" NRes
Nat. Gamma	Deptili	10 NRES

MSI 40GRP E-Log Tool

Probe Top = Depth Ref.

Tool SN: 5019, 5513, & 5514

Four Conductor MSI Probe Top

Bridle connects to wireline cablehead: Wireline armor is the B Electrode.

Bridle Electrode (N Electrode)

Probe Length = 1.98 m or 6.5 ft Bridle Length = 7.88 m or 25.86 ft

Probe Weight = 7.3 kg or 16.0 lbs

Can only be collected in fluid

Isolation Bridle

Temperature Rating: 70 Deg C (158 Deg F)

Presure Rating: 200 bar (2900 psi)

64" Normal Resistivity Electrode/Spontaneous Potential Electrode (M Electrode)

Electrode Measuring Points (from bottom of probe)

Spontaneous Potential (SP): 1.777 m or 5.81 ft

16" Normal Resistivity (16" NRes): 0.3548 m or 1.16 ft

64" Normal Resistivity (64" NRes): 0.9644 m or 3.16 ft

Single Point Resistance (SPR): 0.152 m or 0.50 ft

Natural Gamma Ray (Nat. Gamma): 0.73 m or 2.39 ft

Natural Gamma Ray

16" Normal Resistivity Electrode (M Electrode)

1.63" or 40 mm Diameter (41.4 mm with neoprene heat shrink and electrical tape)

MSI Gamma-Caliper-Temperature-Fluid Resistivity

Probe Top = Depth Ref.

Single Conductor MSI Probe Top

Probe Length = 2.59 m or 8.5 ft Probe Weight = 6.80 kg or 15.0 lbs

Natural Gamma and Caliper can only be collected logging up hole.

Fluid Temperature/Resistivity can only be collected logging down hole.

Temperature Rating: 70 Deg C (158 Deg F)

Presure Rating: 200 bar (2900 psi)

Natural Gamma Ray = 0.76 m (29.75 in)

NOTE: Lengths on a particular tool may vary from those listed on this document due to probe sizes and styles utilized

3-Arm Caliper = 1.44 m (56.75 in)

Distance from tool top: 2.20 m (86.5 in)

Available Arm Sizes: 3", 9", and 15"

1.375" or 34.9 mm Diameter



Company FLORENCE COPPER

Well O-04

Field FLORENCE COPPER

County PINAL State ARIZONA

Final

E-Log Summary


) 			ă 1
	Sei	Southwest Exploration Services, LLC	St E	xplor	ation	. 1965
	bore	borehole geophysics & video services	ysics 8	k video se	ervices	Ĩ
	COMPANY	FLORENCE COPPER	OPPER			
	WELL ID	O-04				
	FIELD	FLORENCE COPPER	OPPER			
	COUNTY	PINAL		STATE	ARIZONA	
	TYPE OF LOGS:		GAMMA - CALIPER	LIPER	OTHER SERVICES	/ICES
	MORE:	TEMI	TEMP. / FLUID RES.	D RES.	SONIC	
	LOCATION				DEVIATION	
	SEC	TWP	RGE			
PERMANENT DATUM			ELEVATION		K.B.	
LOG MEAS. FROM	GROUND LEVEL		ABOVE PERM. DATUM	M	D.F.	
DRILLING MEAS. FROM GROUND LEVEL	GROUND LEVE				G.L.	
DATE	1-15-18		TYPE FLUID IN HOLE	D IN HOLE	MUD	
RUN No	1		MUD WEIGHT	EIGHT	N/A	
TYPE LOG	GAMMA -	GAMMA - CALIPER - TFR	VISCOSITY	ITY	N/A	
DEPTH-LOGGER	1220 FT.		MAX. REC. TEMP.	TEMP.	26.76 DEG. C	
BTM LOGGED INTERVAL	λL 1220 FT.		IMAGE OR	IMAGE ORIENTED TO:	N/A	
TOP LOGGED INTERVAL	L SURFACE		SAMPLE INTERVAL	TERVAL	0.2 FT.	
DRILLER / RIG#	-	HYDRO RESOURCES	LOGGING TRUCK	TRUCK	TRUCK #200	
RECORDED BY / Logging Eng.		A. OLSON / D. BEAM	TOOL STRING/SN	NG/SN	MSI COMBO	MSI COMBO TOOL SN 5543
WITNESSED BY	CHAD - H&A	kΑ	LOG TIME	LOG TIME:ON SITE/OFF SITE	E 6:45 A.M.	
RUN BOREHOLE RECORD	ECORD		CASING RECORD	CORD		
NO. BIT	FROM	ТО	SIZE	WGT. FR	FROM	ТО
1 ? IN.	SURFACE	40 FT.	14 IN.	STEEL SU	SURFACE	40 FT.
2 12 1/4 IN. 3	40 FT.	TOTAL DEPTH				
COMMENTS:						


Tool Summary:					
Date	1-15-18	Date	1-15-18	Date	1-15-18
Run No.	1	Run No.	2	Run No.	3
Tool Model	MSI COMBO TOOL	Tool Model	MSI E-LOG 40GRP	Tool Model	MSI 60MM SONIC
Tool SN	5543	Tool SN	5019	Tool SN	5050
From	SURFACE	From	SURFACE	From	SURFACE
То	1220 FT.	То	1220 FT.	То	1220 FT.
Recorded By	A. OLSON	Recorded By	A. OLSON	Recorded By	A. OLSON
Truck No	200	Truck No	200	Truck No	200
Operation Check	1-12-18	Operation Check	1-12-18	Operation Check	1-12-18
Calibration Check	1-12-18	Calibration Check	1-12-18	Calibration Check	N/A
Time Logged	8:20 A.M.	Time Logged	9:30 A.M.	Time Logged	10:20 A.M.
Date	1-15-18	Date		Date	
Run No.	4	Run No.	5	Run No.	6
Tool Model	MSI DEVIATION	Tool Model		Tool Model	
Tool SN	3082	Tool SN		Tool SN	
From	SURFACE	From		From	
То	1220 FT.	То		То	
Recorded By	A. OLSON	Recorded By		Recorded By	
Truck No	200	Truck No		Truck No	
Operation Check	1-12-18	Operation Check		Operation Check	
Calibration Check	N/A	Calibration Check		Calibration Check	
Time Logged	12:00 P.M.	Time Logged		Time Logged	
Additional Comr Caliper Arms Use		Calibr	ration Points: 8	N. & 23 IN.	
<u> </u>	- ((000 0)				


E-Log Calibration Range:	1-1000 OHM-M	Calibration Points:	1 & 1000 OHM-M	


Disclaimer:


All interpretations of log data are opinions based on inferences from electrical or other measurements. We do not guarantee the accuracy or correctness of any interpretations or recommendations and shall not be liable or responsible for any loss, costs, damages, or expenses incurred or sustained by anyone resulting from any interpretation made by any of our employees or agents. These interpretations are also subject to our general terms and conditions set out in our current Service Invoice.














Probe Top = Depth Ref. **Single Conductor MSI Probe Top** Probe Length = 2.59 m or 8.5 ft Probe Weight = 6.80 kg or 15.0 lbs Natural Gamma and Caliper can only be collected logging up hole. Fluid Temperature/Resistivity can only be collected logging down hole. Temperature Rating: 70 Deg C (158 Deg F) Presure Rating: 200 bar (2900 psi) **Natural Gamma Ray = 0.76 m (29.75 in)** *NOTE: Lengths on a particular tool may vary from those listed on this document due to probe sizes and styles utilized* 3-Arm Caliper = 1.44 m (56.75 in) Distance from tool top: 2.20 m (86.5 in) Available Arm Sizes: 3", 9", and 15" TFR (Temperature/Fluid Resistivity) = 0.39 m (15.5 in) 1.375" or 34.9 mm Diameter



Company FLORENCE COPPER

Well O-04

Field FLORENCE COPPER

County PINAL State ARIZONA

Final

GCT Summary

- Trust	Sei	Southwest Exploration Services, LLC	st E , LL	xplor	ation	
	boreh	borehole geophysics & video services	ysics 8	k video se	ervices	ĺ
	COMPANY	FLORENCE COPPER	OPPER			
	WELL ID	O-04				
	FIELD	FLORENCE COPPER	OPPER			
	COUNTY	PINAL		STATE	ARIZONA	
	TYPE OF LOGS:		60mm SONIC		OTHER SERVICES	/ICES
	MORE:	GAMI	GAMMA - CALIPER	LIPER	TEMPERATURE	'RE
	LOCATION				FLUID RESISTIVITY DEVIATION	STIVITY
	SEC	TWP	RGE			
PERMANENT DATUM			ELEVATION		K.B.	
LOG MEAS. FROM	GROUND LEVEL		ABOVE PERM. DATUM	M	D.F.	
DRILLING MEAS. FROM GROUND LEVEL	GROUND LEVEI				G.L.	
DATE	1-15-18		TYPE FLUID IN HOLE	D IN HOLE	MUD	
RUN No	1 & 3		MUD WEIGHT	EIGHT	N/A	
TYPE LOG	SONIC - G	SONIC - GAMMA - CALIPER	VISCOSITY	ТҮ	N/A	
DEPTH-DRILLER	1220 FT.		MAX REC TEMP	TEMP	FULL 26.76 DEG C	
BTM LOGGED INTERVAL			IMAGE OR	IMAGE ORIENTED TO:	N/A	
TOP LOGGED INTERVAL			SAMPLE INTERVAL	NTERVAL	0.25 FT.	
DRILLER / RIG#	HYDRO RI	HYDRO RESOURCES	LOGGING TRUCK	TRUCK	TRUCK #200	
RECORDED BY / Logging Eng.	-	A. OLSON / D. BEAM	TOOL STRING/SN	NG/SN	MSI 60mm SC	MSI 60mm SONIC SN 5050
WITNESSED BY	CHAD - H&A	kA	LOG TIME	LOG TIME:ON SITE/OFF SITE	E 6:45 A.M.	
RUN BOREHOLE RECORD	CORD		CASING RECORD	CORD		
NO. BIT I	FROM	ТО	SIZE	WGT. FR	FROM	ТО
1 ? IN. S	SURFACE	40 FT.	14 IN.	STEEL SU	SURFACE	40 FT.
2 12 1/4 IN. 2	40 FT.	TOTAL DEPTH				
COMMENTS:						


Tool Summary:					
Date	1-15-18	Date	1-15-18	Date	1-15-18
Run No.	1	Run No.	2	Run No.	3
Tool Model	MSI COMBO TOOL	Tool Model	MSI E-LOG 40GRP	Tool Model	MSI 60MM SONIC
Tool SN	5543	Tool SN	5019	Tool SN	5050
From	SURFACE	From	SURFACE	From	SURFACE
То	1220 FT.	То	1220 FT.	То	1220 FT.
Recorded By	A. OLSON	Recorded By	A. OLSON	Recorded By	A. OLSON
Truck No	200	Truck No	200	Truck No	200
Operation Check	1-12-18	Operation Check	1-12-18	Operation Check	1-12-18
Calibration Check	1-12-18	Calibration Check	1-12-18	Calibration Check	N/A
Time Logged	8:20 A.M.	Time Logged	9:30 A.M.	Time Logged	10:20 A.M.
Date	1-15-18	Date		Date	
Run No.	4	Run No.	5	Run No.	6
Tool Model	MSI DEVIATION	Tool Model		Tool Model	
Tool SN	3082	Tool SN		Tool SN	
From	SURFACE	From		From	
То	1220 FT.	То		То	
Recorded By	A. OLSON	Recorded By		Recorded By	
Truck No	200	Truck No		Truck No	
Operation Check	1-12-18	Operation Check		Operation Check	
Calibration Check	N/A	Calibration Check		Calibration Check	
Time Logged	12:00 P.M.	Time Logged		Time Logged	
Additional Comr		Calibr	ration Points: 8	N. & 23 IN.	
	•·· <u> </u>				-


E-Log Calibration Range:	1-1000 OHM-M	Calibration Points:	1 & 1000 OHM-M


Disclaimer:


All interpretations of log data are opinions based on inferences from electrical or other measurements. We do not guarantee the accuracy or correctness of any interpretations or recommendations and shall not be liable or responsible for any loss, costs, damages, or expenses incurred or sustained by anyone resulting from any interpretation made by any of our employees or agents. These interpretations are also subject to our general terms and conditions set out in our current Service Invoice.


Nat. Gamma	Depth	RX1 - VDL			RX2 - VDL		
0 API 200	1in:20ft	100	uSec	1000	100	uSec	1000
3-Arm Caliper		RX1 - Travel Time			RX2 - Travel Time		
0 Inches 40		100	uSec	1000	100	uSec	1000
Delta T							
240 uSec/ft 40							
	20.0						
	60.0						
	80.0						
	100.0						
	120.0						
	140.0						











MSI 60 mm 2 RX Full Waveform Sonic Tool

Tool SN: 5001, 5050 & 6003

Probe Top = Depth Ref.

Four Conductor MSI Probe Top

Probe Length = 2.8 m or 9.19 ft
Probe Weight = ~26.5 kg or 58.4 lbs

Sensors: Ceramic Piezoelectric

Transmitter Frequency: 24 - 28 kHz resonant frequency

Rx - Rx Spacing: 0.3 m (12.0 in)

Typically centralized with external centralizers

Can only be collected in fluid

Temperature Rating: 80 Deg C (176 Deg F)

Presure Rating: 200 bar (2900 psi)

Rx-2 Tx - Rx2 Spacing = 1.22 m (48.0 in)

Rx-1 Tx - Rx1 Spacing = .91 m (36.0 in)

Acoustic Isolater

Tx = Acoustic Transmitter

MSI Gamma-Caliper-Temperature-Fluid Resistivity

Probe Top = Depth Ref.

Single Conductor MSI Probe Top

Probe Length = 2.59 m or 8.5 ft Probe Weight = 6.80 kg or 15.0 lbs

Natural Gamma and Caliper can only be collected logging up hole.

Fluid Temperature/Resistivity can only be collected logging down hole.

Temperature Rating: 70 Deg C (158 Deg F)

Presure Rating: 200 bar (2900 psi)

Natural Gamma Ray = 0.76 m (29.75 in)

NOTE: Lengths on a particular tool may vary from those listed on this document due to probe sizes and styles utilized

3-Arm Caliper = 1.44 m (56.75 in)

Distance from tool top: 2.20 m (86.5 in)

Available Arm Sizes: 3", 9", and 15"

TFR (Temperature/Fluid Resistivity) = 0.39 m (15.5 in)

1.375" or 34.9 mm Diameter



Company FLORENCE COPPER

Well O-04

Field FLORENCE COPPER

County PINAL State ARIZONA

Final

Sonic Summary

		E C		ĺ	Į.	
- Trut	Sei	Southwest Exploration Services, LLC	st E , LL	Coplor	ation	
	boreh	borehole geophysics & video services	ysics 8	ጷ video s	ervices	ú
	COMPANY	FLORENCE COPPER	OPPER			
	WELL ID	O-04				
	FIELD	FLORENCE COPPER	OPPER			
	COUNTY	PINAL		STATE	ARIZONA	
	TYPE OF I	TYPE OF LOGS: 3-ARM CALIPER	M CALI	PER	OTHER SERVICES	TCES
	MORE:	W/V	W / VOLUME CALC.	CALC.	SONIC	
	LOCATION				DEVIATION NAT. GAMMA TEMPERATURE	A RE
	SEC	TWP	RGE		FLOID RESISTIVITY	114111
PERMANENT DATUM			ELEVATION	,	K.B.	
LOG MEAS. FROM	GROUND LEVEL		ABOVE PERM. DATUM	JM	D.F.	
DRILLING MEAS. FROM GROUND LEVEL	GROUND LEVE	('			G.L.	
DATE	1-15-18		TYPE FLUID IN HOLE	D IN HOLE	MUD	
RUN No	1		MUD WEIGHT	EIGHT	N/A	
TYPE LOG	VOLUME	VOLUME CALCULATION	VISCOSITY	ITY	N/A	
DEPTH-DRILLER	1220 FT.		LEVEL		FULL	
DEPTH-LOGGER			MAX. REC. TEMP.	. TEMP.	26.76 DEG. C	
TOP LOGGED INTERVAL	SURFACE		SAMPLE INTERVAL	SAMPLE INTERVAL	0.2 FT.	
DRILLER / RIG#		HYDRO RESOURCES	LOGGING TRUCK	TRUCK	TRUCK #200	
RECORDED BY / Logging Eng.		A. OLSON / D. BEAM	TOOL STRING/SN	ING/SN	MSI COMBO	MSI COMBO TOOL SN 5543
WITNESSED BY	CHAD - H&A	kA	LOG TIME	LOG TIME:ON SITE/OFF SITE	TE 6:45 A.M.	
RUN BOREHOLE RECORD	CORD		CASING RECORD	ECORD		
NO. BIT I	FROM	ТО	SIZE	WGT. FF	FROM	ТО
1 ? IN.	SURFACE	40 FT.	14 IN.	STEEL SU	SURFACE	40 FT.
2 12 1/4 IN. 2	40 FT.	TOTAL DEPTH				
COMMENTS:			·			


Tool Summary:					
Date	1-15-18	Date	1-15-18	Date	1-15-18
Run No.	1	Run No.	2	Run No.	3
Tool Model	MSI COMBO TOOL	Tool Model	MSI E-LOG 40GRP	Tool Model	MSI 60MM SONIC
Tool SN	5543	Tool SN	5019	Tool SN	5050
From	SURFACE	From	SURFACE	From	SURFACE
То	1220 FT.	То	1220 FT.	То	1220 FT.
Recorded By	A. OLSON	Recorded By	A. OLSON	Recorded By	A. OLSON
Truck No	200	Truck No	200	Truck No	200
Operation Check	1-12-18	Operation Check	1-12-18	Operation Check	1-12-18
Calibration Check	1-12-18	Calibration Check	1-12-18	Calibration Check	N/A
Time Logged	8:20 A.M.	Time Logged	9:30 A.M.	Time Logged	10:20 A.M.
Date	1-15-18	Date	_	Date	_
					_
Run No. Tool Model	4 MSI DEVIATION	Run No. Tool Model	5	Run No. Tool Model	6
Tool SN	3082	Tool SN		Tool SN	
From	SURFACE	From		From	
To	1220 FT.	To		To	
Recorded By	A. OLSON	Recorded By		Recorded By	
Truck No	200	Truck No		Truck No	
Operation Check		Operation Check		Operation Check	
Calibration Check		Calibration Check		Calibration Check	
Time Logged		Time Logged		Time Logged	
Additional Comr				<u> 9</u>	1
Caliper Arms Use		Calibi	ration Points: 8 I	N. & 23 IN.	
=	u. 10 11 1.				-


E-Log Calibration Range:	1-1000 OHM-M	Calibration Points:	1 & 1000 OHM-M
		_	


Disclaimer:


All interpretations of log data are opinions based on inferences from electrical or other measurements. We do not guarantee the accuracy or correctness of any interpretations or recommendations and shall not be liable or responsible for any loss, costs, damages, or expenses incurred or sustained by anyone resulting from any interpretation made by any of our employees or agents. These interpretations are also subject to our general terms and conditions set out in our current Service Invoice.


Total Volume	Depth	3-Arm Caliper	Cumulated Volume (cu.yd)
0 cu.yd 47.34	1in:20ft	0 Inches 40	
3-D View			Decedes F.F. OD Oct
-0°			Based on 5.5" OD Casing
	0.0		
	20.0		
	40.0		
	60.0		46.47
	80.0		45.59
	100.0		44.67
	120.0		43.81
	140.0		42.90
	160.0		41.91











Probe Top = Depth Ref. **Single Conductor MSI Probe Top** Probe Length = 2.59 m or 8.5 ft Probe Weight = 6.80 kg or 15.0 lbs Natural Gamma and Caliper can only be collected logging up hole. Fluid Temperature/Resistivity can only be collected logging down hole. Temperature Rating: 70 Deg C (158 Deg F) Presure Rating: 200 bar (2900 psi) **Natural Gamma Ray = 0.76 m (29.75 in)** *NOTE: Lengths on a particular tool may vary from those listed on this document due to probe sizes and styles utilized* 3-Arm Caliper = 1.44 m (56.75 in) Distance from tool top: 2.20 m (86.5 in) Available Arm Sizes: 3", 9", and 15" TFR (Temperature/Fluid Resistivity) = 0.39 m (15.5 in) 1.375" or 34.9 mm Diameter



Company FLORENCE COPPER

Well O-04

Field FLORENCE COPPER

County PINAL State ARIZONA

Final

Caliper w / Volume Calculation Summary



Wellbore DRIFT Interpretation

PREPARED ESPECIALLY FOR FLORENCE COPPER O-04

Monday - January 15, 2018



This Wellbore Interpretation Package represents our best efforts to provide a correct interpretation. Nevertheless, since all interpretations are opinions based on inferences from electrical or other types of measurements, we cannot and do not guarantee the accuracy or correctness of any interpretation, and we shall not be liable or responsible for any loss, costs, damages, or expenses incurred or sustained by Customer resulting from any interpretation made by this document. We do not warrant or guarantee the accuracy of the data, specifically including (but without limitations) the accuracy of data transmitted by electronic process, and we will not be responsible for accidental or intentional interception of such data by third parties. Our employees are not empowered to change or otherwise modify the attached interpretation. Furthermore, along with Eagle Pro Software we do not warrant or guarantee the accuracy of the programming techniques employed to produce this document. By accepting this Interpretation Package, the Customer agrees to the foregoing, and to our General Terms and Conditions.

WELLBORE DRIFT INTERPRETATION

Southwest Exploration Services, LLC

Company:		FLO	RENCE COI	PPER	Well Owner					
County:		PINAL		State:	Arizona		Country:		USA	
Well Numbe	r:	O-04		Survey Date:	Monday - January 15,	2018	Magnetic Declinat	ion: Dec	clination Correction	n Not Used
Field:		FLORENCE	COPPER		Drift Calculation Metho	dology:	В	alanced Tangen	tial Method	
Location:										
Remarks:										
Witness:	CHAD- H&A	Vehicle No.:	200	Invoice No.:	Operator:	A. OLSON	Well Depth:	1220 Feet	Casing size:	12.25 Inches
Tool:		Compass - 3082		Lat.:	Long.:		Sec.:	Twp.:	Rae.:	

M	EASURED DA	TA			DA	TA COMPUTA	TIONS		
DEPTHS, feet	INCLINATIONS, degrees	AZIMUTHS, degrees	TVD, feet	T. LATITUDE, feet	T. LONGITUDE, feet	DOGLEG SEV., degrees per 20 Feet	DOGLEG SEV., degrees per 100 feet	DRIFT DIST., feet	DRIFT BGR. degrees
0	0.28	059.35	0.00						
20	0.37	353.37	19.99	0.089	0.035	1.00	3.69	0.10' (1.20")	021.20
40	0.35	050.68	39.98	0.192	0.075	0.41	3.25	0.21' (2.52")	021.30
60	0.07	272.19	59.97	0.231	0.110	0.96	6.33	0.26' (3.12")	025.50
80	0.03	107.54	79.96	0.230	0.103	0.84	6.71	0.25' (3.00")	024.10
100	0.14	310.73	99.96	0.244	0.089	0.42	6.63	0.26' (3.12")	020.10
120	0.30	002.30	119.95	0.312	0.073	0.13	2.94	0.32' (3.84")	013.10
140	0.06	114.99	139.94	0.360	0.085	0.43	5.63	0.37' (4.44")	013.20
160	0.21	299.67	159.93	0.374	0.063	0.83	6.76	0.38' (4.56")	009.50
180	0.28	311.51	179.92	0.425	-0.005	0.95	0.70	0.42' (5.04")	359.30
200	0.25	333.27	199.91	0.496	-0.061	0.37	1.28	0.50' (6.00'')	353.00
220	0.19	007.56	219.90	0.568	-0.076	1.00	2.00	0.57' (6.84")	352.40
240	0.32	346.35	239.89	0.655	-0.085	1.00	1.25	0.66' (7.92")	352.60
260	0.09	335.26	259.88	0.724	-0.105	0.34	0.65	0.73' (8.76")	351.80
280	0.14	336.94	279.87	0.761	-0.121	0.93	0.10	0.77' (9.24")	351.00
300	0.35	340.55	299.86	0.841	-0.151	0.78	0.21	0.85' (10.20'')	349.80
320	0.31	297.97	319.85	0.924	-0.219	0.53	2.46	0.95' (11.40'')	346.70
340	0.11	335.08	339.84	0.967	-0.275	0.00	2.15	1.01' (12.12")	344.10

Page No. 1 True Vertical Depth: 1219.41'

Final Drift Distance: 3.48' (41.76")

Final Drift Bearing: 62.60°

Note: Magnetic Declination is not used because it is not a factor in the calculation of well drift or alignment. Magnetic Declination is only important if attempting to hit a target or miss another well and then it is included in the calculations.

WELLBORE DRIFT INTERPRETATION Southwest Exploration Services, LLC (480) 926-4558

O-04

M	EASURED DA	ГА			DA	TA COMPUTA	TIONS		
DEPTHS, feet	INCLINATIONS, degrees	AZIMUTHS, degrees	TVD, feet	T. LATITUDE, feet	T. LONGITUDE, feet	DOGLEG SEV., degrees per 20 Feet	DOGLEG SEV., degrees per 100 feet	DRIFT DIST., feet	DRIFT BRG degrees
360	0.13°	306.83°	359.83	0.998	-0.301	0.56	1.65	1.04' (12.48'')	343.20
380	0.11°	321.09°	379.82	1.027	-0.331	0.73	0.84	1.08' (12.96")	342.10
400	0.21°	324.84°	399.81	1.072	-0.364	0.88	0.22	1.13' (13.56")	341.20
420	0.06°	280.78°	419.80	1.104	-0.395	0.20	2.54	1.17' (14.04'')	340.30
440	0.12°	339.25°	439.79	1.126	-0.413	0.97	3.31	1.20' (14.40'')	339.90
460	0.05°	293.08°	459.78	1.149	-0.428	0.96	2.65	1.23' (14.76")	339.60
480	0.14°	003.81°	479.77	1.177	-0.434	0.12	3.92	1.25' (15.00'')	339.70
500	0.11°	348.38°	499.76	1.220	-0.436	0.81	0.91	1.30' (15.60")	340.30
520	0.29°	009.48°	519.75	1.289	-0.432	0.59	1.24	1.36' (16.32")	341.50
540	0.22°	345.01°	539.74	1.376	-0.434	0.73	1.43	1.44' (17.28'')	342.50
560	0.10°	017.20°	559.73	1.430	-0.439	0.28	1.88	1.50' (18.00")	342.90
580	0.11°	203.98°	579.72	1.429	-0.442	0.77	6.76	1.50' (18.00")	342.80
600	0.05°	220.00°	599.71	1.405	-0.455	0.49	0.94	1.48' (17.76")	342.00
620	0.10°	093.04°	619.70	1.397	-0.443	0.69	6.06	1.47' (17.64")	342.40
640	0.08°	276.87°	639.69	1.398	-0.439	0.13	6.77	1.47' (17.64")	342.50
660	0.18°	051.79°	659.68	1.419	-0.428	0.83	6.25	1.48' (17.76")	343.20
680	0.04°	075.14°	679.67	1.440	-0.397	0.80	1.37	1.49' (17.88")	344.60
700	0.30°	094.37°	699.66	1.438	-0.338	0.25	1.13	1.48' (17.76")	346.80
720	0.19°	093.46°	719.65	1.432	-0.253	0.54	0.05	1.45' (17.40")	350.00
740	0.25°	040.80°	739.64	1.463	-0.191	0.24	3.00	1.48' (17.76")	352.50
760	0.11°	156.50°	759.63	1.478	-0.155	0.94	5.73	1.49' (17.88'')	354.00
780	0.23°	131.84°	779.62	1.434	-0.117	0.65	1.45	1.44' (17.28'')	355.30
800	0.22°	031.16°	799.61	1.440	-0.067	0.97	5.21	1.44' (17.28'')	357.30
820	0.00°	033.42°	819.60	1.473	-0.047	0.06	0.13	1.47' (17.64'')	358.20
840	0.37°	095.75°	839.59	1.467	0.017	0.29	3.50	1.47' (17.64'')	000.70
860	0.34°	122.15°	859.58	1.429	0.131	0.57	1.55	1.43' (17.16")	005.30
880	0.78°	145.64°	879.57	1.285	0.258	0.47	1.38	1.31' (15.72")	011.40
900	0.15°	043.39°	899.56	1.192	0.353	0.42	5.27	1.24' (14.88'')	016.50
920	0.53°	093.84°	919.55	1.205	0.463	0.69	2.88	1.29' (15.48'')	021.00
940	0.57°	056.29°	939.54	1.254	0.638	0.04	2.18	1.41' (16.92'')	027.00
960	0.42°	066.46°	959.53	1.338	0.788	0.30	0.60	1.55' (18.60'')	030.50
980	0.37°	089.04°	979.52	1.368	0.920	0.98	1.33	1.65' (19.80'')	033.90
1,000	0.22°	358.94°	999.52	1.407	0.984	0.95	4.79	1.72' (20.64")	035.00


Page No. 2 True Vertical Depth: 1219.41' Final Drift Distance: 3.48' (41.76") Final Drift Bearing: 62.60°

WELLBORE DRIFT INTERPRETATION Southwest Exploration Services, LLC (480) 926-4558

O-04

DEPTHS,						TA COMPUTA			
feet	INCLINATIONS, degrees	AZIMUTHS, degrees	TVD, feet	T. LATITUDE, feet	T. LONGITUDE, feet	DOGLEG SEV., degrees per 20 Feet	DOGLEG SEV., degrees per 100 feet	DRIFT DIST., feet	DRIFT BRG degrees
1,020	0.53°	087.23°	1,019.51	1.450	1.076	0.96	4.71	1.81' (21.72")	036.60
1,040	0.42°	066.69°	1,039.50	1.483	1.236	0.46	1.21	1.93' (23.16")	039.80
1,060	0.23°	120.64°	1,059.49	1.492	1.338	0.25	3.07	2.00' (24.00")	041.90
1,080	0.59°	114.26°	1,079.48	1.429	1.466	0.92	0.38	2.05' (24.60")	045.70
1,100	0.87°	073.92°	1,099.47	1.429	1.706	0.09	2.33	2.23' (26.76")	050.10
1,120	0.91°	087.20°	1,119.46	1.479	2.011	0.16	0.78	2.50' (30.00")	053.70
1,140	0.83°	063.57°	1,139.45	1.551	2.299	0.98	1.39	2.77' (33.24")	056.00
1,160	0.52°	111.33°	1,159.44	1.582	2.513	0.54	2.74	2.97' (35.64")	057.80
1,180	0.57°	094.76°	1,179.43	1.541	2.697	0.80	0.98	3.11' (37.32")	060.30
1,200	0.58°	054.88°	1,199.42	1.591	2.879	0.66	2.31	3.29' (39.48")	061.10
1,220	0.79°	110.54°	1,219.41	1.601	3.091	0.94	3.16	3.48' (41.76")	062.60


Page No. 3 True Vertical Depth: 1219.41' Final Drift Distance: 3.48' (41.76") Final Drift Bearing: 62.60°



3D PROJECTION VIEW - O-04

FLORENCE COPPER

346.0




Date of Survey: Monday - January 15, 2018

Balanced Tangential Calculation Method

Southwest Exploration Services, LLC (480) 926-4558


POLAR VIEW - O-04 FLORENCE COPPER




Date of Survey: Monday - January 15, 2018

Balanced Tangential Calculation Method

Southwest Exploration Services, LLC (480) 926-4558





borel	nole geoph	<u>ਨ</u> .	k video	serv	ices	
COMPANY WELL ID	FLORENCE C 0-04	OPPER				
WELL ID	O-04 FLORENCE C	OPPER				
OUNTY	PINAL		ST/		\RIZONA	
YPE OF I	LOGS: GAM	MA - CA	LIPER		OTHER SERVIC	ŒS
MORE:	TEMI	./FLUII	D COND	•	SONIC 4 PI DENSITY DUAL DENSITY	Y
SEC	TWP	RGE				
		ELEVATION		-	K.B.	
ROUND LEVEI		PERM. DATU	Ā		D.F.	
ROUND LEVEI	('				3.L.	
3-22-18		TYPE FLUI	D IN HOLE	I	ORMATION W	ATER
1		MUD W	EIGHT	7	V/A	
GAMMA -	CALIPER - TFR	VISCOS	TY	7	V/A	
1200 FT		LEVEL		,	-229 FT	
1191 FT		MAX. REC.	TEMP.	(1)	34.44 Deg C	
1191 FT		IMAGE OR	ENTED TO:		N/A	
SURFACE		SAMPLE IN	TERVAL).2 FT	
_	NEG / A DI SONI	TOOL STAL	NG/SN RUCK		IRUCK #/50	OOI ON 55/12
_	1&A	LOG TIME:	ON SITE/OF	_	7:30 AM	OCE SIA SOFS
		CASING DI	Con			
M	TO	SIZE	WGT.	FROM	T	ТО
SURFACE	40 FT	14"	STEEL	SURFA		500 FT
40 FT	500 FT	5"	FG	SURFA		500 FT
] 	TOTAL DEPTH	S	PVC	500 FT	Т	TOTAL DEPTH
	COMPANY WELL ID FIELD		DMPANY FLORENCE COPPER ELL ID O-04 ELL ID O-04 ELL ID O-04 ELT ID O-04 YPE OF LOGS: GAMMA - ORE: TEMP./FL CATION TWP ILEVAT DUND LEVEL ABOVE PERM. D SURPFACE SURFACE SURFACE SURFACE SURCES LOGGI M. QUINONES / A. OLSON TOOL S COLLIN - H&A TO SIZE ACE 100 FT 14" 500 FT 5" TOTAL DEPTH 5" TOTAL DEPTH 5"	DMPANY FLORENCE COPPER ELL ID O-04 ELL ID O-04 ELL ID O-04 ELT ID O-04 ELT ID O-04 ELT ID O-04 YPE OF LOGS: GAMMA - ORE: TEMP./FL CATION TWP I SUND LEVEL ABOVE PERM. D DUND LEVEL ABOVE PERM. D DUND LEVEL ABOVE PERM. D SUND LEVEL IN MU GAMMA - CALIPER - TFR VIS 1200 FT IN MAGE SURFACE SURFACE SAMPI HYDRO RESOURCES LOGGI M. QUINONES / A. OLSON TOOL S COLLIN - H&A IN GE ACE TOTAL DEPTH 5" TOTAL DEPTH 5" TOTAL DEPTH 5"	DORE: TWP STATE TYPE FLUID IN HOLE 1 1 1 1 3-22-18 1-1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	DOTE FLORENCE COPPER


	ω ω				
Tool Summary:					
Date	3-22-18	Date	3-22-18	Date	3-22-18
Run No.	1	Run No.	2	Run No.	3
Tool Model	MSI COMBO TOOL	Tool Model	ALT 4 RX SONIC	Tool Model	COMPROBE 4 PI
Tool SN	5543	Tool SN	4572	Tool SN	6009
From	SURFACE	From	238 FT	From	SURFACE
То	1191 FT	То	1191 FT	То	1191 FT
Recorded By	M. QUINONES	Recorded By	M. QUINONES	Recorded By	M. QUINONES
Truck No	750	Truck No	750	Truck No	750
Operation Check	3-22-18	Operation Check	3-22-18	Operation Check	3-22-18
Calibration Check	3-22-18	Calibration Check	N/A	Calibration Check	N/A
Time Logged	8:00 AM	Time Logged	8:35 AM	Time Logged	9:20 AM
				_	
Date	3-22-18	Date		Date	
Run No.	4	Run No.	5	Run No.	6
Tool Model	ALT QL DENSITY	Tool Model		Tool Model	
Tool SN	6187	Tool SN		Tool SN	
From	SURFACE	From		From	
То	1191 FT	То		То	
Recorded By	M. QUINONES	Recorded By		Recorded By	
Truck No	750	Truck No		Truck No	
Operation Check	3-22-18	Operation Check		Operation Check	
Calibration Check	3-22-18	Calibration Check		Calibration Check	
Time Logged	10:00 AM	Time Logged		Time Logged	
Additional Comr	ments:				
Caliper Arms Use	d: 9"	Calibr	ration Points: 4'	" & 12"	
		0-111-		1/4	


E-Log Calibration Range: N/A	Calibration Points: N/A	<u> </u>	

Disclaimer:

All interpretations of log data are opinions based on inferences from electrical or other measurements. We do not guarantee the accuracy or correctness of any interpretations or recommendations and shall not be liable or responsible for any loss, costs, damages, or expenses incurred or sustained by anyone resulting from any interpretation made by any of our employees or agents. These interpretations are also subject to our general terms and conditions set out in our current Service Invoice.

	Nat. Gamma		Depth		 3-Arm Caliper	
	API	200	1in:50ft	0	 Inches	 1(
F	Fluid Resistivit	у			Temperature	
	Ohm-m	20		20	Deg C	40
E			-0.0		1	
\leq						
麦	-					
3						
->			50.0			
4	3				3	
	?		100.0			
	2					
	\$					
1	1		150.0			
	\$		150.0			
	3					
			200.0			
-						
5						
	3		250.0			
-						
			300.0			
13			200.0			
	3					
	4		4- 0 -		5	
	\$		350.0			





Probe Top = Depth Ref. Single Conductor MSI Probe Top Probe Length = 2.59 m or 8.5 ft Probe Weight = 6.80 kg or 15.0 lbs Natural Gamma and Caliper can only be collected logging up hole. Fluid Temperature/Resistivity can only be collected logging down hole. Temperature Rating: 70 Deg C (158 Deg F) Presure Rating: 200 bar (2900 psi) Natural Gamma Ray = 0.76 m (29.75 in)

NOTE: Lengths on a particular tool may vary from those listed on this document due to probe sizes and styles utilized 3-Arm Caliper = 1.44 m (56.75 in) Distance from tool top: 2.20 m (86.5 in) Available Arm Sizes: 3", 9", and 15" TFR (Temperature/Fluid Resistivity) = 0.39 m (15.5 in) 1.375" or 34.9 mm Diameter



Company

FLORENCE COPPER

Well Field O-04 FLORENCE COPPER

County State PINAL ARIZONA

Final

GCT Summary



APPENDIX F

Cement Bond Log Summary

WELL O-04

Geophysical Log Summary

COMPANY: FLORENCE COPPER COMPANY

STATE: ARIZONA

FLORENCE COPPER SITE

WELL ID: O-04

FIELD:


COUNTY: **PINAL** Logging Engineer: VARIOUS


Date Logged: **VARIOUS** Processed By: K.M / B.C.


Date Processed: 07-17-18




















	Cased 3-22-18 Nat. Gamma			Open 1-15-18 RX1 - VDL (60mm)			Cased 3-22-18 RX1 - VDL			Cased 3-22-18 RX4 - VDL			Cased 3-22-18 Velocity Analysis			Cased 3-22-18 Near Density	
0	API	200	100	uSec	1000	100	uSec	1020	100	uSec	1020	40	us/ft	220	1	g/cc	
	Cased 3-22-18 3-Arm Caliper			Open 1-15-18 RX1 - TT (60mm)			Cased 3-22-18 RX1 - TT			Cased 3-22-18 RX4 - TT			Cased 3-22-18 P-Wave Slow			Cased 3-22-18 Far Density	
0	Inches	10	100	uSec	1000	100	uSec	1020	100	uSec	1020	40	us/ft	220	1	g/cc	
	Comp Density												Steel			4 Pi Density (Dry)	
	Cased 3-22-18											40	us/ft	220	,	Cased 3-22-18	
-1	g/cc	3											FRP		1200	CPS	
	Compensation											40	us/ft	220		4 Pi Density (Wet)	
	Cased 3-22-18												PVC			Cased 3-22-18	
-3	g/cc	1										40	us/ft	220	300	CPS	_
													Cement				


APPENDIX G SAPT Documentation

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY STANDARD ANNULAR PRESSURE TEST

Operator_FLORENC	CE COPPER, INC		State Per	mit No. P-101704
Address 1575 W	. HUNT HWY		USEPA 1	Permit No. R9UIC-AZ3-FY11-1
FLORE	NCE, AZ 85132		Date of T	
Well Name O-04				e ENV-MONITORING- Class III
LOCATION INFO	RMATION	SE Quarter of		uarter of the SW Quarter
of Section 28	; Range		nship 4S	
Company Represent	Status Gillery - North		1	
	Pressure transduc	er	Field Inspector LA	,
Type of Pressure Ga			psi full scale;	0.001 psi increments;
New Gauge? Yes	No 🗖 If no, date	of calibration	Calibration certi	fication submitted? Yes 🛮 No 🎷
TEST RESULTS Readings must be ta	ken at least avery 1	O minutes for	5-year or a	nnual test on time? Yes No
minimum of 30 min	utes for Class II, II	l and V wells and 60		A'd wells on time? Yes No
minutes for Class I v	wells.			After rework? Yes No
For Class II wells, an psig. For Class I we	nnulus pressue shoi	ald be at least 300	Nov	
greater of 300 psig of			New	'ly permitted well? Yes ♥ No □
injection pressure.				
Original chart record	lings must be subm	itted with this form.		
	Pressure ((in psig)		
Time	Annulus	Tubing	Casing size	5" - NOMINAL
17:31	167.34	same	Tubing size	
17:41	167.31	same	Packer type	INFLATABLE PACKER
17:51	167.55	same	Packer set (a	(i) 1.37(top), 479.70(bottom)
18:01	167.84	same	Top of Perm	nitted Injection Zone 430 feet
			Is packer 10	0 ft or less above top of
			Injection Zo	ne ? Yes 🗹 No 🔲
			If not, please	e submit a justification.
			Fluid return	(gal.)0.47
			Comments: Two tes	ts were conducted to confirm results, data
T4 D	N		for both	tests attached in the chart and table
Test Pressures:	Max. Allowable I	Pressure Change: Ini		
<i>II</i>		Те	st Period Pressure c	hange 0.5 psi
Test Passed	Test Failed			
If foiled to t	and the selection of the			
Corrective action	st be shut in, no inj	ection can occur, an	d USEPA must be o	contacted within 24 hours.
recommence.	us to occur, the we	ii retested, and writt	en authorization rec	eived before injection can
recommence,				

I certify under penalty of law that this document and all attachments are, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations. (See 40 CFR 144.32(d))

Tan Ream
Printed Name of Company Representative Signature of Company Representative Date



Well O-04 SAPT Data		
Transducer Serial Number:	554227	
Tranducer Model Number:	Level TROLL 400 non-vented 300 psi	
Date and Time	Pressure (PSI)	Corrected Pressure (PSI) (Sensor pressure - barometric pressure)
3/28/2018 16:46	148.345	134.44
3/28/2018 16:47	148.485	134.58
3/28/2018 16:48	148.554	134.65
3/28/2018 16:49	148.639	134.73
3/28/2018 16:50	148.745	134.84
3/28/2018 16:51	148.806	134.90
3/28/2018 16:52	148.929	135.02
3/28/2018 16:53	148.966	135.06
3/28/2018 16:54	149.01	135.10
3/28/2018 16:55	149.097	135.19
3/28/2018 16:56	149.212	135.31
3/28/2018 16:57	149.277	135.37
3/28/2018 16:58	149.35	135.44
3/28/2018 16:59	149.417	135.51
3/28/2018 17:00	149.487	135.58
3/28/2018 17:01	149.581	135.67
3/28/2018 17:02	149.7	135.79
3/28/2018 17:03	149.749	135.84
3/28/2018 17:04	149.818	135.91
3/28/2018 17:05	149.895	135.99
3/28/2018 17:06	149.945	136.04
3/28/2018 17:07	150.065	136.16
3/28/2018 17:08	150.153	136.25
3/28/2018 17:09	150.273	136.37
3/28/2018 17:10	150.271	136.36
3/28/2018 17:11	150.233	136.33
3/28/2018 17:12	150.437	136.53
3/28/2018 17:13	150.58	136.67
3/28/2018 17:14	150.488	136.58
3/28/2018 17:15	150.615	136.71
3/28/2018 17:16	150.763	136.86
3/28/2018 17:17	150.841	136.93
3/28/2018 17:18	150.773	136.87
3/28/2018 17:19	150.82	136.91
3/28/2018 17:20	14.747	0.84
3/28/2018 17:21	13.907	0.00
3/28/2018 17:31	181.245	167.34
3/28/2018 17:32	181.155	167.25
3/28/2018 17:33	181.128	167.22
3/28/2018 17:34	181.096	167.19
3/28/2018 17:35	181.122	167.22

Well O-04 SAPT Data		
Transducer Serial Number:	554227	
Tranducer Model Number:	Level TROLL 400 non-vented 300 psi	
Date and Time	Pressure (PSI)	Corrected Pressure (PSI) (Sensor pressure - barometric pressure)
3/28/2018 17:36	181.085	167.18
3/28/2018 17:37	181.152	167.25
3/28/2018 17:38	181.149	167.24
3/28/2018 17:39	181.165	167.26
3/28/2018 17:40	181.205	167.30
3/28/2018 17:41	181.219	167.31
3/28/2018 17:42	181.188	167.28
3/28/2018 17:43	181.219	167.31
3/28/2018 17:44	181.25	167.34
3/28/2018 17:45	181.289	167.38
3/28/2018 17:46	181.338	167.43
3/28/2018 17:47	181.35	167.44
3/28/2018 17:48	181.365	167.46
3/28/2018 17:49	181.417	167.51
3/28/2018 17:50	181.433	167.53
3/28/2018 17:51	181.457	167.55
3/28/2018 17:52	181.48	167.57
3/28/2018 17:53	181.515	167.61
3/28/2018 17:54	181.544	167.64
3/28/2018 17:55	181.548	167.64
3/28/2018 17:56	181.613	167.71
3/28/2018 17:57	181.604	167.70
3/28/2018 17:58	181.654	167.75
3/28/2018 17:59	181.697	167.79
3/28/2018 18:00	181.7	167.79
3/28/2018 18:01	181.746	167.84
3/28/2018 18:02	181.811	167.90
3/28/2018 18:03	13.96	0.05
3/28/2018 18:04	13.97	0.06

APPENDIX H

Well Development Field Forms

Project Name: FLI PTF	Project No.: 1296874507
Well No.: 0-04	Date: 2/27/18
Location: O-06 Florence, AZ	Measuring Point: D'Scharts
Total Depth of Well (ft bls): 1900	Screen Interval (ft bis): 500 - 1200
Pump Type/Setting (ft bls):	Activity: Aire Pundona Ariat
How Q Measured: Corre Stopwatch	H&A Personnel: S. Handel

750	(gpm)	Water Level (ft) 422	Capacity (gpm/ft)	Content (ppm)	4	(µmhos/cm)	°C	NTU		
750					4					
750		422		10	161					
	6.2			0.0	8.11	1309	17.45	710.2	to sella, 554 to trivia	3
1/c	5.3	422	-	0.0	8.18	1361	19.12	45.6	Cloudy	
	5.3	422		0,0	8.20	1386	19.71	24.7	. 11	
820	5.3	422		0.0	8,22	1400	20.01	19.4	II.	
835	5.3	422	~	0.0	8.24	1409	20.78	14.0	glar	
1010	5.6	617	-	0.1	8.01	1436	21.15	78.7	closes, aprilar at	4
1025	5.6	617	-	0.0	8.19	1420	21.56	(01.1	cloud	
1040	9.6	617	-	0.0	8.17	1424	21.83	51.1	el (
1055	9.6	617	1-	0.0	8.20	1437	22.48	31.8	N	
_	5.6	617	~	0.0	8,24	1441	22.60	17.2	year	
	8.3	910.	~	0.0	8.09	1453	22.63	57,7	cloudy, arrive 685	
	4.3	610	~	0.0	8.10	IMMY.	23.62	over	-de.4 / clouds	
1305	8.3	410	-	0.0	8.17	1449	23,94	11,2	weart	
1220 0	6.3	\$10	-	0,0	8.12	1451	23.90	8,77	IA	
	4.3	810	-	0.0	8.12	1451	24,09	6.74	N.	
1420	8-5	1805	-	6.2	7.77	1440	23.33	124	Brown arthre ats	N.
1440	8.5	1005	*	8.0	7.52	1422	22.90	54.2	Cloudy	
1455	8.5	1009	_	0.0	8.12	1408	22.84	14,2	Yerdr	
1510	8.5	1005	*	0.0	8,20	1407	23,09	10.7	Clear	
1525	8.5	1005	-	0.0	8.27	1416	23.53	8.05	dear	
1530			-	-	-	_	-	-	RIMPOSE	
1710			-	-	~	-	-	-	Pump on	
1715	7.9	1199	-	0.0	8.05	1338	20,93	19-5	clear, airline at so	In
1725	7.9	1199		5.0	8.60	1259	21.84	presona	e operative brown	
740	79	1199	-	5.2	8.02	1382	22.04	overande	opague brown	
1795	7,9	1199	-	0.5	8.20	1369	21.80	Iverrano	e brown	
1610	7.9	PPis	4	0.3	8.21	1361	21.48	399	brownytan	
1895	7.9	1199	-		8.33	1350	2134	153	tan	

Project Name: FCF PTF	Project No.: 129687-007
Well No.: ()=04	Date: 3/28/18 - 3/1/18
Location: flowers, AZ	Measuring Point: Discharge
Total Depth of Well (ft bis): 1700	Screen Interval (ft bis): Goo 1200
Pump Type/Setting (ft bls):	Activity: Aidist
How Q Measured: Cone / Stopwith	H&A Personnel: S. He ase I

Time	Discharge	Pumping	Specific	Sand	рН	Sp. Cond.	Temp.	Turbidity	Comments
	(g pm)	Water Level	Capacity	Content		(µmhos/cm)	°C	NTU	
	Spn	(ft)	(gpm/ft)	(ppm)	Winney.	A STATE OF			
725	8.9	1199	-	0.0	7.90	1272	17.27	22.9	cloudy
140	व.व	1199	***	1.1	4.20	1342	19.71	274	tan /bown
199	8.4	11,33	68	0.2	8.30	1389	2088	110	tan
10	8.3	1199	g _e	0.0	8.34	1370	2101	34.1	Cloudy
25	8.8	1119	*	0.0	8.32	1374	21.19	19.2	cilat
40	9.2	1199	4	0.5	6-34	1354	20.91	OVERBAN	borney, operant
55	7,2	1199		0.7	8.32	1410	22.83	Overrotas	e brown upagers
55	9.2	1199	-	1.0	8.33	14100	22.70	237	tan
25	9,2	1199	*	0.1	8.33	1402	27.69	119	ton/ clover
55	9,0	1199	**	0.5	8.22	1344	21.58	Or econoce	brewn, orphana
010	9.0	1199	jihn.	0.3	8.38	1408	23.03	331	tan
025	9,8	1199	4	0.0	8.38	1381	22,22	56.9	doudy
548	9,0	1299	-	0.0	8:37	1380	82.18	12.4	chearl
159	9,2	1149	~	0.3	8.34	1381	22.72	642	brems Han
15	3.2	1199	41.0	0.0	8.37	1387	22,54	83.6	(1000)
136	7,2	1149	-	0.0	8,35	1404	23.51	13.6	west.
40	-	-	-	~	_	-	-	-	PLMP ODS
940	-	-	~	-	-		-	212	Ampan
945	5.66	420 422	40	0.0	8.11	1345	12.11	292	tarlelova
000	5,66	422	-	0.0	8.82	1419	19.81	146	cloudy
020	9.66	422	~	0.0	8-24	1454	20.37	216	close
240	5,66	422	4	0.0	8.27	1473	20.75	151	Cloudy
630	5.66	493	-	0.0	8,29	1490	20.80	74,6,	double
115	5,66	422	1	0.6	8.29	1509	21,47	57.5	woody liker
120	-	-	-	-	-	-		-	Roy off
210	-		-	-	-	~	-	-	Pump or
	6.34	6t0 617	-	6.0	8.15	1519	21.74	69.0	double
240	6.34	640 617	-	0.0	8,20	(0,19	22,49	60.4	cloudy
210 220 240 mment	6.34	610 617	1 1			6.0 8.15	6.0 8.15 1519	0.0 8.15 1519 21.74	6.0 8.15 1519 21.74 69.0

HALEY

Project Name: FLI P7F	Project No.: 129 687 -607
Well No.: 0-64	Date: 3/1/18 - 3/2/18
Location: Florence, AZ	Measuring Point: Pischarak
Total Depth of Well (ft bls): \7.50	Screen Interval (ft bis): 500 1200
Pump Type/Setting (ft bls):	Activity: As Might
How Q Measured: Cont / Stopwatch	H&A Personnel: <

	1			Sand	рН	Sp. Cond.	Temp.	Turbidity	Comments
	(gpm)	Water Level	Capacity	Content		(µmhos/cm)	°C	NTU	
		(ft)	(gpm/ft)	(ppm)	A STATE OF THE STA				
1255	6.34	(010) (57	N	0.0	4,25	1519	22,69	50.4	Flores Elear
310	6.34	617617		0-0	8,30	1514	22.77	47.7	chear
330	6,34	to +0 617	-	0.0	8.28	15(1)	2a.97	46.2	Urn
1349	6.34	610 Ce 17	-	6-0	8:28	1509	23.66	3413	CHON
1350	-	-	-	-		1	1	~	Tump off
450	-	_	-	-	-	1	-	_	Pumpon
455	7,90	810	-	0.0	8.19	1515	23.38	48.0	clear
510	7.20	810	12	0.0	9.19	1200	23.42	39.7	Gear
530	7.90	810	~	0,0	4.22	1493	23.89	2410	Clear
545	7.90	BID	-	0.0	8,25	1493	23.86	21.0	Llear
600	7,90	810	~	6.0	8,23	1441	23.81	18.9	Clear
605		-	~	~	-	~	~	-	RMP 054
640	-	-	~	-	-	-	~	-	Pump on
645	8.32	1005	-	0.0	8.23	1466	23,21	14.0	Wear
700	4.32	1005	7	0.0	9,24	1562	33,22	135	douby
719	4.32	1005	*	0.0	3.22	1450	23,29	14.8	Clear
730	8.32	1005	5-	0.0	8.22	1435	23.11	11.6	Wear
745	8.32	100%		0.0	8.24	1431	23.27	8.18	Clear
799	~	-	-	-	~	-	-	-	Rimpost
755	~	-	-	~	-	-	-	-	Pundan
800	8.67	1179	-	0.0	7.87	1240	17.87	48.5	cloudy
820	8.27	1199	- 0,	200	8.19	1419	21,44	735	Brown Popague
\$35	8,67	1199		0.0	8.19	1374	21.95	70.3	cloudy
350	4.67	1199	-	0.0	8.26	1371	22.86	30.7	clear
715	8,67	1199	600	0.0	8,23	1372	23,08	11.7	clear.
934	9.87	1199	-	0.5	8.12	1357	23.07	overune	brown botique
005	9187	1149	-	0.0	8,26	1381	23.5	17.3	clear
1040		1199	-	0.0	4.24	1348	23.8	6.20	- Clear
ommen	ts:							5.19	

3/1/18

Project Name: FCF PTF	Project No.: 129687-007	
Well No.: 0-04	Date: 3/8/18.	
Location: Florence, AZ	Measuring Point: Discharge	
Total Depth of Well (ft bls): \ 200	Screen Interval (ft bis): 500 - 1200	
Pump Type/Setting (ft bls):	Activity: Althirt	
How Q Measured: Cone / Stopwartch	H&A Personnel: 5 Hensel	

Time	Discharge (gpm)	Pumping Water Level (ft)	Specific Capacity (gpm/ft)	Sand Content (ppm)	pН	Sp. Cond. (µmhos/cm)	Temp.	Turbidity NTU	Comments	
1100	9.70	1149	(951111)	03	4.25	1379	23.70	947	chear bran /opaque	
120	\$.70	1799	~	0.0	4.32	1344	23.84	27.2	(ican	
1140	9,00	1199	-	0.0	4.23	1388	23.94	5.19	Chear	
1205	9,75	1199	~	0.0	8-23	1387	24.02	191	Cloudy	
1270	9:43	1199	~	0.0	8.26	1396	25,35	21.3	il park	
1234	9.79	1199	~	0.0	8.29	1340	24,37	13.4	clear	
1255	9.75	1139	~	0.0	8.25	1394	24.46	5.86	theort.	200
1300	-	(1)	-	-	-	0	-	-	Pump off, end airlist	1966
_			DTW							
Sex	- puo	at 1164	4							Totalize
1435	Start		Total		4735					
1436	~60	1164	219	<0.1	706	2430	22.37		Brown, St. cloudy	
1450	~60	1164	-	<0.1	7.53	2311	75.16	13.7	Clear	474300
1505	~60	1164	-	0.0	7.58	7284	25.15	11.5	VI.	475306
1520	~60	1164	255.8	0.0	7.57	2279	25.29	5.78	4.	467100
1535	~60	1164	256.0	0.0	7.65	2260	75.08	3.55		477006
1540	PUMP								(A)	
1605	-		770.6							
1606	PUMP			-						
1607		1164	251.4	(0,1	7.60	2246	74.60	3.79	Clear	
1620	~60	1164	254.7	0.0	7.70	2762	25.23	3.61	ii .	4779a
1635	~ 60	1164	255.9	0.0	7.62		25.14	4.38	11	478700
1638	PUMP	OFF -								47890
1707			220.8							
1708	Pump	ON -								
1709		1164	255 249	7 0.0		2705	54.54	6.41	lear	
1720	~60	1164	254.4	0.0	7.68		25.09	7-03	it	47970
1735	~60	1164	255.8	0.0	7.65	2730	75.10	5.07	H	480 500
1739 Comment		OFF					4			480700
mmeni	S:									

3-3-18

	-		
Page	7	of_	

Project Name: FLT PTC	Project No.: 129 (447-407	
Well No.: 0 -04	Date: 3/4/13	
Location: Florale, Az	Measuring Point: Spicket	
Total Depth of Well (ft bls): 120 0	Screen Interval (ft bls): 500 - 1200	
Pump Type/Setting (ft bls): givatos elietric	Activity: Pumping	
How Q Measured: totalizer	H&A Personnel: 5 Hensel	

277	Discharge	Pumping	Specific	Sand	pН	Sp. Cond.	Temp.	Turbidity	Comm	nents (bgs)
	(gpm)	Water Level	Capacity	Content		(µmhos/cm)	°C	NTU		
715	-	(ft)	(gpm/ft)	(ppm)		-			0	DTw.
0770	al	111		. ()	4	0	c0 01	79 in 100	Furp un	2110.25
	-	1104	~	0.0	8.12	2011	20,86	73.7	Cloudy	1216,25
0725	-	-	_		-	-	-	-	Rimpods	
5740	66	11.1	_	-			-	-	Pumpen	-
745		1164	-	0.0	7.45	2058	21.44	6.68	clear	251.05
200	66	1164	_	0.0	7.44	2161	23,94	3.24	char	252,25
1815	(260	1164	-	0.0	7,46	2184	23.78	2.07	Clean	25285
1820	-		~		-	-	**	-	Prop Je	262.93
0835	0.1	11.11	-	-	w 4.60	1 - 7 -	-	- 1	Pumpan	218.75
3840	Ç4	1144		0.0	7,43	2226	18.36	2.13	cierr	273222
0960	69	11604	4-	0.0	7,46	2157	24.05	3.64	cheur	291.25
2915	Cets	1164	-	0.0				2.23	clear	251.95
1920	-	-	-	-	-	-	-	1-	Propose	251,60
025	~		-	-	-	-	L	-	Pumbon	212.35
030	to.	900	-	0.0	7.66	2107	23,34	24.4	dear	213.20
100	63	900	-	0.0	7.48	2176	24.87	7.33	clear	245,15
1115	63	900	~	0,0	7,54	2172	24.81	9,97	ilear	245.50
120	1	,-	+	1	-	~	-	,	Plmp off	245.82
135	-	-	4	-	-	-	-	-	Pumper	214.20
140	70	900		0.0	7.51	2128	23,68	8.03	Ment	216.20
1200	70	960	-	0,0	7.58	2162	24.87	9.32	Hear	245.75
1220	70	900	-	6.0	7.53	2656	22,26	5.59	dear.	047.07
225	~	-	-	-	-	-	-	*	PUMP OFF	249 95
250	-	-	_	lam	-	-		-	Pumpon	213.75
255	75	900	~	0.0	7.59	2127	24.06	5.19	clear	214, 29
310	75	COP	-	0.0	7.54	2132	24.25	9,55	clear	244-15
325	75	900		0.0	7.55	3158	24.84	4.99	clear	245.80
330	but.	-	-	-	-	-	-	-	PUMP OSS	246.00

ALDRICH

PUMPING TEST/DEVELOPMENT FIELD DATA LOG

Project Name: FCI PTF	Project No.: 129687-007	
Well No.: 0 - 04	Date: 3/4/18	
Location: Florence, AZ	Measuring Point: Souther	
Total Depth of Well (ft bls): しゅう	Screen Interval (ft bls): 506-1709	
Pump Setting (ft bls): Van by	Pump Type: gauses electric	
How Q Measured: Lone / Strongworth total	alizer Personnel: 5 Hersel	

Time	Discharge (gpm)	Pumping Water Level	Specific Capacity	Sand Content	рН	Sp. Cond. (mmhos/cm)	Temp.	(Comments いてい)	(695)
		(ft)	(gpm/ft)	(ml/L)					whichly	DTW.
1350	-	-	~	-	-	-	-	Pur DA	8.08	214.85
1355	68	100	^	0.0	7.53	2127	24,35	year)	8.08	216,20
1410	66	900	-	0.0	7.55	2153	24.94	clear	4.27	246.05
1430	64	900	-	0.0	7.52	2118	24.11	Clear		246.29
1450	68	900	-	0.0	7.54	2193	25.05	clear	2.52	247.09
1455	~	-	-		-	-	1	Pump off	-	248.20
1555	-	1	-	,	~	-	^	RMPON	-	213.15
1600	69	600	~	6.0	7.53	2237	23.82	clear	10.7	214.75
1615	69	600	~	0.0	7.55	2134	24.60	Cheer	2.96	245.65
1635	69	600	-	0.0	7.58	2127	24.59	Chear	3.63	2416.65
1640	~	_	-	-	-	^	-	Pump Sof	-	246.90
+ Jell 5	_	-	-	-	-	-	-	Pump on	-	214.65
1700	68	600	de	0.0	7.58	2070	23,80	Crear	4.85	216.75
1720	68	600	-	0.0	7.59	2127	24.63	Clear	3.56	235.79
1740	69	600	-	0.0	8.04	2301	20.79	Wear	4,71	247.09
1745		-	~	-	-	-	-	PUMPOSA	~	247.35
0700	-	-	-	-	-	-	_	Pumpan	-	20.65
0705	60	(000	-	0.0	7.63	1123	19:33	clear	393	212.09
0725	60	600	~	0,0	7.69	1298	23,49	thear	3,37	244.95
0745	00	600	4	0.0	7,77	1315	23.90	clear	4.96	245.86
0805	60	600	-	0.0	7.74	1317	23.66	Clear	3.82	247.05
0410	-	-	-	-	-	-	-	Pump 88	-	247.35
6829		-	-	-	-	4	-	Prop on	-	214.69
0430	66	600	-	0.0	7.77	1305	23.28	Char	3.86	217.25
0845		600	W.	0-0	7.71	1336	24.13	year	2.24	217,50
0900	60	600	-	0.0	7.72	1333	24,34	dear	2.61	245,99
0915	66	600	-	0-0	7.71	1338	24.42	clear	2.32	247,25
0920	-	-	-	-	-	-	-	Pump off	-	1247.50

	7		
Page		of	

PUMPING TEST/DEVELOPMENT FIELD DATA LOG

Project Name: FCI PTF	Project No.: 129687 -007
Well No.: 0 -04	Date: 3/5/18
Location: Florence, AZ	Measuring Point: 50 cket
Total Depth of Well (ft bls): 17-00	Screen Interval (ft bis): 500 - 1200
Pump Setting (ft bls): Various	Pump Type: & lowers electric
How Q Measured: 600 Totalizer	Personnel: S. Hensel

Totali		comments		Temp.	Sp. Cond.	рН	Sand	Specific	Pumping	Discharge	Time
	n= .	- 1.11		°F	(mmhos/cm)		Content	Capacity	Water Level	(gpm)	
3122	DTW.	Turbidity	D	- 2			(ml/L)	(gpm/ft)	(ft)		
Cia	19.99		Emp on		17.	-7.70		-	,	-	1950
5123	120.50 48.6		dear	23.19	1316	8. otto	0.0	~	600	72	0955
2151	48.6		Clear	24.99	1356	7.80	0.0	^	600	72	\$ 9 15
7131	47.65		chear	23.54	1343	7.30	6.0	~	(000)	77	1035
515	47.95	-	Pump off	L-'	^		1	-	~	-	1040
31720	216.75	7 113	RMPOA	-		7.68	_	-	- 1/2	-	1055
51530	118.90	P .	Cleur	24.33	1370	8-29	0.0	2-	600	73	1100
166	147,25	3.25	Chear	25.00	1357	7.81	0.0	~	600	73	1126
51800	149.35	2.38	Deer	25.19	1360	7.79	0.0	*	Lebo	73	140
1810	250-05	~	Plup off	_	-		-	-	17		1145
									Pumping	End	
									/		
					81						
			-1								
	*										
										100	
					(a)						
						-				1	
										l Comments:	Additional
										I Comments:	tional

APPENDIX I

Well Video Log and Gyroscopic Survey Reports



Southwest Exploration Services, LLC

25811 S. Arizona Avenue Chandler, AZ. 85248

Phone: (480) 926-4558 Fax: (480) 926-4579 Web: www.swexp.com


Client: Florence Copper		Survey Date: March 21, 2018
Address: 1575 West Hunt Hwy		Invoice: Run: 1
	State: AZ Zip: 85132	
	P.O.:	
Copy To:		Camera:
B		Zero Datum: Top of Casing
Location:		
Field: Florence Copper Project		Type Perfs: Horizontal Slots
1st Csg.O.D. <u>5 In.</u> Csg Weight: From: <u>0 ft.</u>	To: 1195 ft.	2nd Csg.O.DCsg Weight:From:To:
Standing Water Level: 230 ft. Pumping Water Level:	Pump Depth:O.D.Ref.	.: Measured Casing Buildup: None
Operator: D. Beam Lat.:	Long.:	Sec:Twp:Rge:
Other Information: True Dep Wellbore Snapshots (SideScan-		WELLBORE / CASING INFORMATION
0 Ft (See Other Side) 92.1 Ft (See Other Side) 0.	Survey started at the top	of the case.
Su EXPLOSITION FLORENCE COPPER HERE TO THE POPER COPPER	Seam above static water	· level.
1.0.0-8 1 83/21/2018	Static water level observe	ed.
500.1	Transition piece observed	d.
230.1 Ft (See Other Side) 500.1 Ft (See Other Side) 503.	First perforations observe	ed.
723.1	Down view of the casing.	
743.1	View of perforations.	
503 Ft (See Other Side) 723.1 Ft (See Other Side) 850.1	Another view of the perfo	prations.
951	Perforations appear to be	e clear.
1,150.	Perforations near the bot	ttom of the casing.
1,195.	Bottom of the casing obs	served, survey ended.
743.1 Ft (See Other Side) 850.1 Ft (See Other Side)		
951 Ft (See Other Side) 1150.1 Ft (See Other Side)		
51: SE SE		
1195.1 Ft (See Other Side)		
HR II		
Notes:		
Page Number: 1		

11 WELLBORE SHAPSHOTS

0 Ft (Enlargement)



92.1 Ft (Enlargement)



230.1 Ft (Enlargement)




500.1 Ft (Enlargement)



503 Ft (Enlargement)



723.1 Ft (Enlargement)




743.1 Ft (Enlargement)



850.1 Ft (Enlargement)



951 Ft (Enlargement)



1150.1 Ft (Enlargement)



1195.1 Ft (Enlargement)



O-04 Page No. 2



Wellbore DRIFT Interpretation

PREPARED ESPECIALLY FOR

Florence Copper and Florence Copper

O-04

Wednesday - March 21, 2018



This Wellbore Interpretation Package represents our best efforts to provide a correct interpretation. Nevertheless, since all interpretations are opinions based on inferences from electrical or other types of measurements, we cannot and do not guarantee the accuracy or correctness of any interpretation, and we shall not be liable or responsible for any loss, costs, damages, or expenses incurred or sustained by Customer resulting from any interpretation made by this document. We do not warrant or guarantee the accuracy of the data, specifically including (but without limitations) the accuracy of data transmitted by electronic process, and we will not be responsible for accidental or intentional interception of such data by third parties. Our employees are not empowered to change or otherwise modify the attached interpretation. Furthermore, along with Eagle Pro Software we do not warrant or quarantee the accuracy of the programming techniques employed to produce this document. By accepting this Interpretation Package, the Customer agrees to the foregoing, and to our General Terms and Conditions.

WELLBORE DRIFT INTERPRETATION

Southwest Exploration Services, LLC $_{(480)}$ $_{926-4558}$

	Pinal State: O-04 Survey Date: Florence Copper Project	er .	Well Owner:	Florence Copper		
County:	Pinal	State:	Arizona	Country:	United States	
Well Number:	O-04	Survey Date:	Wednesday - March 21, 2018	Magnetic Declination:	Declination Correction Not Used	
Field:	Florence Copper Project		Drift Calculation Methodology:	Balanced	Tangential Method	

Remarks:

Location:

Witness: H&A Vehicle No.: 800 Invoice No.: Operator: K. MITCHELL Well Depth: 1220 Fe

ell Depth: 1220 Feet Casing size:

5 Inches

Tool: Gyro - 1422 Lat.: Long.: Sec.: Twp.: Rge.:

M	EASURED DA	TA			DA	ATA COMPUTATIONS				
DEPTHS, feet	INCLINATIONS, degrees	AZIMUTHS, degrees	TVD, feet	T. LATITUDE, feet	T. LONGITUDE, feet	DOGLEG SEV., degrees per 20 Feet	DOGLEG SEV., degrees per 100 feet	DRIFT DIST., feet	DRIFT BGR., degrees	
0	0.22	310.40	0.00							
20	0.16	357.69	19.99	0.053	-0.030	1.00	3.57	0.06' (.72")	330.10	
40	0.31	064.61	39.98	0.104	0.018	0.41	4.90	0.11' (1.32")	009.70	
60	0.46	067.66	59.97	0.158	0.141	0.96	0.24	0.21' (2.52'')	041.80	
80	0.45	047.16	79.96	0.242	0.273	0.84	1.58	0.36' (4.32'')	048.40	
100	0.43	030.34	99.96	0.360	0.368	0.42	1.30	0.52' (6.24")	045.70	
120	0.41	020.16	119.95	0.492	0.431	0.13	0.79	0.65' (7.80'')	041.20	
140	0.47	013.49	139.94	0.639	0.475	0.43	0.52	0.80' (9.60'')	036.60	
160	0.46	352.01	159.93	0.798	0.483	0.83	1.66	0.93' (11.16")	031.20	
180	0.48	049.32	179.92	0.932	0.535	0.95	4.26	1.07' (12.84'')	029.90	
200	0.47	348.08	199.91	1.067	0.582	0.37	4.53	1.22' (14.64'')	028.60	
220	0.42	009.12	219.90	1.220	0.577	1.00	1.62	1.35' (16.20'')	025.30	
240	0.41	035.18	239.89	1.351	0.630	1.00	2.00	1.49' (17.88'')	025.00	
260	0.46	053.58	259.88	1.457	0.736	0.34	1.42	1.63' (19.56'')	026.80	
280	0.35	095.28	279.87	1.499	0.861	0.93	3.16	1.73' (20.76")	029.90	
300	0.23	344.15	299.86	1.532	0.911	0.78	7.33	1.78' (21.36")	030.70	
320	0.17	127.12	319.85	1.553	0.924	0.53	8.43	1.81' (21.72'')	030.70	
340	0.15	154.31	339.84	1.512	0.959	0.00	2.09	1.79' (21.48'')	032.40	

Page No. 1 True Vertical Depth: 1195.21' Final Drift Distance: 5.16' (61.92") Final Drift Bearing: 90.60°

Note: Magnetic Declination is not used because it is not a factor in the calculation of well drift or alignment. Magnetic Declination is only important if attempting to hit a target or miss another well and then it is included in the calculations.

WELLBORE DRIFT INTERPRETATION

Southwest Exploration Services, LLC

O-04

M	EASURED DA	TA			DA	TA COMPUTA	TIONS		
DEPTHS, feet	INCLINATIONS, degrees	AZIMUTHS, degrees	TVD, feet	T. LATITUDE, feet	T. LONGITUDE, feet	DOGLEG SEV., degrees per 20 Feet	DOGLEG SEV., degrees per 100 feet	DRIFT DIST., feet	DRIFT BRG. degrees
360	0.16°	179.48°	359.83	1.460	0.971	0.56	1.94	1.75' (21.00'')	033.60
380	0.15°	191.82°	379.82	1.406	0.966	0.73	0.96	1.71' (20.52'')	034.50
400	0.37°	177.43°	399.81	1.316	0.964	0.88	1.11	1.63' (19.56'')	036.20
420	0.41°	185.28°	419.80	1.180	0.960	0.20	0.61	1.52' (18.24")	039.10
440	0.35°	167.86°	439.79	1.049	0.966	0.97	1.35	1.43' (17.16'')	042.60
460	0.32°	194.95°	459.78	0.935	0.964	0.96	2.08	1.34' (16.08'')	045.90
480	0.18°	127.54°	479.77	0.862	0.975	0.12	4.93	1.30' (15.60'')	048.50
500	0.39°	123.64°	499.76	0.805	1.057	0.81	0.30	1.33' (15.96'')	052.70
520	0.54°	098.78°	519.75	0.753	1.207	0.59	1.91	1.42' (17.04'')	058.00
540	0.64°	112.57°	539.74	0.696	1.403	0.73	1.07	1.57' (18.84'')	063.60
560	0.29°	108.44°	559.73	0.637	1.554	0.28	0.32	1.68' (20.16'')	067.70
580	0.52°	080.53°	579.72	0.636	1.692	0.77	2.14	1.81' (21.72'')	069.40
600	0.30°	065.46°	599.71	0.673	1.829	0.49	1.17	1.95' (23.40'')	069.80
620	0.36°	036.53°	619.70	0.745	1.914	0.69	2.22	2.05' (24.60")	068.70
640	0.41°	013.70°	639.69	0.865	1.968	0.13	1.76	2.15' (25.80'')	066.30
660	0.35°	032.19°	659.68	0.986	2.017	0.83	1.43	2.25' (27.00")	063.90
680	0.24°	345.52°	679.67	1.078	2.039	0.80	3.52	2.31' (27.72")	062.10
700	0.09°	081.23°	699.66	1.121	2.044	0.25	6.59	2.33' (27.96")	061.30
720	0.22°	324.60°	719.65	1.155	2.037	0.54	7.57	2.34' (28.08'')	060.50
740	0.32°	197.70°	739.64	1.133	1.998	0.24	7.95	2.30' (27.60")	060.40
760	0.41°	215.85°	759.63	1.022	1.939	0.94	1.40	2.19' (26.28'')	062.20
780	0.58°	158.09°	779.62	0.870	1.935	0.65	4.29	2.12' (25.44'')	065.80
800	0.53°	135.37°	799.61	0.710	2.038	0.97	1.75	2.16' (25.92'')	070.80
820	0.72°	107.83°	819.60	0.606	2.223	0.06	2.12	2.30' (27.60")	074.80
840	0.43°	102.49°	839.59	0.551	2.416	0.29	0.41	2.48' (29.76")	077.10
860	0.47°	083.82°	859.58	0.544	2.571	0.57	1.44	2.63' (31.56")	078.10
880	0.31°	228.41°	879.57	0.517	2.612	0.47	8.47	2.66' (31.92'')	078.80
900	0.27°	109.61°	899.56	0.465	2.616	0.42	7.65	2.66' (31.92'')	079.90
920	0.23°	158.76°	919.55	0.412	2.675	0.69	3.70	2.71' (32.52'')	081.20
940	0.52°	139.21°	939.54	0.306	2.749	0.04	1.51	2.77' (33.24")	083.70
960	0.77°	116.70°	959.53	0.177	2.928	0.30	1.74	2.93' (35.16")	086.50
980	0.56°	093.28°	979.52	0.111	3.146	0.98	1.80	3.15' (37.80")	088.00
1,000	0.59°	081.45°	999.52	0.121	3.345	0.95	0.92	3.35' (40.20")	087.90


Page No. 2 True Vertical Depth: 1195.21' Final Drift Distance: 5.16' (61.92") Final Drift Bearing: 90.60°

WELLBORE DRIFT INTERPRETATION Southwest Exploration Services, LLC (480) 926-4558

	r	١٨
J	-ι	14

MEASURED DATA			DATA COMPUTATIONS							
DEPTHS, feet	INCLINATIONS, degrees	AZIMUTHS, degrees	TVD, feet	T. LATITUDE, feet	T. LONGITUDE, feet	DOGLEG SEV., degrees per 20 Feet	DOGLEG SEV., degrees per 100 feet	DRIFT DIST., feet	DRIFT BRG degrees	
1,020	0.46°	057.99°	1,019.51	0.179	3.515	0.96	1.81	3.52' (42.24")	087.10	
1,040	0.28°	045.30°	1,039.50	0.256	3.618	0.46	0.98	3.63' (43.56")	086.00	
1,060	0.31°	098.07°	1,059.49	0.283	3.706	0.25	3.95	3.72' (44.64")	085.60	
1,080	0.36°	113.57°	1,079.48	0.250	3.817	0.92	1.20	3.83' (45.96")	086.20	
1,100	0.63°	124.16°	1,099.47	0.163	3.966	0.09	0.82	3.97' (47.64")	087.60	
1,120	0.80°	114.80°	1,119.46	0.043	4.184	0.16	0.73	4.18' (50.16")	089.40	
1,140	0.85°	106.88°	1,139.45	-0.059	4.453	0.98	0.61	4.45' (53.40")	090.80	
1,160	0.54°	095.92°	1,159.44	-0.112	4.689	0.54	0.85	4.69' (56.28")	091.40	
1,180	0.76°	079.54°	1,179.43	-0.098	4.913	0.80	1.27	4.91' (58.92'')	091.10	
1,196	1.04°	079.33°	1,195.21	-0.052	5.157	0.61	0.03	5.16' (61.92'')	090.60	

Page No. 3 True Vertical Depth: 1195.21 Final Drift Distance: <u>5.16'</u> (61.92") Final Drift Bearing: 90.60°



3D PROJECTION VIEW - O-04


Florence Copper Florence Copper

Drift Distance = 5.16 Feet

Drift Bearing = 90.6 Degrees

True Vertical Depth = 1195.21 Feet





Total Departure (Feet)


Date of Survey: Wednesday - March 21, 2018

Balanced Tangential Calculation Method

Southwest Exploration Services, LLC (480) 926-4558

POLAR VIEW - 0-04

Florence Copper Florence Copper



Date of Survey: Wednesday - March 21, 2018

Balanced Tangential Calculation Method

Southwest Exploration Services, LLC (480) 926-4558

